

Reims Cessna F172N, G-BFMX, 5 March 1997

AAIB Bulletin No: 8/97 Ref: EW/G97/03/04 Category: 1.3

Aircraft Type and Registration:	Reims Cessna F172N, G-BFMX
No & Type of Engines:	1 Lycoming O-320-H2AD piston engine
Year of Manufacture:	1978
Date & Time (UTC):	5 March 1997 at 1327 hrs
Location:	Near Farley Farm Airstrip, Hampshire
Type of Flight:	Private
Persons on Board:	Crew - 1 - Passengers - None
Injuries:	Crew - None - Passengers - N/A
Nature of Damage:	Propeller bent, damage to front lower cowling, exhaust pipe, wheel strut fairings, plastic cowls, tailplane and elevator
Commander's Licence:	Private Pilot's Licence
Commander's Age:	36 years
Commander's Flying Experience:	229 hours (of which 71 were on type) Last 90 days - 3 hours Last 28 days - 1 hour
Information Source:	Aircraft Accident Report Form submitted by the pilot and information from repair/overhaul facilities

The pilot arrived at Farley Farm Airstrip and removed the cover from the aircraft before checking the fuel contents. He then checked for water using a fuel strainer/cup at all three drain-points. On finding a small quantity of water (which he estimated as 2 to 3 cc) from the engine drain point, he drained a considerable amount of fuel until he was satisfied that no water remained.

The pilot then ran the engine up to temperature, stopped it and completed a full set of external checks, including a further check on the three fuel drain points, during which no water was found.

The pilot reported that internal checks, start-up, taxi and power checks were all normal and the engine ran very smoothly. In view of the wetness of the strip, he opted to carry out a short-field take off. At approximately 300 feet AGL the engine abruptly stopped delivering power. The pilot carried

out a quick panel scan, selected a field, transmitted a mayday call and switched off the fuel and ignition. He then realised that he would be unable to reach his chosen field and therefore touched-down in the field before it. The aircraft rolled for approximately 50 yards before passing through a hedge and stopping on a road.

Personnel involved in salvaging the aircraft later reported that water was found to be present in the carburettor bowl. During subsequent repairs the fuel strainer bowl was found to have evidence of internal corrosion and one of the seals on a fuel filler cap was also found to be broken. The carburettor was sent for specialist servicing during which a considerable amount of water was found remaining inside. No specific defects were found, however, other than a number of slightly worn items which typically require replacement during carburettor servicing. No pre-impact defects were found in the remainder of the aircraft. After repair and re-assembly, the engine was successfully ground run and a Certificate of Airworthiness renewal test flight conducted before the aircraft was returned to service.

It is known that the aircraft was parked in the open, out of use, for an extensive period before the accident flight. During this period a cover was used which did not extend over the fuel filler caps and the aircraft was parked on slightly sloping ground. The Cessna 172 has no wing dihedral and hence the undersides of the tanks are almost flat and do not slope towards the drain valve locations. It is thus possible for an accumulation of water to be present in one of the tanks and for it to remain in a corner remote from the drain when the aircraft is not parked on level ground. Water will thus not be readily detectable during fuel drain checks, unless the aircraft is re-orientated and the drain-points re-tested.