

# VPM M16 Tandem Trainer gyroplane, G-YRAT, 23 February 1996

**AAIB Bulletin No: 7/96 Ref: EW/G96/02/09 Category: 2.3**

**Aircraft Type and Registration:**VPM M16 Tandem Trainer gyroplane, G-YRAT

**No & Type of Engines:**1 Arrow GT1000R piston engine

**Year of Manufacture:**1992

**Date & Time (UTC):**23 February 1996 at 1320 hrs

**Location:**1 mile south west of Kemble Airfield, Wiltshire

**Type of Flight:**Private

**Persons on Board:**Crew - 1 Passengers - 1

**Injuries:**Crew - None Passengers - Minor

**Nature of Damage:**Damage to rotor blades, propeller, main frame, tailplane, fibreglass shell and nose wheel

**Commander's Licence:**Private Pilot's Licence with Flying Instructor Rating

**Commander's Age:**55 years

**Commander's Flying Experience:**405 hours (of which 380 were on type)

Last 90 days - 20 hours

Last 28 days - 9 hours

**Information Source:**Aircraft Accident Report Form submitted by the pilot

This gyroplane featured in a previous AAIB Bulletin, 4/95. The previous mishap involved a fatigue failure in the control fork which acts to transmit the pilot's control movements to the rotor head.

The aircraft was departing from Kemble on a local flight and was in level flight at 500-600 feet QFE when the pilot noted that the normal light back pressure on the control column had disappeared. The pilot asked the passenger whether he had touched the controls; the passenger confirmed that he had not and the pilot realised that the freedom of movement of the control column showed that it was no longer connected to the rotor head.

The pilot found that the aircraft was remaining stable in roll and pitch and he established a glide angle of 3° to 4° at 60 mph and an engine speed of 5,000 RPM. He was able to control the aircraft

heading by use of the rudder and headed for an open field, where he was able to head the aircraft into the wind (SW at some 20 mph) before it hit the ground. The pilot attempted to use a burst of power to pitch the nose up just before impact but the only effect of this thrust was to accelerate the machine, which struck the ground and rolled over. The aircraft was severely damaged and the passenger (with a full restraint harness) suffered minor injuries; the pilot, with lap belt only, was uninjured.

Examination of the aircraft after the accident showed that a bolt had come free in the flying control system, thus disconnecting the control fork from the control columns; neither the bolt nor the nut remained in the aircraft and were thus not available for examination. In the VPM M16 design, this control fork acts as the simple 'mixing unit' between the pilot's control column movement and the control rods which set the lateral and longitudinal positions of the rotor head: its correct operation is, therefore, essential to continued safe flight.

The nut originally supplied with the aircraft kit was all-metal of the ('Kayloc'-type) variety in which the upper threaded portion of the nut is formed out-of-round during manufacture to produce a self-locking function. This nut had been replaced after G-YRAT's previous mishap, in which the control fork had suffered a high-stress low-cycle fatigue failure (AAIB Bulletin, 4/95). The replacement nut was of an approved type, in this case a self-locking 'Nyloc' stiff nut, wherein a nylon insert applies friction between the nut and mating bolt. The pilot comments that the nut and bolt had been properly secured but would not routinely be in full view on a 'preflight' inspection.

There have been a number of instances, particularly in light aeroplanes, where self-locking stiff nuts of various descriptions have come undone. This topic is covered for light aeroplanes within the JAA's Joint Aviation Requirements (JARs) by JAR 23.607 (part of Subpart D - Design and Construction):

#### **"JAR 23.607 Fasteners**

(a) Each non-self-locking bolt, screw, nut, pin or other fastener must, if its loss would preclude continued safe flight and landing, incorporate an additional locking device.

(b) Fasteners and their locking devices must not be adversely affected by the environmental conditions associated with the particular installation such as temperature or vibration.

(c) No self-locking nut may be used on any bolt subject to rotation in operation unless a non-friction locking device is used in addition to the self-locking device."

Thus the use of self-locking stiff nuts, without a separate locking device, is not precluded in flying control assemblies where, for instance, the design incorporates a ball-and-race assembly to accommodate the relative rotation. For small rotorcraft (JAR 27 - Small Rotorcraft), however, the current design requirement (a) is slightly different in requiring *two* separate locking devices:

#### **"JAR 27.607 Fasteners**

(a) Each removable bolt, screw, nut, pin or other removable fastener whose loss could jeopardise the safe operation of the rotorcraft must incorporate two separate locking devices. The fastener and its locking devices may not be adversely affected by the environmental conditions associated with the particular installation.

(b) ....."

As G-YRAT was operating on a Permit-To-Fly issued by the CAA its design is not certificated to JARs. The JAR excerpts above show, however, that for a small rotorcraft undergoing current JAR certification, self-locking stiffnuts, without a separate locking device, would be precluded in flying control assemblies.