

# **Boeing 747-235, N516MC, 20 December 1995**

**AAIB Bulletin No: 5/96 Ref: EW/C95/12/3 Category: 1.1**

**Aircraft Type and Registration:** Boeing 747-235, N516MC

**No & Type of Engines:** 4 General Electric CF6-50-E2 turbofan engines

**Year of Manufacture:** 1980

**Date & Time (UTC):** 20 December 1995 at 1806 hrs

**Location:** London Gatwick Airport

**Type of Flight:** Public Transport

**Persons on Board:** Crew - 3 Passengers - None

**Injuries:** Crew - 3 Passengers - N/A

**Nature of Damage:** No.4 engine bleed duct, engine cowlings and wheels and brakes

**Commander's Licence:** Airline Transport Pilot's Licence

**Commander's Age:** 33 years

**Commander's Flying Experience:** 9,410 hours (of which 734 hours were on type)

Last 90 days - 206 hours

Last 28 days - 41 hours

**Information Source:** AAIB Field Investigation

## **History of the flight**

The aircraft was scheduled to carry out a freight flight from Gatwick to Abu Dhabi and, following the routine pre-flight checks, the aircraft was pushed back at 1744 hrs and taxied to Runway 08R for take off. No abnormalities or unserviceabilities of the aircraft had been found and the brakes were released for takeoff at 1805 hrs.

As the aircraft was accelerating through 130 kt, both pilots became aware of an unusual "engine air sound". The Master Fire Warning indicator light in front of each pilot then illuminated and the commander rejected the take off at 140 kt, 15 kt below V<sub>1</sub>, and informed ATC that there was a fire (unspecified) on board. There had been no associated indications on either the Master Warning Panel or the Engine Fire indicators. The auto brake system slowed the aircraft to a walking pace

and the aircraft was turned off onto the high speed exit at holding point 'B'. The ATC 'Air Controller', who had initiated an 'Aircraft Ground Incident', seeing smoke emanating from the area of the aircraft's main landing gear, instructed the crew to hold at their present position. The captain had intended to taxi clear of the runway 'surface' but, on receiving this instruction, immediately stopped and shut down the engines. The fire extinguishers on all four engines were then operated. The Airport Fire Service (AFS) was in immediate attendance, with six appliances, and informed the crew that the brakes were smoking but not yet alight (subsequently there was fire in three wheel assemblies), and advised evacuation. The crew therefore left the aircraft via the normal front left door and were assisted to the ground by the AFS.

Because the brakes had seized when the aircraft stopped, the aircraft could not be moved until 0400 hrs the following morning, which prevented further use of Runway 08R until that time.

### **Engineering information**



The 14th stage HP air duct on the No 4 engine, part number 9068M-40-G01, had failed causing two blow-out panels to operate, and damage to one half of the reverser shroud. The No 4 reverser deployed, but would not stow. Braking, followed by the aircraft being held stationary had caused brake overheating which led to tyre failures and brake seizure on the right main gear, and, in order to move the aircraft, wheels and brake packs had to be changed.

The 14th stage air is at a temperature of approximately 350°C and would have reduced in temperature as it mixes with other engine bay air. The resultant temperature would probably not be hot enough to activate an engine bay fire warning, however, engine bay temperatures are displayed on gauges mounted on the flight engineer's panel. Engine bay temperatures are not monitored on take off as the flight engineer's duties require him to guard the throttles and monitor the engine instruments on the forward panel, he is therefore unable to see the engine bay temperature gauges during take off.

A metallurgical examination of the duct carried out at DRA Farnborough reported that:

'The duct had burst approximately mid way along its length becoming grossly distorted around its circumference and fracturing one of the attachment lugs. Examination of the duct fracture

surfaces revealed the presence of a fatigue crack growing from multiple origins at the weld toe at the base of an attachment lug. The fatigue crack, which was approximately 40 mm in length, had penetrated through the saddle/duct section and extended along the duct for approximately 5 mm on either side of the saddle. This led to a longitudinal tear approximately 450 mm in length before changing direction in a manner consistent with a high pressure rupture, causing one end of the duct to become detached.

Examination of the other saddle-lug welds remote from the fracture revealed one other example of cracking along a saddle weld. This crack, when broken open and examined, was also caused by fatigue growth from multiple origins at the weld toes and had penetrated through the saddle material but had not progressed into the duct wall.

Examination of the fracture surfaces at high magnification by scanning electron microscopy revealed a large number of very fine fatigue striations. However, due to rubbing damage at the crack origins it was not possible to determine for how long the crack had been present. The large number of striations observed would tend to suggest that the cracks had been present before the last inspection, 104 cycles previously, although it is possible that they could also have been caused since by a resonant condition present in the assembly.

Hardness tests carried out on a polished section of saddle material gave an average result of 228 Hv(30kg) equivalent to a tensile strength of approximately 740 MPa which is within the strength range for Inconel 625 material in a solution annealed condition (690-830 MPa).

There was no evidence of mechanical or corrosion damage that could have influenced the failure nor did the material condition appear to be at fault.'

A similar occurrence to a CF6-50 engine fitted to a DC-10-30 in June 1989 was reported in AAIB Bulletin 9/89. At that time, according to the engine manufacturer, there had been 84 reported failures of the duct across the fleet, which resulted in 17 in-flight shutdowns and 9 rejected take offs. The current position (5 Jan. 96) is that 181 events have been reported since 1985, including 18 in-flight shutdowns and 17 rejected take offs.

An improved design has been introduced by Service Bulletin 75-065 which provided a duct with a revised mounting system to be fitted on an attrition basis. This duct was designed to match its thermal expansion with that of the engine structure, and incorporated integral rings to replace the fillet welded lugs. The manufacturer stated that the new duct had addressed the majority of the early failure modes, but had revealed new failure modes. The proposed solution to these new difficulties introduced spring links to reduce thermal stresses and used rod-end bearings to provide an improved tolerance to misalignment. A six month service evaluation of the new configuration was due to start in February 1996 with a projected release of the field modification during the second quarter of 1996.

In December 1994 the manufacturer replaced a fluorescent penetrant inspection (FPI) of the duct attachment lugs with a visual inspection at the same frequency - every 750 hours or 250 cycles. The AAIB were informed that the failed duct had been inspected 104 cycles previously, and was coming up to a further inspection on flight hours. Some operators have decided to continue with the FPI as they do not have sufficient confidence in the probability of success of the visual inspection. This lack of confidence would appear to be justified by the failure of the visual inspection technique to detect the two cracks on the duct from N516MC 104 cycles before the duct failed.

During the investigation a comment was made that a cracked lug was relatively easy to see if the visual inspection was carried out conscientiously, and that the perceived success of the FPI had been brought about by the enhanced inspection discipline it introduced rather than the superiority of the FPI technique over the visual inspection.