

# Piper PA-23-160 Apache, G-ARJU, 10 November 1995

**AAIB Bulletin No: 5/96 Ref: EW/C95/11/5 Category: 1.2**

**Aircraft Type and Registration:**Piper PA-23-160 Apache, G-ARJU

**No & Type of Engines:**2 Lycoming O-320-B3B piston engines

**Year of Manufacture:**1961

**Date & Time (UTC):**10 November 1995 at 1530 hrs

**Location:**3 miles west of Clacton

**Type of Flight:**Private (Training)

**Persons on Board:**Crew - 2 Passengers - None

**Injuries:**Crew - None Passengers - N/A

**Nature of Damage:**No 3 cylinder connecting rod failure

**Commander's Licence:**Commercial Pilot's Licence

**Commander's Age:**34 years

**Commander's Flying Experience:**7950 hours (of which 112 were on type)

Last 90 days - 169 hours

Last 28 days - 81 hours

**Information Source:** Aircraft Accident Report Form submitted by the pilot and further enquiries by the AAIB

The aircraft was being used for training during which flight under asymmetric power conditions was to be practised. The student had just completed an exercise with the left engine throttled back when, almost immediately after normal flight had been resumed, the aircraft suddenly started to vibrate severely. The instructor observed that all engine indications appeared normal, and throttling back of each engine in turn did not appear to influence the vibration level.

The student, who had retained control, noticed that he was having to apply some left rudder to keep the aircraft straight and level. In the absence of any clear indication of distress associated with the right engine, and because they were relatively near their base airfield, the instructor decided to keep both engines running and to land as soon as possible. The return flight and landing were uneventful and after taxiing back to the maintenance hangar, with the severe vibration persisting, the engines were shut down and the symptoms reported to the engineer.

The right engine was subsequently sent for strip examination during which it was found that the No 3 cylinder connecting rod big-end had suffered failure of both its clamping bolts and the connecting rod itself had severed about halfway along its length. The fragments of this connecting rod and its big-end bolts were all recovered from within the engine. There were no parts of the engine which had suffered any damage which might have been consistent with poor lubrication.

A metallurgical examination was conducted on all of the big-end nuts and bolts from the engine. The associated steels of the nuts and bolts, including those which had failed, were found to comply with the correct material specifications.

The two failed bolts from the No 3 big-end exhibited quite different characteristics. One had failed entirely as a result of bending overload and the associated nut had separated from its thread. The last two threads from within the nut had been 'stripped' and there was metal adhering to the end of the bolt threads. The pressure face of the nut, and the area of the big-end cap with which it had been in contact, showed clear evidence of 'hammering' due to looseness whilst the engine had been running. Additionally, whereas none of the other big-end nuts from this engine, including the second one from this failed big-end, showed significant loss of the copper plating from their contact faces, most of the copper plating had been worn off the contact face of this nut. In addition, the pressure face on the machined pad, on the connecting rod itself, from under this bolt head had also been severely 'hammered' and the locating corners of the bolt head had heavily scored the side face of the pad (see Fig 3). The bolt thread, below the deposited metal, also showed slight evidence of hammering wear.

The second bolt from this big-end had suffered a high strain fatigue failure over most of its cross section, with final separation in tensile overload (see Fig 2). The fatigue had initiated from the side which had been nearer to the crankpin, and had occurred over a very short period of engine operation. The nut had been retained on the thread, after bolt separation, and although it had run back a little from its expected position when fully tightened, there was no evidence of hammering wear on the threads. There was also very little evidence of the bolt head hammering on the machined pad on the connecting rod shoulder (see Fig 4). Although there was some evidence of scoring by the bolt head on the side face of the pad, it was much lighter than that caused by the other bolt.

Examination of the clamped faces between the big-end cap and the connecting rod revealed that the faces on the side with the bolt which had failed in bending showed only light evidence of relative movement, whereas those on the side with the fatigued bolt were heavily polished.

The damage observed was consistent with the nut on the bolt which had failed in bending having worked loose and having run back along its thread. This would have overloaded the second bolt, inducing the associated high strain fatigue and causing polishing between the securely clamped faces of the big-end of the rod and the cap (See Figs 1, 5 & 6).

The engine had been subjected to a shock load inspection, following a propeller ground strike, some 230 flying hours before this failure. During this inspection, all the big-end bolts and nuts had been replaced and, although the associated parts had not been supplied by the engine manufacturer, they met the appropriate material specifications. Information from the manufacturer indicated that a small number of engines have suffered from big-end bolts becoming loose some considerable time (ie up to about 1000 hours) after overhaul. The manufacturer's investigations of many of these instances has not revealed any evidence that these could have been caused by any reason other than that the big-end bolts had not been tightened in such a way as to achieve and retain the desired clamping force. The engine design specification does not require mechanical locking of such big-end bolts, eg by tab washers, which used to be general practice on all piston engines of general

aviation aircraft, before such manufacturers adopted torquing of big-end bolts as the sole means of assuring security.