AAIB Bulletin No: 3/94 Ref: EW/G93/12/03 Category: 1.1

**INCIDENT** 

Aircraft Type and Registration: Boeing 747-136, G-AWNC

No & Type of Engines: 4 Pratt & Whitney JT9D-7 turbofan engines

Year of Manufacture: 1970

Date & Time (UTC): 3 December 1993 at 1435 hrs

Location: Stand T5, Terminal 4, London Heathrow Airport

Type of Flight: Public Transport

Persons on Board: Not known

Injuries: None

Nature of Damage: Impact damage to rear cargo door frame

Commander's Licence: Airline Transport Pilot's Licence

Commander's Age: 47 years

Commander's Flying Experience: Approx 10,000 hours (of which 6,000 were on type)

Last 90 days - 180 hours Last 28 days - 66 hours

**Information Source:** Aircraft Accident Report Form submitted by the pilot,

and information from the Metropolitan Police Heathrow

The aircraft was in the final stages of preparation for departure on a scheduled service to Toronto. Passenger boarding was in progress. The delivery height of a Cargo King Baggage Elevator vehicle was being adjusted in order to position it into the rear cargo hold. A bracket on the far side of the belt, out of the operator's view, came into contact with the door frame of the cargo hold, causing a tear in the aircraft skin.

Statistics recorded at Heathrow for the year 1993 indicate that there were 101 occurrences reported which involved damage to aircraft as a result of unintentional contact with ground vehicles or equipment. The AAIB has made Safety Recommendations (numbers 93-76 and 93-77) to the Civil Aviation Authority and to the BAA PLC regarding apron safety.