

BAe 146, EI-CMY, 25 June 1997

AAIB Bulletin No: 4/98 Ref: EW/C97/6/3 Category: 1.1

Aircraft Type and Registration:	BAe 146, EI-CMY
No & Type of Engines:	4 ALF502 turbofan engines
Year of Manufacture:	1985
Date & Time (UTC):	25 June 1997 at 0843 hrs
Location:	London City Airport
Type of Flight:	Public Transport
Persons on Board:	Crew - 5 - Passengers - 49
Injuries:	Crew - Nil - Passengers - Nil
Nature of Damage:	Nil
Commander's Licence:	Airline Transport Pilot's Licence
Commander's Age:	30 years
Commander's Flying Experience:	3,277 hours (of which 835 hours were on type) Last 90 days - 182 hours Last 28 days - 73 hours
Information Source:	AAIB Field Investigation

History of flight

The aircraft was on a scheduled flight from Dublin to London City and was making an approach to Runway 28. The airport had been using Runway 10 and this was the first approach to the westerly runway that morning. At 0820 hrs, the airport 'Automatic Terminal Information Service' had transmitted information 'Hotel'; this had been received by the crew and it included the following weather information: Surface wind 180°/07 kt, varying between 110° and 300°; visibility greater than 10 km; light rain; cloud few at 1,800 feet and broken at 4,800 feet; QNH 1004 mb. With this weather information, the crew had requested, through Thames Radar, if they could use Runway 28 for landing; this was agreed by London City ATC and the crew were informed.

The commander was the handling pilot for the approach and carried out a normal 5.5° glide slope ILS approach to the runway. As part of the approach checks the wheel brake hydraulic system was

changed to 'green' and the brake pressure checked at which time it was confirmed that 3,000 psi each side was registered on the gauge. With Flap 33° selected, the aircraft was stabilised at an approach speed of Vref plus 5 kt; this was an indicated airspeed of 115 kt. EI-CMY was cleared to land at approximately 7 miles range and the crew were also advised that the runway was damp and that the surface wind was 170°/09 kt; this equates to a tailwind of 3 kt. At 2 miles, the crew called for a windcheck and ATC transmitted that the wind was 160°/08 kt; this equates to a tailwind of 4 kt. The crew considered that touchdown was at the end of the touchdown zone, close to the 'end of zone lights'. Then, once the nose wheel was on the ground, the commander activated the spoilers and the first officer confirmed their deployment. However, when the commander commenced wheel braking, she considered that the brakes were 'snatching' and that the retardation was less than normal. She continued to apply foot pressure to the wheel brakes and both crew members confirmed that the brake pressure gauges were indicating normal values. As the aircraft approached the end of the declared runway, the commander changed the operating wheel brake hydraulic system from 'green' to 'yellow' and asked the first officer if he was on the brakes. The commander had also maintained pressure on her brake pedals and the crew then felt an immediate improvement in the braking performance of EI-CMY. The commander was now confident that the aircraft would stop within the hard standing and, in consideration of passenger comfort, reduced the brake pressure slightly; the aircraft stopped just short of the grass. EI-CMY travelled beyond the end of the declared runway, past the 75 metres 'Runway Starter Extension' and into the final 24 metres hard standing surface.

The ATC controller had watched the aircraft land towards the end of the touchdown zone and thought that it appeared faster than normal as it progressed along the runway. As EI-CMY passed the control tower, the controller considered that it could overrun the runway and pressed the crash alarm; thereafter, she monitored the aircraft and noted that it seemed to 'snake' as it passed into the 'Starter Extension' and then saw it come to rest short of the grass; as it stopped, the controller noticed a short 'puff' of smoke from the area of the right gear and asked the crew if they required any assistance. When the crew of EI-CMY transmitted that they were serviceable, the controller gave them permission to taxi to the parking area. Shortly afterwards, when the Airfield Fire Service (AFS) checked in on the radio, the controller advised them of the situation, stood them down from the 'alert' but asked them to attend the aircraft on the stand. The AFS checked the aircraft on stand and then, after confirming that there was no evidence of excessive heat in the area of the brakes and wheels of EI-CMY, were stood down.

Engineering investigation

Witness markings on the runway which appeared to be caused by the incident aircraft were found on the starter extension at the far end of the landing runway. A very limited amount of rubber had been laid down and there was also some scalding of the white painted markings where the tyres had crossed them. The marks had been made by main wheel tyres, and showed that the aircraft had swung to the left at the end of its landing roll. A number of other marks existed which were associated with the subsequent turn, and there were also some marks which were clearly not associated with this aircraft. In all, the relevant marks were consistent with braking following the drop-out of the anti-skid system which normally occurs at low speed. No evidence of anti-skid malfunction was observed from the ground marks. Smoke or steam had been reported coming from the area of the landing gear at the end of the landing run; in the opinion of the engineer who examined the aircraft at the time, this could have been due to the damp conditions and the heat generated by the braking action, as there was no evidence of gross overheating.

Immediately after the incident, the green and yellow brake systems were bled in accordance with Chapter 32-40-00 of the Maintenance Manual. Air was found in the port outer and starboard inner brake units. The amount was small and it was considered that it would not have reduced the braking effort. Following this, the anti-skid system was tested in accordance with the Maintenance Manual and was found to be serviceable. Additionally, two taxi runs and brake tests were conducted, testing the brakes and spoiler on both green and yellow systems. The only defect found was on the green brake system pressure gauge which had a spurious indication. As permitted by the MEL, the aircraft was despatched to Dublin where the defect was cleared by replacing a brake pressure transmitter.

At Dublin, the aircraft was extensively re-checked and several taxi and brake test runs carried out. No further air was found, and the green and yellow system checked out normally. Although no faults were found, the anti-skid control unit was changed as a precaution. Following this, further taxi tests were carried out; the flight crew who carried out the taxi and brake tests expressed a subjective view that the braking was more effective with the new unit fitted.

On 20 June 1997, five days before the incident, another Captain made the following entry to the Technical Log: *"Check anti-skid Green control valve anti-skid not working properly skipping had to select yellow two landings in a row"*. Maintenance action was a check of the anti-skid system in accordance with the Maintenance Manual. No fault was found, the rectification box includes the comment *"please report further"*.

The anti-skid control unit, part number A20556, serial GX212, which had been removed at Dublin, was sent to the manufacturer for testing with the AAIB in attendance. It had first been supplied in June 1995 and this was its first return to the manufacturer. The unit consists of five circuit cards; a power card which is common and four wheel cards. Each wheel card has wheel speed processing circuitry plus green and yellow output modules. Thus, multiple card failures would be required to cause the loss of braking on more than one wheel. Power card failure would not inhibit braking but would mean that anti-skid protection would not be available.

The anti-skid control unit was given the normal acceptance test using Automated Test Equipment (ATE) and passed as serviceable. After this, it was subjected to 9 hours of vibration testing with temperature cycling. During this time, the No. 3 card exhibited a hard fault which would have prevented it from sensing a wheel speed transducer failure, and was also found to be slightly outside calibration limits. However, neither of these defects would have had any effect on the unit's operation in the aircraft.

Between the removal of the anti-skid control unit and the testwork, the aircraft flew a further 100+ sectors without recurrence, and no further anomalies have since arisen. It has not therefore been possible to positively identify a fault with the aircraft.

Optional modification HCM01040A, which has been fitted as standard to all aircraft manufactured since December 1989, introduced an increased angle to the toe brake pedals. The relevant Service Bulletin stated: "The existing toe brake pedal angle has been criticised by some pilots who have found it awkward to apply full brake pressure." This optional modification was not embodied on any of the operator's aircraft.

Flight recorder information

The Flight Data Recorder, a PV1584, was removed and replayed at the AAIB. Figure 1 shows selected parameters from the approach and landing at London City. The aircraft passed the a height of 35 feet at 120 kt IAS and at touchdown, which was identified from the normal acceleration of 1.45g, the airspeed was 106 kt. The spoilers were deployed between two and four seconds later; it is not possible to be more precise since this discrete parameter is only sampled every two seconds. Once the spoilers were deployed, from an airspeed of 98 kt the aircraft began to decelerate initially at a level of 0.25 to 0.3g; the total time from deployment of the lift spoilers until the aircraft stopped was 24 seconds. After around 13 seconds, with the aircraft at an airspeed of approximately 65 kt, the deceleration decreased to a level of 0.1g for roughly three seconds. The deceleration then increased to a level of between 0.3 and 0.4g for around 7 seconds before the aircraft came to a stop; the airspeed does not indicate below 50 kt. During this final deceleration phase there was a turn to the left of roughly 10° onto a heading of 270°. Braking parameters are not recorded by the FDR so it was not possible to determine the level of braking applied.

A double integration was performed from the recording of longitudinal acceleration in order to calculate the stopping distance, and therefore the touchdown point. The total ground run was calculated as 900 metres from touchdown to the aircraft coming to a complete stop. The touchdown point was calculated and, within the accuracy of the method used, was therefore consistent with the witness reports.

The manufacturer used their performance data to calculate an unfaired stopping distance in the conditions pertaining, ie the distance that the aircraft would use to stop, from a speed of 98 kt, using wheel brakes and lift spoilers. The time to stop is given in parentheses, for each case. The results are detailed below:

Maximum application of wheel brakes and lift spoilers deployed:

	Dry	Wet
Zero wind	399 metres (14.0 seconds)	568 metres (21.5 seconds)
5 kt tailwind	430 metres (14.5 seconds)	621 metres (22.7 seconds)
7 kt tailwind	443 metres (14.8 seconds)	643 metres (23.1 seconds)

Half maximum application of wheel brakes and lift spoilers deployed:

	Dry	Wet
Zero wind	587 metres (23.0 seconds)	791 metres (33.1 seconds)
5 kt tailwind	639 metres (24.1 seconds)	869 metres (34.9 seconds)
7 kt tailwind	661 metres (24.6 seconds)	901 metres (35.6 seconds)

A simulation performed by the manufacturer reproduced the deceleration profile and ground roll distance using the following assumptions:

a) 7 kt tailwind,

- b) medium braking action on first brake application (green) and a braking action between maximum wet and maximum dry braking on the second brake application (yellow),
- c) 0.5 second delay switching from green to yellow brakes,
- d) 90% effectiveness of lift spoilers due to application of forward stick after touchdown.

Airfield information

London City Airport is situated in the dockland area of the city; it has a single runway which is designated 10/28. Information contained within the UK Aeronautical Information Publication (UKAIP) includes the fact that the Landing Distance Available (LDA) in either direction is 1,199 metres; there is also a footnote stating that these distances include a 75 metre starter extension for Runway 10 and a 186 metre starter extension for Runway 28. These footnotes are confusing as the starter extension distances are not included in the LDA. Additionally, there is an extra 24 metres of hard standing at each end of the starter extensions; this information is not included in the UKAIP. Following this incident, the airport authorities submitted an amendment to the UKAIP to clarify the information relating to London City Airport.

There are standard threshold markings and lights for each runway and the end of each touchdown zone is marked by white lights inset in the runway 336 metres from the threshold. The approach and runway lighting and PAPIs are set for a 5.5° approach. For steep approaches, the screen height has been reduced from the normal 50 feet to 35 feet.

After the incident, a runway braking inspection was carried out; this was done some 2 hours and 20 minutes afterwards and rain had continued during the intervening period. The runway was then assessed as wet and the inspection included both directions and on both sides of the runway. The lowest Mu-meter reading was .45; braking action is good when the Mu-meter reading is .40 and above.

The UKAIP details the procedures which ATC will use for reporting the presence of water on the runway. On this occasion, the runway was reported as 'Damp' indicating that the surface was showing a change of colour due to moisture. The next level would be 'Wet' when the surface is soaked but no significant patches of standing water are visible. The UKAIP also includes the information that pilots may assume that an acceptable level of runway braking friction is available with conditions of 'Damp' or 'Wet', unless the runway has been notified as "liable to be slippery when wet". This notification is required when the friction characteristics of a runway or a significant portion thereof deteriorate to a Mu-meter calibration value of 0.39 or less; this was not applicable in the case of the runway at London City Airport.

During the investigation to a similar incident to another BAe146 at London City Airport on 18 November 1996, reported in AAIB Bulletin No 8/97, the airport authority stated that they were considering some form of ground arrester system at both ends of the runway. This installation was completed on 18 August 1997.

Operating information

The commander was well experienced in operating into London City Airport and had completed 64 previous landings there; of these, approximately 30 had been in wet/damp conditions. The first officer was also experienced with 2,100 hours total flying and 1,600 hours on type.

At touchdown, the aircraft weight was calculated as 31,952 kg; from the company manuals, the required V_{ref} for this landing weight at 33° flap is 110 kt.

The factored landing distances, calculated by the manufacturer, at 32,000 kg, +11°C and sea level were as follows:

	Dry	Wet
Zero wind	928 metres	1066 metres
5 kt tailwind	1030 metres	1184 metres

The landing distances are measured, assuming V_{ref} at a screen height of 35 feet, and with maximum braking on the runway. The measurements are then factored by 1.67 for a dry runway and 1.92 for a wet runway to allow for operational contingencies.

Company procedures and manuals

The company procedures for take off and landing at London City are similar to other companies operating the same type. The handling pilot will always be the commander unless the first officer has at least 1,000 hours on type; additionally, the handling pilot must have completed specific London City simulator training and a line check. Wind limitations include a crosswind limit of 20 kt, including any gusts and a tailwind limit of 5 kt.

Approach procedures require the aircraft to be configured with gear down and full flap (33°) and to be stabilised at $V_{ref}+5$ kt before glideslope intercept; as the glideslope is intercepted, the airbrakes are selected out. This configuration is maintained with a target speed over the threshold of V_{ref} . At the threshold, the throttles are retarded to flight idle as the flare is commenced. After touchdown, the throttles are reduced to ground idle and, with the nose wheel on the ground, the commander deploys the liftspoilers. The non-handling pilot confirms that the spoilers have deployed and checks the brake pressure. If it appears that the aircraft will touchdown beyond the touchdown zone, a go-around must be initiated before aircraft touchdown.

Company performance manuals include a sheet for landing limitations; this details the performance limited weight for wet or dry runways for various tail and head winds. The limit for a Flap 33° landing with zero wind is 35,389 kg; for a 5 kt tail wind component, the limit is 31,078 kg; there are no limits displayed for tailwind components between zero and 5 kt.

Summary

The landing weight was below that required for the runway and the prevailing conditions. However, this incident highlighted the large difference in weight limitations, between zero and 5 kt tail wind components, contained in the company manuals. Although, there are practical difficulties of operating to very precise wind strengths, particularly at London City Airport where the surface wind

is often different at each end of the runway, the operating company are reviewing the content and presentation of the manuals.

The crew used the correct procedure and landed near the end of the touchdown area. The touchdown point was corroborated by the crew and the ATC controller, and the FDR calculations were consistent with their assessment. The spoilers were deployed correctly and the commander commenced braking; the aircraft should have stopped within the declared runway. The fact that EI-CMY did not stop until the end of the starter extension indicates that the runway surface was slippery, or that the braking technique used was incorrect or late, or that there was some kind of technical malfunction.

Mu-meter checks of the runway indicated good braking conditions and previous and subsequent landing aircraft reported no braking difficulties. Both crew members were confident that the correct braking technique was used and, when the retardation was less than expected, an alternative hydraulic system was selected; this immediately resulted in an improved performance. In fact, the commander reported that she was then so confident of the braking performance that she could have stopped within the declared runway but was able to reduce braking slightly to minimise passenger discomfort. The crew's account was also strengthened by the fact that an identical malfunction had been reported five days earlier. Following the earlier incident, no defect was found. After this later incident, minor defects were noted within the braking system but no fault could be detected which would have caused the reported symptoms. However, when the anti-skid control box was replaced, subjective views of the crew who did taxi checks before and after the replacement, were that the braking system had improved. Extensive checking revealed no significant defect with the control box. Nevertheless, the evidence on balance indicates that there was some sort of technical malfunction which degraded the anti-skid system.