AAIB Bulletin No: 12/95 Ref: EW/G95/10/02 Category: 1.1

Aircraft Type and Registration: Boeing 747-136, G-AWNB

No & Type of Engines: 4 Pratt & Whitney JT9D-7 turbofan engines

Year of Manufacture: 1970

Date & Time (UTC): 4 October 1995 at 0724 hrs

Location: London Heathrow Airport

Type of Flight: Public Transport

Persons on Board: Crew - 18 Passengers - 362 not no supposed

Injuries: Crew - None Passengers - None

Nature of Damage: Damage to door 1L

Commander's Licence: Airline Transport Pilot's Licence

Commander's Age: 46 years

Commander's Flying Experience: 10,765 hours (of which 4,350 were on type)

Last 90 days - 120 hours Last 28 days - 50 hours

Information Source: Aircraft Accident Report Form submitted by the pilot and

AAIB enquiries

The aircraft was engaged on a scheduled flight from New York to Heathrow. After arrival on Stand S3, the jetty was positioned as normal at door 1LD. However, during the disembarkation process the jetty started to rise and in doing so jammed solidly against the door, causing the departure of the passengers to be halted. It was not possible immediately to free the jetty from the door, and alternative arrangements were made to disembark the remaining passengers.

The jetty's hoist limit was then overridden to relieve the load on the door and the jetty and aircraft were then separated. A visual check of the aircraft found damage to the door and its hinge mechanism which subsequently required removal of the door for dressing, NDT inspection and repairs to the upper hinge, and other parts of the mechanism. The jetty was examined and subsequently found to have a hoist fault, causing it to rise against the aircraft door. The jetty was removed from service at 0721 hrs, inspected, the auto leveller adjusted and it was also subjected to a full functional test. The jetty was then returned to service at 0950 hrs. The repairs to the aircraft took several days, including other work.