

# Aeronca 7AC Champion, G-LEVI, 28 October 1995

**AAIB Bulletin No: 4/96 Ref: EW/G95/10/16 Category: 1.3**

**Aircraft Type and Registration:**Aeronca 7AC Champion, G-LEVI

**No & Type of Engines:**1 Continental A65-8F piston engine

**Year of Manufacture:**1946

**Date & Time (UTC):**28 October 1995 at 1210 hrs

**Location:**1 nm South West of White Waltham Airfield, Berkshire

**Type of Flight:**Private

**Persons on Board:**Crew - 1 Passengers - None

**Injuries:**Crew - None Passengers - N/A

**Nature of Damage:**Engine damaged

**Commander's Licence:**Private Pilot's Licence with IMC Rating

**Commander's Age:**47 years

**Commander's Flying Experience:**263 hours (of which 29 were on type)

Last 90 days - 6 hours

Last 28 days - 6 hours

**Information Source:**Aircraft Accident Report Form submitted by the pilot and AAIB telephone enquiries

Just after take off the pilot heard a loud thump from the tail of the aircraft. As there had been tailwheel problems with the aircraft in the past, the pilot requested a visual check of the tailwheel during a flypast along Runway 21. The ground staff reported that the tailwheel appeared normal and the pilot re-applied full power at the runway mid point to commence a climb on runway heading; it was subsequently reported that self centralisation of the tailwheel under spring loading could sometimes produce the type of thump heard.

During the climb, at about 800 ft agl, the engine suddenly began to vibrate noisily and the power output reduced to a very low level. The pilot made an immediate 180° left turn while transmitting a Mayday call to Waltham Radio. On rolling level the aircraft was heading directly back towards Runway 03. However, the pilot was in some doubt about clearing a line of tall trees between his position and the airfield boundary so he shut down the engine. As soon as the magnetos were

switched off the propeller stopped rotating. The aircraft was now at about 500 ft agl and the pilot turned 90° left to land in the only available field, approximately 1 nm short of the Runway 03 landing threshold. After touchdown in a three-point attitude followed by gentle wheel braking the aircraft came to a stop after a ground roll of about 50 yards. No damage was sustained in the landing.

Engine strip by an overhauler revealed that the exhaust valve of the No 2 cylinder had fractured. The head of the valve had fallen into the cylinder and then been driven into the cylinder wall by the piston. No other significant engine defects were found. The valve pieces were forwarded to AAIB. It was apparent that a flat planar type fracture of the valve stem had occurred at the start of the blend radius between the stem and the head. The head portion of the valve was complete but had been severely mangled and the original fracture surface had been obliterated by damage; the stem portion of the fracture had been coated with a black deposit but was undamaged. Both the head portion and the adjacent part of the stem had an overheated appearance. Specialist examination found that the material composition was consistent with the VMS201 high-chromium, high-nickel steel specified. The material hardness near either end of the stem was well below the minimum specified (32 HRC (Rockwell C Hardness)); a considerably lower value for the head end of the stem (21 HRC) than for the other end (27 HRC) suggested that the low hardness had resulted from overheating.

Clear evidence was found showing that the fracture had been caused by the growth of a fatigue crack across almost the entire section of the stem, under bending loading. There was no evidence at the point of crack initiation of any pre-failure damage that might have affected the fatigue life of the valve. Some features of the severely damaged seating face of the valve could have been indicative of a small particle having become lodged between the valve and its seat; it is possible for such an effect to apply bending loads to the valve and to result in the type of fatigue failure identified.