


Photograph 1

Courtesy of HT Consultants

present in the area marked 2. Overload tearing had started in the area marked 3 which Enlarged view of the forward fracture faces on the left Centre Frame Rear Cluster Fitting after solvent cleaning. Separation had resulted from a very high cycle tension fatigue mechanism that had initiated along the edge marked 1. A secondary initiation was led to the final separation.



Photograph 4

Courtesy of HT Consultants

Non approved welded patch repair to the right Centre Frame
Rear Cluster Fitting of G-BPPY Page 3 of 4

INITIALS

### Models 269A, TH-55A, A-1, B & C - Appx B

### Tuble B-1. DAILY INSPECTION - BEFORE FIRST FLIGHT OF THE DAY

NOTE

Refer to the applicable Lycoming Operator's and Maintenance Manuals listed in Related Publications and Directives table (Basic HMI, Section 2) for detailed requirements on daily inspection of the engine.

When unusual local conditions (environment, utilization, etc.) dictate, it is the prerogative and responsibility of the helicopter operator or owner to increase the extent and/or frequency of inspection to promote safe operation.

Inspections in this table are grouped by location so that inspection can be performed on an area shy-area basis. Thus, inspection of the entire helicopter may be accomplished by starting at the front and working in counterclockwise progression to completion.

### What to Inspect (Power OFF)

### FRONT - Canopy and Pilot's Compartment

- 1. Remove all tie downs and covers if installed.
- 2. Canopy and front exterior for obvious damage; windshields for condition and cleanliness.
- 3. Canopy attachment areas for condition and security.
- 4. OAT sunshield for obstructions, condition and security.
- 5. Pitot tube cover removed and pitot tube for obstructions. Drain bole clear.
- 6. VHF Antenna for condition and security.
- 7. Side and lower forward fairing and air induction system for condition, security and obstructions.
- 8. Filter bousing lock pin for damage and security. Daily cleaning of filter required in some aircraft operations (Basic HMI, Section 2).
- 9. Door window for condition.
- 10. Door vent for operation, condition and security. Rotational tab stop in place.
- 11. Door latch for operation, condition and security.
- 12. Door hinge pins and door stops for operation and security.
- 13. Canopy slat for obvious damage and cracks; slat attachment hardware and canopy attachment areas for condition and security.
- 14. Fire extinguisher for condition and security.
- 15. Loose equipment (in pilots compartment) for proper stowage.

Reissued: 20 May 1993

ـــا 2-3

Models 269A, TH-55A, A-1, B & C - Appx B

### Tuble B-1. DAILY INSPECTION - BEFORE FIRST FLIGHT OF THE DAY

### What to Inspect (Power OFF)

### LEFT SIDE - Fairing Assembly, Engine Components, and Landing Gear (con't.)

 Impeller for evidence of contact with shroud. Impeller attach bolts for evidence of looseness or working. Weight ring to impeller rivets for working or looseness (no contact or working allowed).

INITIALS

- 14. Visible portions of tail rotor control linkage for security and obvious damage.
- 15. Landing gear stabilizer for security and obvious damage.
- 16. Drag strut for condition and security.
- 17. Visually inspect attachment lugs for tailboom support strut on BSC aft cluster fittings (fittings with thin lugs 0.070 to 0.100 inch) for cracks or damage. Due penetrant inspect fittings if cracking is suspected.
- 18. Landing skid for obvious damage and security. With assistance, rock helicopter back and inspect bottom of skid tube for wear.

### WARNING

GROUND RESONANCE CAN RESULT IF THE HELICOPTER IS OPERATED WHEN THE LANDING GEAR DAMPER EXTENSION, OIL TYPE AND/OR OIL TO AIR PROPORTIONS ARE INCORRECT.

- (269A/TH-55A, 269A-1 and 269B only) Inspect forward landing gear damper for extension (1-inch minimum or use extension check tool), security, damage and leaks. Aft damper for extension (3/8-inch minimum or use extension check tool), security, damage and leaks.
- 20. (269°C only) With fuel tank(s) full, inspect landing gear dampers for condition by observing stance of belicopter. Check damper extension (HMI, Configuration Supplement C, Section 12) if belicopter is nose down or unusually nose up. (Normal stance is slightly nose up.) Visually check dampers for leakage; replace if leakage is obvious or extension is not within limits (HMI, Configuration Supplement C, Section 12).
- 21. Rear skill strut for security and obvious damage; freedom of swivel joints.
- 22. Aft crossbeam for damage, security and excessive bending (One inch maximum allowed with no weight on gear, Basic HMI, Section 12).

Reissued: 20 May 1993

INITIALS

Models 269A, TH-55A, A-1, B & C - Appx B

### Table B-1. DAILY INSPECTION - BEFORE FIRST FLIGHT OF THE DAY

What to Inspect (Power OFF) con't.

LEFT SIDE - Pulley Assembly, Fuel Tunk, and Main Rotor System (con't.)

- 10. Main rotor mast for security; mast support tubes for security and evidence of cracks at welds.
- 11. Lower control rods and belleranks for wear and security; mast bellerank support lugs for evidence of cracks in radius.
- 12. Flight control rods, rod ends, bearings and stationary swashplate scissors link assembly, for wear, damage and security.

### WARNING

INCORRECT PHASING AND TORQUE ADJUSTMENT, AS WELL AS IMPROPER SERVICING OF THE MAIN ROTOR BLADE DAMPERS CAN LEAD TO CONDITIONS THAT MAY RESULT IN GROUND RESONANCE AND DESTRUCTION OF THE HELICOPTER. FOLLOW ALL INSTRUCTIONS IN THE BASIC HMI CAREFULLY TO ENSURE SAFE HELICOPTER OPERATION.

13. Main rotor blade friction dampers (if installed) for position and oil level; refill as required. Field-clean and service if roughness is noticed. Check phasing and rephase as necessary (Basic HMI, Section 8).

### CAUTION

Excessive lend-lag loads applied to the main rotor blades during ground handling can result in damage to the elastomeric damper and failure of the damper assembly. Operators and maintenance personnel should exercise caution to avoid lead-lag loads in excess of 35 lbs. at the tip of the main rotor blades.

- 14. Visually check elastomeric dampers (if installed) for cracks in elastomer or in elastomer-to-metal bond at end face of damper. Inspect damper turnbuckle, jamnuts and safetywire for security, corrosion and cracks. Inspect clevis bushing for wear and looseness. Inspect bearing in rotor blade at damper attachment for looseness around outer race. (No bearing end play is permitted when manually tested.)
- 15. Swashplate assembly, rotating seissors link assembly and upper control rods for wear, damage and security.

### CAUTION

If installed, use care to prevent damage to or bending of trailing edge tabs on main rotor blades.

16. Visually inspect three main rotor blades for cleanliness, trailing edges and blade tips for condition. Inspect upper and lower surfaces for cracks and bond separation at root fittings and doublers. Inspect upper and lower surfaces for dents, scratches, corrosion and hardware security. Inspect vent hole for obstruction. (Basic HMI Section 8 and/or Supplement C, Section 8.)

Reissued: 20 May 1993

Models 269A, TH-55A, A-1, B & C - Appx B

### Tuble B-1. DAILY INSPECTION - BEFORE FIRST FLIGHT OF THE DAY

What to Inspect (Power OFF) con't.

### Stabilizer, Tall Rotor Transmission, and Tail Rotor Assembly INITIALS 1. Check drive shaft aft coupling nut lockwire for security. 2. Tail rotor transmission for excessive oil leakage, security of mounting and correct oil level (service if low). 3. Tail rotor blades, bub, and pitch control linkage for free movement, obvious damage, wear and security. Rubber stop or nylon bumper for condition. 4. Visually inspect each tail rotor blade abrasion strip for paint cracking or chipping along the abrasion strip to airfoil bond line. If cracking or chipping is observed, inspect for bond separation with 10X magnifying glass. Perform abrasion strip tap test. If bonding defects are suspected but not confirmed, inspect tail rotor blade in accordance with HMI, Appendix C, Part VII. 5. Check conical bearings for evidence of reddish fretting products. If found, check for looseness and repair (HMI, Appendix C, Part VII). NOTE Feathering the blades of a static LTS tail rotor can produce a loud snapping noise as the strap pack is twisted and bent without a centrifugal load imposed. Such a noise is not harmful and of no concern. 6. Tail rotor control rod at gearbox, and pitch control links at rotor for excessive bearing looseness, free movement and security. Tail rotor control rod for clearance, bellerank for damage, swashplate for freedom and boots for condition. 7. Horizontal stabilizer for condition and security. Check for cracks in all attachment mounts and castings, skins and rear spar close out; corrosion, loose rivets and other damage. 8. Tail light and wires for condition and security. 9. Tail skid for looseness in socket, damage and security. RIGHT SIDE - Tailboom and Vertical Stabilizer NOTE INITIALS Misalignment of the marks indicates torsional windup damage to the tail rotor drive shall. If misalignment is evident, remove drive shall and perform additional inspections in accordance with Basic HMI, Section 10.

1. Place aft grease fitting on tail rotor drive shaft in center of inspection hole in tail rotor gearbox adapter; check for misalignment of marks at forward tail boom fitting and forward end of drive shaft which is indicative of tail rotor driveshaft torsional damage.

Relssued: 20 May 1993

Models 269A, TH-55A, A-1, B & C - Appx B

### Tuble B-I. DAILY INSPECTION - BEFORE FIRST FLIGHT OF THE DAY

What to Inspect (Power OFF) con't.

### RIGHT SIDE - Fuel Tunk, Clutch Assembly, V-belts, and Pulleys (con't.)

6. Inspect idler pulley for smooth operation. Try to move pulley at right angles (laterally) to shaft to determine that no perceptible lateral play exists. Spin pulley through several quick rotations; listen and feel for evidence of noisy or rough bearings. Check support bracket for evidence of cracks (pay special attention to areas of bracket adjacent to clutch shaft and bearing retainers). Check support eastings for evidence of cracks. Determine that a minimum axial (fore and aft) play of 0.030-inch exists with up to 15 pounds of axial load applied. (If obsolete 269A5444 series or 269A5515 dual arm pulley assembly is installed, check for 0.002-inch axial play with up to 10 pounds of axial load applied. Visually check idler pulley bearings for corrosion, wear, and damage. See N-85.3, N-90.1, and N-95).

INITIALS

- 7. Clutch control spring assembly for condition and security. Clutch cable for wear or fraying.
- 8. Clutch linear actuator attachment lug and mating frame fitting strap for bending, cracks, physical stress, strain or other defects.
- 9. Cable guide pulley for condition and security; pulley mount straps for cracks.
- 10. Visually inspect attachment lugs for tailboom support strut on BSC aft cluster fittings (fittings with thin lugs 0.070 to 0.100 inch) for cracks or damage. Dye penetrant inspect fitting if cracking is suspected.

RIGHT SIDE - Landing Geor, Engine Components, and Fairing

1. Aft crossbeam for attachment and security.

INITIALS

- 2. Rear skid strut for security and obvious damage; freedom of swivel joint.
- 3. Landing gear stabilizers for security and obvious damage.
- 4. Drag strut for security and condition.
- 5. Landing skid for obvious damage and security. With assistant, rock belicopter back and inspect bottom of tube.

WARNING

GROUND RESONANCE CAN RESULT IF THE HELICOPTER IS OPERATED WHEN LANDING GEAR DAMPER EXTENSION, OIL TYPE, AND/OR OIL TO AIR PROPORTIONS ARE INCORRECT.

6. (269A/TH-55A, 269A-1 and 269B only) Inspect forward landing gear dampers for extension (1-inch minimum or use extension check tool), security, damage and leaks. Aft damper for extension (3/8-inch minimum or use extension check tool), security, damage and leaks.

Relssued: 20 May 1993

2-11

Models 269A, TH-55A, A-1, B & C - Appx B

### Tuble B-1. DAILY INSPECTION - BEFORE FIRST FLIGHT OF THE DAY

What to Inspect (Power ON)

- I. Turn BAT switch to ON position, and check the following:
  - (a) Exterior lighting (landing, position and anticollision lights) for proper operation; switches OFF after check.
  - (b) Interior lighting (panel lights) and communication equipment for proper operation; all switches OFF after check.

### CAUTION

Exercise care when trimming the cyclic stick on 269 series helicopters. Operators should avoid continued trimming against a mechanical stop. Proper trimming practices will help prevent dumage to the trim control assembly.

- (c) Cyclic trim control for proper operation.
- (d) Instruments for normal indication with engine off.
- (c) Exhaust beater blower san (if installed) for proper operation; circuit breaker OFF after check.
- (f) Engage clutch control switch. Check alignment of clutch spring compression marks. Release clutch switch.
- (g) Fuel tank shutoff valve open (control knob full in).

### CAUTION

Do not run fuel boost pump with fuel shutoff valve closed.

- (b) Turn suel boost switch ON. Drain suel silter. Turn suel boost switch OFF.
- 2. Turn BAT switch to OFF position.

INITIALS

Relsaued: 20 May 1993

LAMS Helicopters

A10 Cabin Area

Check - flying and engine controls for full and free movement in the correct sense; friction devices for correct

operation

Check - instrument readings are consistent with ambient conditions

Perform manual override and disengagement check on auto-stabiliser system Check - avionic equipment operation, using self-test facilities where provided Inspect seats, belts harnesses for satisfactory condition, locking and release Check - emergency equipment properly stowed and inspection dates valid

Test operation of electrical circuits

Inspect - cabin and baggage doors for damage, security and for correct operation and locking.

Check that markings and placards are legible,

A11 Agricultural Operations Inspect - hopper, hopper lid, tank, pump, boom assemblies, pipe runs, blowers and spreaders for damage and

security

Check - emergency dump doors, fan brake and pump control for correct operation

NOTE: At the conclusion of agricultural operations the helicopter shall be completely cleaned to remove chemicals, and an inspection of those parts of the structure which are likely to have been contaminated, eg skin/covering and exposed control cables, shall be carried out before the helicopter is returned to any work other

than agricultural operations

A12 Marine Helicopters

Inspect - floats, spreaders, struts, bracing wires for damage, security and corrosion

Check fixed float inflation pressures

A13 Special Purpose Equipment Inspect - emergency flotation gear, lifting hooks, rescue hoists, stretcher installations and similar equipment for

damage and security.

Check - lifting hook release operation

March 1999

7/3

### PART 1 OWNER'S AND OPERATOR'S RESPONSIBILITIES

### 1 INTRODUCTION

An aircraft registered in the United Kingdom in respect of which a Certificate of Airworthiness (C of A) is in force shall not fly unless the aircraft (including its engines), together with its equipment and radio station, is maintained in accordance with a maintenance schedule approved by the CAA. The Light Aircraft Maintenance Schedule (LAMS) has been approved by the CAA for this purpose.

Owners/Operators are responsible for ensuring that their aircraft are maintained in accordance with the requirements of the CAA Approved Maintenance Schedule, at the intervals prescribed therein, otherwise the C of A ceases to be in force.

1.2 Approved maintenance requirements and therefore maintenance costs, vary between C of A and operational categories. It follows that Owner/Operators should ensure that the C of A and operational category for their aircraft is that which is appropriate to its particular operation.

### 2 MAINTENANCE MANAGEMENT: NON-COMMERCIAL AIR TRANSPORTATION

Owners/Operators are reminded that they are the maintenance managers of their aircraft and that they must make suitable arrangements for all continuing airworthiness requirements to be met. They should also understand that if they fail to do so, then, apart from any airworthiness hazards that may result, they could also incur unnecessary expense at the time of the Star Inspection. It is appreciated that not all Owner/Operators of aircraft would consider themselves competent to meet this responsibility themselves, in which case they are recommended to delegate the task to a licensed aircraft maintenance engineer or maintenance organisation of their choice (both hereafter referred to as 'maintenance organisation').

The CAA is of the opinion that Owner/Operators should enter into a suitable contract with a maintenance organisation which is mutually acceptable and on-going. This arrangement is likely to produce the most cost effective maintenance and C of A renewals consistent with an acceptable level of safety. Clearly, if the aircraft is taken from one maintenance organisation to another, there must be an element of added work involved in the new maintenance organisation becoming familiar with the particular aircraft.

The contract should address the following matters:

- (a) General arrangements for technical liaison between Owner/Operator and the maintenance organisation.
- (b) Accomplishment of maintenance at the approved locations of the maintenance organisation or provision of suitable accommodation at other locations.
- (c) Provision of appropriately licensed aircraft maintenance engineers and non-licensed personnel sufficient in numbers for the completion and certification of scheduled maintenance, rectification of defects and completion of duplicate inspections.

- (d) Assessment of Service Information made by aircraft, engine, propeller and component type design organisations, in the form of Service Bulletins, Letters, etc, as appropriate to the aircraft and its operation.
- (e) Incorporation of modifications.
- 3.2 Owners/Operators must appreciate that a maintenance organisation cannot carry out work or certify inspections without their instructions or agreement, and it follows that they should be quite specific when making known their work requirements to the maintenance organisation. Difficulties regularly occur because there is a misunderstanding between Owner/Operators and the maintenance organisation as to the former's requirements.

The written contract should clearly define what scope for action is allowed the maintenance organisation without prior consultation, and what tasks require the Owner/Operators agreement.

Whenever an aircraft is presented for scheduled or unscheduled maintenance it is essential that a precise indication is given of the work required and of all defects known to exist on the aircraft, plus any additional work required to be carried out.

- NOTES: 1 If the Owner or Operator of a Transport or Aerial Work Category aircraft elects to have his routine maintenance accomplished by a licensed aircraft maintenance engineer it will nevertheless be necessary for him to present the aircraft to a suitably approved organisation for completion of Annual checks and Star Inspections.
  - 2 Private Category aircraft must be presented to a suitably approved organisation for completion of the Annual Check associated with renewal of the Certificate of Airworthiness (Star Inspection).
  - 3 A suitably approved organisation in this context is one approved to the requirement of BCAR Section A, Chapter A8-15, commonly known as an M3 approved organisation.
- 3.3 Difficulties have also occurred where Owner/Operators fail to provide the maintenance organisation with the Log Books for the aircraft at the time the work is initiated, or provides Log Books that have not been kept up to date so as to reflect the current maintenance and operating status of the aircraft, engines and propellers.

In addition to the Log Books, the maintenance organisation must be provided with the LAMS and CAP 543 Time Limited Task and Component Change Record for the particular aircraft before any scheduled maintenance work can be started. The full maintenance history is a prerequisite for completion and certification of a Certificate of Maintenance Review (CMR).

3.4 Provision is made in LAMS Section 6 for the period between certain <u>calendar controlled tasks</u> to be varied (permitted variations) for maintenance planning reasons, provided that airworthiness is not impaired, but only on the authority of a person who is an acceptable signatory for the prescribed Check. Permitted variations for tasks <u>controlled by flying hours</u> however, should not be understood to be a maintenance planning tool, but as an exceptional means to allow Owner/Operators to fly for a limited period of time until the required maintenance is performed.

Owners/Operators who take advantage of permitted variations must ensure that the Log Books are endorsed accordingly by the authorised person at the time the permitted variation is granted. (See Part 3 Para 7)

### **CIVIL AVIATION AUTHORITY**

Safety Regulation Group

### **AIRCRAFT SURVEY REPORT**

REGISTRATION: G-AYLX TYPE: HUGHES 269C SERIAL NO: 900041									
DATE OF SURVEY: 28 October 1999 AIRCRAFT LOCATION: Biggin Hill.									
OPERATORS AOC NO: OPERATORS NAME: —									
MAINTENANCE ORG. APP NO: MAINTENANCE ORG. NAME:									
Status During Survey: Hangar 2 Ramp Issue / Renewal / Export / In-Service / Accident Survey*									
Documents sampled: C of A C of R AFM W/B V Tech. Log ADD W/Pk									
ATA Zones									
Lower half of fuselage 200 Upper half of fuselage 300 Empennage 400 Powerplants and struts									
500 Left wing 600 Right wing 700 Landing Gear 800 Doors									
Survey sample									
Zone ATA Actions Defect Description									
1 200 6210 1.4 Air mtwice Gwd clamp disconnected. 2 200 5600 4 6 Compass Swing required. 3 300 6110 4 6 Compass Swing 24.0896. 4 400 8510 1 1 Main rotor blades installed are 5 100 1100 4 1 Main rotor blades installed are PTNO 269 A 1185M-STC. The Shight marrial supplement is missing From the Shight Mamval.  8 1 These rotor blades are approved 9 1 Sor installation under AAN 23220									
Survey Actions: 1 = Before Flight 2 = Carried Forward [Hangar] 3 = ADD [Ramp] 4 = Nil									
Suitability of facilities for work in progress: Yes No / N/A * Person(s) contacted:									
Areas not listed have not been sampled. All findings have been notified in writing to operators representative.									
Survey carried out by: (Name)									
Accepted by: on behalf of the maintenance organisation									

Normal Procedures Pliot's Flight Manual

SCHWEIZER AIRCRAFT CORP.

Model 269C Helicopter

Section IV

# NORMAL PROCEDURES

## PREFLIGHT REQUIREMENTS 4-1.

- Have a thorough understanding of operating limitations. (Refer to Section II.
- Service the helicopter as required. (Refer to Aircraft Handling, Servicing and Maintenance, Section VII.)
- Determine that the helicopter loading is within limits. Refer to Section II and VI
- Check the helicopter performance data. Refer to Sections V, VI and VIII.
- accomplished within 24 hours prior to the first flight of each day. Determine that a Daily Inspection (in accordance with the Handbook of Maintenance Instructions (HMI)) has been
- Perform a pilot's preflight inspection prior to each flight.

NOTE: Refer to the applicable Lycoming Operator's and Maintenance Manuals listed in Related Publications and Directives table, Section II, Basic HMI for detailed requirements on daily inspection of the en-

ler operator or owner to increase the extent and/or frequency of inspection to promote safe operation It is the prerogative and responsibility of the helicopwhen unusual local conditions (environment, utilization, etc.) dictate.

Group all inspections by locations so that inspection can be performed on an area-by-area basis. Accomplish inspection of the entire helicopter by starting at the front and working in counterclockwise progression. NOTE:

Refer to HMI for complete inspection criteria (Appendix B, Tables B1 through B3)

# PILOT'S PREFLIGHT INSPECTION

4-2.

- normal or not within limits. Examples of conditions to look for are: inoperable equipment, excessive leakage, discoloration due to heat, Visually check the following items for wear, general condition and damage; however, do not limit inspection to the above conditions. obvious damage. Damage is defined as any condition that is not dents, cracks, punctures, abrasion, chaffing, galling, nicks and evidence of corrosion. These are the most common types of
- Perform further inspection prior to the next flight if discrepancies are noted to determine if the rotorcraft is airworthy.
- Flight is prohibited when unrepaired damage exists which makes the rotorcraft unairworthy.

### WARNING

TION SUPPLEMENT C, SECTION 12 NOT IN GOOD OPERATING CONDI-(REFER TO HMI CONFIGURA-THE LANDING GEAR DAMPERS ARE IF HELICOPTER IS OPERATED WHEN GROUND RESONANCE MAY RESULT FOR DETAILED INSPECTIONS. TION.

4-2

Reissued: 21 September 1988 Revised: 03 Nov 1992

SCHWEIZER AIRCRAFT CORP. Model 269C Helicopter
---

Normal Procedures Pilot's Flight Manual

Pilot's Flight Manual

Normal Procedures

SCHWEIZER AIRCRAFT CORP.

Model 269C Helicopter

ENGINE - LEFT SIDE (cont) (3)

IF CRACKING OF CLUSTER FITTINGS IS SUSPECTED DYE PENETRANT INSPECT IN ACCORDANCE WITH SERVICE INFORMATION CHECK NOTICE N-82.3 BEFORE FLIGHT. CAUTION Rear oleo damper extension

CHECK

CHECK

Left navigation light and strobe for damage

or looseness

ENGINE - LEFT SIDE

CHECK

CHECK CHECK

Engine and components, exhaust and intake

Engine sump plug

Engine oil level

tubes, fuel and oil lines

Alternator drive belt and belt tension

Center frame aft cluster fittings for cracks, deformation, or damage

CHECK

4 MAIN ROTOR SYSTEM

Main rotor transmission and mast

CHECK

exterior of boot for cracking, fraying, chips,

and deterioration. If any damage is

Using a flashlight (or equivalent), inspect

Fore and aft movement

Engine lower coupling shaft

observed, replace boot prior to next flight.

CHECK CHECK

Main transmission oil level

Blades and rotor head

Main rotor dampers

CHECK

CHECK

Main rotor swashplate, pitch links, upper and lower bearings

Main rotor mixer bellcrank Main rotor control rods

CHECK CHECK CHECK

CHECK

Tail rotor shaft, set alignment marks

metal-to-metal contact noise is heard, lower

coupling drive shaft and engine adapter

must be removed and inspected in

accordance with Basic HMI, Section 10

Belt drive lower H-frame tie bar bracket

and strut for cracks and security

Aft crossbeam

Battery

Engine impeller (any indication of

(ooseness)

prior to further flight.

contact noise between gear teeth. If any

rotate coupling shaft back and forth to take

up backlash in both directions (CW and

CCW). Listen for hard metal-to-metal

Grasp lower pulley AFT spacer and

shaft for adequate lubrication as follows:

Audibly inspect lower coupling drive

CHECK TAILBOOM LEFT SIDE Tailboom for damage or dents

deformation, damage, looseness and security for cracks, Tailboom supports and fittings -

CHECK CHECK

> Static port clear of obstructions Beacon light

CHECK

CHECK

Tailboom support strut end fitting for cracks, deformation, or damage

for cracks, deformation, damage, looseness Exhaust diffuser installation (if installed) and security.

Revised: 18 Jul 1997 Reissund: 21 September 1988

CHECK

4-6

Reissued: 21 September 1988

Revised: 12 Nov 1997

INSPECT CHECK CHECK

4-5

Page 3 of 6

CHECK	CHECK	CHECK
Ground handling wheel (if installed) in up position with quick-release pin installed	Ground handling wheel handle (if installed); quick-release pin installed	Tail rotor control cable
•	•	•

CHECK	CHECK	

This page is intentionally left blank,

4-8.1

4-8.2

Reissued: 21 September 1988 Revised: 28 Feb 1997

Reissued: 21 September 1988 Revised: 28 Feb 1997

bb) Clutch control cable	cc) Main fuel tank - visual check of contents	dd) Main fuel tank - drain sump & inspect fuel sample	ee) Rear oleo damper extension	Engine components, exhaust and intake tubes	gg) Fuel low point - drain & inspect fuel sample (fuel must be	<u>(no</u>	Landing gear skid tube		Front oleo damper extension	Position light		kk) Door		ll) Canopy slat	mm)Canopy	· ·	nn) Landing light		oo) Pitot tube	ont aerial
bb) C	cc) M	dd) N	ee) R	E) E	gg) F	ÖI	1 hb) L		ii)	ii) F	à	kk) 1		(II	nm)		(mi		(00	bb
Rear oleo damper extension	Engine lower coupling shaft - no end play	Aft crossbeam	Battery	Main rotor transmission and mast (oil level with gearbox ff)		Rotor head, control, rods, blades and dampers	Tail rotor shaft, set alignment marks - no metal to metal hb) Landing gear skid tube	contact in end float		Tailboom, supports and fittings	Anti-collision beacon light		w) Tail rotor shaft alignment	Toil rotor accombly oil level much mill rod and tail skid	tan totol assembly, on revel, proc. present	Horizontal stabiliser, vertical fin and tail light		Tail rotor control cable		It drive system (idle pulley)
0)	(0	(d	(þ	r)		s)	t)			n)	>	3	(M	(	રે	>	ì	(z	4	a <sub>9</sub>
EXTERIOR CHECK	Starting on the LH side check:	Induction system and fairing	Front crossbeam	Landing gear skid tube	Front oleo damper extension	Position light		Door		Canopy slat	Engine oil - check cap secure		Engine sump plug - wired	Emina commonante exhanet and intake tubes		Alternator belt tension		Auxiliary fuel tank - visual check of contents	alumbo Erid Common 9	ixiliary fuel tank - drain sump & inspect fuel sample
c		a)	(q	c)	Đ	(b)	`	(J		ac ac	h)		<u>.</u>		ſ	(X	ĺ			CT .

Copy of the locally produced Pilot's Check List Pre Flight Inspection

### SAFETY REGULATION GROUP

Aviation House Gatwick Airport South West Sussex RH6 0YR UNITED KINGDOM Direct Dial

+44(0)1293 573149 +44(0)1293 573993 Switchboard Fax Telex +44(0)1293 567171 +44(0)1293 573999 878753



Our ref 9/97/CtAw/115

17 March 2000

### LETTER TO OWNERS/OPERATORS NO SCHWEIZER (HUGHES) 269A, 269A-1, 269B, 269C AND 269C-1 SERIES HELICOPTERS FAILURE OF TAILBOOM FITTING ATTACHMENT LUG

An early finding from the Air Accidents Investigation Branch investigation of a fatal accident to a Schweizer 269 helicopter has revealed the failure of a Fitting Attachment Lug (for tailboom support strut) on the Cluster Fitting Part No 269A2234 (see Service Notice N220). The failure was due to an in-service weld repair having been carried out on the Fitting Attachment Lug, although further metallurgical investigations are being carried out.

As a result of this finding and in anticipation of possible mandatory action, the CAA recommends owners/operators of Schweizer 269 Series helicopters, to instigate a one-time visual inspection carried out by an appropriately licensed aircraft maintenance engineer. This visual inspection should cover the Centre Frame Rear Cluster Fittings, the Tailboom Support Fitting, the Support Struts and the Centre Attachment Fitting and look for evidence of any in-service weld repairs. Any parts having in-service weld repairs should be assessed for compliance with the appropriate Schweizer Service Information. It is also recommended that this inspection and assessment be certified in the aircraft log book.

To assist the CAA regarding possible mandatory action, would you please report all findings to Mr D A Marsh, Deputy Regional Manager, Civil Aviation Authority, Safety Regulation Group, Ground Floor, Consort House, Consort Way, Horley, Surrey RH6 7AF (Tel No 01293 828223, Fax No 01293 824014).

Enquiries regarding this LTO should also be referred to Mr D A Marsh.

**RJTEW** 

Applications and Certification Section

- (i) Remove the strut assemblies, P/N 269A2015 or P/N 269A2015-5.
- (ii) Visually inspect the strut aluminum end fittings for deformation or damage and dye-penetrant inspect the strut aluminum end fittings for a crack in with accordance Step II of Schweizer Service Information Notice No. N-109.2, dated September 1, 1976 (SIN N-109.2).
- (iii) If deformation, damage, or a crack is found, before further flight, modify the strut assemblies by replacing the aluminum end fittings with stainless steel end fittings, P/N 269A2017-3 and -5, and attach bolts in accordance with Step III of SIN N-109.2; or replace each strut assembly P/N 269A2015 with P/N 269A2015-9, and replace each strut assembly P/N 269A2015-5 with P/N 269A2015-11.
- (2) Within 500 hours TIS or one year, whichever occurs first, modify or replace the strut assemblies in accordance with paragraph (b)(1)(iii) of this AD.
- (c) For Schweizer Aircraft Corporation Model 269C helicopters, within 100 hours TIS, serialize each strut assembly, P/N 269A2015-5 and 269A2015-11, in accordance with Schweizer Service Information Notice No. N-108, dated May 21, 1973.
- (d) An alternative method of compliance or adjustment of the compliance time that provides an acceptable level of safety may be used if approved by the Manager, New York Aircraft Certification Office (NYACO), FAA. Operators shall submit their requests through an FAA Principal Maintenance Inspector, who may concur or comment and then send it to the Manager, NYACO.
- Note 2: Information concerning the existence of approved alternative methods of compliance with this AD, if any, may be obtained from the NYACO.
- (e) Special flight permits may be issued in accordance with 14 CFR 21.197 and 21.199 to operate the helicopter to a location where the requirements of this AD can be accomplished.
- (f) The inspections and modifications shall be done in accordance with Steps II and III of Schweizer Service Information Notice No. N-109.2, dated September 1, 1976 and Schweizer Service Information Notice No. N-108, dated May 21, 1973, as applicable. This incorporation by reference was approved by the Director of the Federal Register in accordance with 5 U.S.C. 552(a) and 1 CFR part 51. Copies may be obtained from Schweizer Aircraft Corporation, P.O. Box 147, Elmira, New York 14902. Copies may be inspected at the FAA, Office of the Regional Counsel, Southwest Region, 2601 Meacham Blvd., Room 663, Fort Worth, Texas; or at the Office of the Federal Register, 800 North Capitol Street, NW., suite 700, Washington, DC.
- (g) This amendment becomes effective on May 8, 2002, to all persons except those persons to whom it was made immediately effective by Emergency AD



SCHWEIZER SERVICE BULLETIN B-278 06 Sep 2002

- MANDATORY

MANDATORY

MANDATORY =

SUBJECT: 269A2234 BSC AND 269A2235 BSC AFT CLUSTER FITTING MODIFICATION

MODELS AFFECTED: 269A, TH-55A, A-1, B & C Helicopters Equipped with 269A2234 BSC and 269A2235 BSC Aft Cluster-Fittings

NOTE

Helicopters equipped with 269A2234-3 and 269A2235-3 (thick lug) aft Cluster Fittings are not subject to this Service Bulletin, Refer to the Basic HMI Section 13 to distinguish between these fitting types if necessary.

TIME OF COMPLIANCE: • Within the next 400 hours time in service or within 2 years from issue date of this Service Bulletin, whichever occurs first.

REFERENCE: 269A, TH-55A, A-1, B & C Basic HMI; revised 26 Oct 2001.

PREFACE: Schweizer Aircraft Corp. has developed an FAA approved Aft Cluster Fitting Modification Kit (P/N SA-269K-106-1) that is considered an alternate means of compliance for the 50 hour repetitive dye penetrant inspection mandated by AD 2001-25-52 for the 269A2234 BSC and 269A 2235 BSC (thin lug) aft cluster fittings. This kit contains instructions for modification of both 269A2234BSC / 269A2235BSC fittings.

FAA Approval: This Service Bulletin (revision "New") is approved by the Manager, New York Aircraft Certification Office, by letter dated September 06, 2002, as an Alternate Method of Compliance with AD 2001-25-52, paragraph (a).

### PROCEDURE:

- (1) Perform aft cluster fitting inspection mandated by AD 2001-25-52. Replace fittings that are found unacceptable (Basic HMI, Section 13).
  - (2) If fittings meet the requirements of the AD, Install SA-269K-106-1 Kit in accordance with instructions on the SA-269K-106 Kit drawing.
- Becord compliance with Service Bulletin in the aircraft records.

### WEIGHT AND BALANCE

Weight and balance are not affected.

Page 1 of 1