

Piper PA-24-250, G-ASEO, 28 May 1997

AAIB Bulletin No: 8/97 Ref: EW/C97/5/9/025 Category: 1.3

Aircraft Type and Registration:	Piper PA-24-250, G-ASEO
No & Type of Engines:	1 Lycoming O-540-A1D5 piston engine
Year of Manufacture:	1962
Date & Time (UTC):	28 May 1997 at 2000 hrs
Location:	Hermitage Airstrip, Sherborne, Dorset
Type of Flight:	Private
Persons on Board:	Crew - 1 - Passengers - None
Injuries:	Crew - None - Passengers - N/A
Nature of Damage:	Nose landing gear broken off, landing gear operating mechanism, propeller blades and fuselage undersurface damaged
Commander's Licence:	Airline Transport Pilot's Licence
Commander's Age:	48 years
Commander's Flying Experience:	10,482 hours (of which 150 were on type) Last 90 days - 60 hours Last 28 days - 21 hours
Information Source:	AAIB Field Investigation

The aircraft was on a flight from Southampton Airport to Hermitage Airstrip, a private farm strip 5 nm south of Sherborne, near the pilot's home. The wind was very light, from the east, visibility was good and there was no cloud. Hermitage has a grass runway, oriented 08/26, with an LDA of 450 m in either direction. The runway is described as undulating, high at the east end and the centre and low at the west end. The pilot described it as rising sharply from the 08 threshold to a crest approximately half way down the strip.

When the aircraft arrived over the airstrip the sun was low and bright in the western sky and the pilot elected to land on Runway 08. He executed a normal approach, curved to the left to avoid high trees, intending to touchdown as early as possible on the relatively short strip. He had once previously landed on Runway 08, but on that occasion had touched down further along the strip, beyond a path crossing the strip a little distance from the start of the runway.

He selected the landing gear down, and confirmed that the greengear locked down light was lit. Conscious that the initial part of the runway rose quite steeply, the pilot flared the aircraft at the same time as he yawed it to straighten the approach. A witness near the touchdown point reported that the aircraft executed a tight circuit and was in a right skid with a flat pitch attitude relative to the ground as it touched down, very near to the start of the runway. The pilot believed that the left main landing gear touched down first, not very hard, and he immediately became aware that it was collapsing, but too late to prevent a touchdown on the right main landing gear, which also collapsed. He attempted to hold the nose up as long as possible; as it dropped to the ground he turned the fuel tank selector off. The aircraft yawed to the right but came to rest on the runway, on the uphill portion, and the pilot, who was uninjured, vacated the aircraft without difficulty after completing the checks. There was no fire.

A small fuel leak from the left wing was noted as the aircraft yawed across the runway and thus with its right wing low. The main and auxiliary fuel tank in each wing had been filled before departing from Southampton and the left main tank had been used to supply the engine during the 30 minute flight. The maintenance organisation that recovered the aircraft believed that the leakage was likely to have been from the vent of the left auxiliary tank, which remained full.

The pilot reported that there had been no bump or jolt of any magnitude on touchdown and that he had been surprised at the landing gear collapse. However, on subsequent inspection he considered the ground to be rough at the point where he had touched down and believed that this had caused overload failure of the landing gear.

It was reported that marks of the main wheels running on the runway surface were apparent, without any signs of heavy initial contact but with the track narrowing with distance along the runway, consistent with the main landing gears progressively retracting inwards. No nose wheel contact marks or tracks were evident.

Examination of the aircraft by a maintenance organisation and of some components by AAIB found no signs of pre-accident anomaly with the landing gear system, although its rigging could not be checked. System operation is by means of an electric actuator in the fuselage that is connected to the downlock linkage on each leg, via a bowden type cable in the case of each main leg and via a push-pull rod for the nose leg. Each downlock is formed by a two-part overcentre linkage that, with the gear locked down, is maintained overcentred by springs and by the operating mechanism. The main legs retract inwards and the nose leg retracts aft. The piston portion of the nose landing gear leg had bent through about 30° and snapped off in a manner consistent with gross rearward overload on the wheel. The wheel and broken-off part of the leg were recovered from the nose gear bay. Both main legs were found partially retracted, with severe overload damage to the operating mechanism. This consisted of compressive buckling failure of the right main leg operating cable conduit and displacement of the actuator, both consistent with overload applied by landing gear legs forcibly retracting under the influence of ground reaction loads from an unlocked condition. However, no damage was evident to the mounting structure or the downlock mechanism of any of the three landing gears.

The evidence suggested that the nose gear had fractured on touchdown when in a downlocked condition. It appeared likely that the nose wheel and broken-off portion of leg, on entering the nose gear bay, had contacted the downlock mechanism and unlocked the nose gear, allowing ground reaction loads on the remaining part of the leg to be transmitted to the actuator by the operating rod, thereby displacing the actuator and unlocking the main legs.

