

DH82A Tiger Moth, G-AOBJ

AAIB Bulletin No: 6/98 Ref: EW/C97/8/9 Category: 1.3

Aircraft Type and Registration:	DH82A Tiger Moth, G-AOBJ
No & Type of Engines:	1 Gipsy Major 1C piston engine
Year of Manufacture:	1942
Date & Time (UTC):	20 August 1997 at 1831 hrs
Location:	Cardiff Airport, Wales
Type of Flight:	Private
Persons on Board:	Crew - 1 - Passengers - 1
Injuries:	Crew - 1 serious - Passengers - 1 serious (subsequently fatal)
Nature of Damage:	Aircraft destroyed
Commander's Licence:	Private Pilot's Licence
Commander's Age:	54 years
Commander's Flying Experience:	740 hours (the majority of which were on type) Last 90 days - 11 hours Last 28 days - 8 hours
Information Source:	AAIB Field Investigation

History of flight

The pilots of two Tiger Moth aircraft, G-ANFI and G-AOBJ, planned to carry out air-to-air photography with the photographer in 'FI'. The pilot of 'FI' made the radio calls for both aircraft and they entered Runway 30 at taxiway 'H'. They were cleared to takeoff at 1829 hrs. 'FI' took off first, followed after a few seconds by 'BJ'. The pilot of 'FI' turned right onto the downwind leg; when he last saw 'BJ' flying it was climbing on the runway heading at about 150 feet agl.

The ATC controller saw 'BJ' start to turn crosswind but his attention was momentarily drawn to an aircraft on final approach. When he looked back, 'BJ' was descending in a nose down attitude, banked to the right. It then disappeared behind a hangar to the northwest of the Control Tower, only to reappear seconds later climbing in a steep nose up attitude, tracking crosswind. It was reported to

be "twisting and yawing" as it turned to the left and then descended into a field just outside the airfield perimeter. Aircraft accident action was initiated at 1831 hrs and the Airport Fire Service (AFS) was on scene at 1832 hrs.

Both occupants were seriously injured in the impact; the pilot had managed to escape from the wreckage, but the passenger was trapped in the front seat and had to be cut free by the AFS. The pilot of 'FI' landed and went to the accident site. The pilot of 'BJ', who was conscious and a few feet from the wreckage, told him that he had been unable to move the ailerons to the left due to a restriction. Both casualties received first aid treatment and, at 1855 hrs, were transferred to hospital by ambulance.

The passenger was a qualified pilot. An injury to his left ankle was of the type that is associated with the application of left rudder at impact. He also suffered head injuries and was unable to recall any detail of the flight. The pilot subsequently died of his injuries three months after the accident.

Meteorology

An accident special observation was made at 1836 hrs. It contained the following:

Surface wind 300°/7 kt

Visibility 3,500 metres

Weather Haze

Cloud 1 octa, base 3,000 feet

Temp/Dew point 22°C/18°C

QNH/QFE 1016 mb/1008.4 mb

Brief history of the aircraft

The aircraft was built by Morris Motors Ltd in 1942 and entered RAF service in 1943. It was eventually sold and converted for civilian use, and registered as G-AOBJ. The registration was cancelled when it was exported to Europe. It was transported to the USA in 1972, where it operated until 1990, when it was re-imported into the UK. Considerable re-work on the airframe and engine was then carried out. It was re-registered as G-AOBJ and issued with a Certificate of Airworthiness, in the Private Category, in May 1992. The most recent maintenance was an Annual Inspection, carried out in April 1997. This aircraft was not fitted with anti-spin strakes or leading edge slats, nor was it required to be.

Engineering investigation

The aircraft had crashed on a heading of 120°(M) in a steep nose-down attitude, estimated to be around 40°. It was apparent that some left yaw had been present at impact, as the left wing had suffered severe disruption. In contrast, the lower right wing was only slightly damaged as a result of ground contact on its leading edge, and the upper right wing was undamaged, not having contacted the ground. There was no groundslide, with the aircraft having come to an immediate halt, resting on its collapsed main landing gear, nose and lower left wing. The tail structure had remained clear of

the ground, apart from a light impact on the left tailplane tip. A curious feature therefore was the fracture of the tail skid spring close to its attachment fitting on the underside of the rear fuselage. The fracture was fresh in appearance, and it was concluded that it may have been caused by inertial loads at impact. There was no evidence that it had impeded operation of the rudder.

The fuel tank was leaking slightly after the accident. However several gallons of fuel were drained before the wreckage was recovered, and so it was concluded that there had been adequate fuel on board at the time of the accident. One propeller blade had broken off and was found lying underneath the aircraft. The remaining blade was undamaged, not having struck the ground. The broken blade sections showed no evidence of leading edge impact damage or circumferential scuffing, thus suggesting there had been little or no power, or even rotation, at impact.

Following an on-site inspection, the aircraft was recovered to the AAIB's facility at Farnborough for a detailed examination

Detailed examination of the wreckage

Flying controls

In view of the pilot's reported comments immediately following the accident, the investigation initially focused on the flying controls. The aircraft was equipped with dual controls, with much of the cockpit components enclosed within a wooden compartment attached to the floor of the cockpit. The front and rear control columns were attached to the aileron torque tube, which extended along the length of the compartment. A lever arm at the rear of the torque tube protruded downwards through a transverse slot cut in the floor of the rear cockpit. Aileron operating cables were attached to the end of the lever and were in turn connected, via turnbuckles, to chain assemblies in the lower wings. The chains located onto sprocket wheels which were connected to the ailerons by means of adjustable rods.

No disconnections had occurred in the flying control operating system in the accident, although the structure in which many of the components were located had been damaged. The wooden compartment on the cockpit floor had split open in the impact. The controls in this area were examined for evidence of a jam or restriction. There was clearly scope for a loose article to cause such a problem, especially if it had become lodged in the slot in the cockpit floor. However there was no evidence of foreign objects, jammed or restricted controls in the post accident condition.

Both control columns had broken off near their bases, within the gaiters on the top of the wooden compartment. Examination of the fracture of the rear column indicated that it had broken off in a forwards direction, due to pilot induced loads in the impact. The front column had failed in a predominantly rearwards direction, due to the front left side of the cockpit structure and instrument panel having crushed inwards and rearwards onto it, suggesting that the front seat occupant had not been holding it.

The cable runs in the lower mainplanes were examined, but no problems were found. The sprocket and chain assemblies, to which the cables were attached, were effectively built into boxes, with the upper surface being formed by the wing fabric, and the lower by an aluminium alloy cover plate. The cables entered the boxes, which were otherwise sealed against foreign object ingress, through small apertures in the inboard ends, and then joined onto the chains via the turnbuckles. Two wooden ribs within each box were protected, with alloy plates, from abrasion by the chains and

turnbuckles. These also limited the amount of vertical movement of the chains in the event of slack cables, and thus assisted in keeping the chains located on the sprocket teeth. In addition, guides in the form of leaf springs were located in the tangent areas where the chain met the sprocket teeth.

On the undamaged right wing, the chain was found properly located on the sprocket wheel and the associated aileron operated normally (although its operating rod had been damaged during wreckage recovery). Even after the cables had been cut, thus eliminating any tension in the system, the chain could not be encouraged off the teeth. The chain in the left wing was found partially off the sprocket wheel, which in fact limited the movement of its associated aileron. However, the alloy cover plate had been torn off during the impact, and this had resulted in the fracture of one of the shielded wooden ribs. It was found that with the excessive amount of vertical movement of the chain that could then occur (with slack cables), it was possible to encourage the chain to become disengaged from the sprocket without too much difficulty. In the absence of any witness marks on the sprocket teeth and chain links, it was concluded that the left chain came off the sprocket during the impact.

It was noted that one of the turnbuckles in the left wing was badly bent on the end that connected to the chain. This had resulted in a 'kink' in the chain-to-turnbuckle connection such that the latter contacted the side of the sprocket assembly box structure when cable tension was applied. This condition had clearly existed for some time, as a light wear pattern could be seen on the side of the enclosure. However, this interference was not sufficient to produce a jam of the aileron operating system. Although it was not immediately obvious as to how the turnbuckle had become bent, it was found that if the sprocket wheel was rotated to a point at, or beyond, the full right stick position, the shackle linking the chain to the turnbuckle contacted the sprocket teeth in a manner that displaced the turnbuckle into the side of the box structure. A small amount of additional rotation of the sprocket wheel may result in bending of the turnbuckle. However, rotation could not occur beyond a point where the shackle became wedged between the sprocket teeth and its associated chain guard. The accompanying photographs show the sprocket wheel and turnbuckle details. The wedged position of the shackle appeared to produce the as-found amount of distortion in the turnbuckle, and there were contact marks on the side of the box structure that could have been caused by the bending process. However, there were no heavy contact marks on either the shackle or sprocket teeth, and the shackle was easily released from the wedged position, i.e. the system could not be made to jam.

Assuming that the turnbuckle did in fact become bent as a result of the shackle contacting the sprocket teeth, it is considered that the bending may have occurred as a result of multiple applications of full aileron deflection, such as during 'full and free' flying controls checks. The reason the shackle was able to contact the sprocket appeared due either to mis-rigging, or more probably, due to excessive aileron system travel (see below).

It was found that there were two relevant modifications that applied to the aileron system. In 1941, Tiger Moth Modification 101 introduced improved aileron stops which, in the case of GAOBJ, would have been incorporated at build. These took the form of hardwood blocks screwed to the underside of the cockpit floor at the ends of the aileron lever slot. The modification sheet stated that: *'cases had occurred of jamming and failure of the aileron controls in the bottom wing due to the chain and anchorage shackles coming into contact with the aileron sprocket teeth.'* It was found that on certain aircraft the slot in the floor had been cut too long, thus allowing excessive travel of the control cables. Subsequently, in 1943, Modification 101 was superseded by Air Ministry Modification No 125. This introduced an improved aileron sprocket chain guard and reduced the aileron lever slot length to 5 inches in order to reduce the possibility of the chain riding up on the sprocket due to sagging cables, or when the control column was at full deflection. Modification No

125 was declared mandatory by the CAA and its status is discussed in Technical News Sheet (TNS) Nos 1 and 5, issued by British Aerospace, which is the Type Design Organisation for Tiger Moth aircraft. Thus Modification No 125 was designed to eliminate the very condition that was found on G-AOBJ, notwithstanding the fact that a control jam could not be reproduced.

G-AOBJ was found to have the sprocket guards, but there was no evidence of any aileron lever stops ever having been fitted to the underside of the cockpit floor, and the lever slot was found to be approximately 6.5 inches in length. Nevertheless, the modification statement in the aircraft log book listed Modification No 125 as "Found complied with", dated 6 May 1992. There were no log book entries which indicated that any additional work had been carried out in this area.

Engine and fuel system

The fuel tank on a Tiger Moth forms the upper wing centre section, and is mounted on struts on the forward fuselage, ahead of the front cockpit. The ON-OFF cock is mounted on the tank underside, and is connected by rods and bellcranks to a knob on the left side of each cockpit.

Inertial loads during the impact had caused the tank to apply compressive loads to the struts, thus crippling them. This relative movement between the tank and the fuselage had applied an input to the fuel cock operating linkage in a manner which had tended to drive the cockpit end of the linkage towards the ON direction. The loads had been sufficiently severe to drive the rear cockpit selector knob into a paxolin guide block such that it had been distorted. A bellcrank at the forward end of the cockpit linkage had also been moved in the impact, and it was apparent that one of its arms had come into contact with an adjacent throttle control rod, such that black paint on the latter had been scraped off. The extent of the scraped area suggested that the fuel cock bellcrank had been moved during the impact from a position which had been close to OFF. Taken in conjunction with the lack of power indication on the propeller, this evidence raised the possibility of the engine having failed due to fuel starvation. However the nature of the evidence was somewhat tenuous, and in fact it was possible that additional linkage movement occurred during a recoil process following the impact. It was noted that the fuel cock linkage had no detent or over-centre mechanism, but relied simply on friction to maintain the selected position. During the investigation some anecdotal evidence emerged, concerning other Tiger Moth aircraft, which suggested that the mechanism was susceptible to movement due to vibration, with an attendant risk of power failure. It was noted that aircraft on the Australian register have a mandatory modification (Reference DCA/DH82/2) which introduced a locking clip on the fuel cock ON-OFF selector.

The engine was taken to an overhaul agent for a strip-examination. This revealed that the components were in generally good condition. The magneto timing was checked, and the right hand (impulse) unit was found to be correctly timed to 30° before top dead centre (BTDC), with respect to the No 1 cylinder. However, the left hand magneto was timed to top dead centre (ie 0° BTDC). It was considered that this error was the result of timing the magneto with the throttle closed as opposed to open; this would have introduced a 30° angular error in the associated ignition advance ring (which was connected to the throttle) on the magneto. It was then observed that the internal mechanism was 180° out of position. However, the situation had been recovered by transposing plug leads Nos 1 with 4, and Nos 2 with 3. It was concluded that despite the timing error, the engine would have run reasonably normally, although there may have been a larger drop in rpm with the engine running on the left magneto compared to the right.

The carburettor and associated hot air system was checked and found to be satisfactory apart from a slight leak when the unit was connected to a pressurised fuel supply.

Seat harnesses and survivability issues

The harnesses were the original 'Sutton' type which consisted of lap and shoulder straps made from canvas webbing, reinforced locally with leather. The shoulder straps terminated in small pulley assemblies located on a cable that was fixed across the fuselage at the rear of each cockpit. This type of harness has not been manufactured for many years and the age of this particular harness was not recorded.

The right hand attachment of the front cockpit shoulder restraint cable had failed in the impact. This had allowed the occupant's torso to flail forwards, which may have contributed to his head injuries. The cable attachment brackets had been the subject of Technical News Sheet (TNS) No 12 (although this had not been mandated by the CAA), which called for 50 hour inspections for signs of corrosion. In addition, the TNS specified a check to ensure that the brackets were attached to the fuselage longerons by means of high tensile steel (HTS) bolts. The remains of one of the failed bolts on the right hand side, together with both the intact bolts from the left side, were subjected to hardness tests (the second bolt from the right hand side was not recovered). These revealed that two bolts were made from low tensile steel, with one of the intact bolts being of medium tensile strength steel. The aircraft log book contained entries, coinciding with the annual inspections (including the most recent one in April 1997), which recorded compliance with TNS No 12.

In the rear cockpit, the shoulder restraint cable had broken at its mid-point. In addition, the right hand lap strap had torn completely through, close to a stitched joint that attached one of the leather reinforcing strips. This had caused the rear seat pilot to be effectively unrestrained, with the result that he sustained facial injuries, together with a severe chest injury due to contact with the P-type compass that protruded from the instrument panel. Both occupants had additionally suffered severe back injuries as a result of the high vertical component of the impact forces.

The shoulder harness cables were of the correct diameter and appeared to be in reasonable condition; the rear seat cable had failed purely as a result of overload.

Sutton harness failures have featured in previous accidents, most recently involving Tiger Moth G-ANPK, which was reported in AAIB Bulletin 2/97. Tests on that aircraft indicated that although the webbing did not appear to be in a significantly deteriorated condition, it had actually lost between 50 and 75% of its strength. It was considered that as this harness type has not been available for many years, it was reasonable to assume that equipment which remains in service may be similarly deteriorated. The harness webbing in G-AOBJ was noted to be stiff, dirty and frayed in several places, with deteriorated stitching on the leather reinforcing. Although the Light Aircraft Maintenance Schedule (LAMS) calls for regular visual inspections of harnesses, they are not generally subjected to periodic load tests due to the risk of damaging them. By way of comparison, RAF aircraft harness webbing, both canvas and nylon, has a maximum in-service life of ten years.

Safety Recommendation 96-59 (first published in August 1996 in another AAIB accident report, Air Accident Report 4/96, and re-stated in AAIB Bulletin 2/97 referred to above) stated:

"The CAA should give detailed consideration to requiring a programme of sample testing of aircraft harnesses aimed at establishing their fitness for continued use and, if necessary, imposing a life limitation"

The CAA conducted an investigation into all types of harness, but concluded that; "...there is insufficient evidence in the findings of this report (*ie Air Accident Report 4/97*) to indicate the need for [such a programme]...".

Discussion

The pilot's comments in the immediate aftermath of the accident and subsequently in hospital indicated that the accident could have been caused by a loss of control following an aileron jam or restriction.

It was found that a mandatory modification which was designed to limit the amount of aileron travel was not completely embodied on this aircraft. It is probable that the resulting excessive cable travel which this omission allowed had repeatedly caused a turnbuckle shackle to contact the left aileron sprocket wheel (when full right aileron was applied), which eventually caused the turnbuckle to become bent. However, despite this condition the tests conducted on the aileron system did not succeed in reproducing an aileron jam or restriction, although in-flight dynamic loading effects could not be reproduced. Nevertheless, the justification for the aileron system modification indicated that such a jam could occur. The Type Design Organisation has asked the de Havilland Moth Club to inform their members of the importance of Modification 125, as discussed in TNS No. 5. In addition the CAA, in response to a request from the Type Design Authority, has published an article on the subject in a recent edition of the General Aviation Safety Information Leaflet (GASIL), issue number 1 of 1998 (February).

The investigation was complicated by the lack of power indications on the propeller, together with evidence that suggested the possibility of the fuel cock having been near the OFF position before the impact. If a power loss had occurred immediately after take off, because the fuel cock had moved from ON to OFF due to the effects of vibration on the associated linkage, and the aircraft had stalled as a consequence, there is the possibility that the airflow over the ailerons, with the wings in a stalled condition, may have resulted in 'snatch loads' (which reportedly can occur in the aileron circuit under such conditions) that may have been interpreted by the pilot as an aileron restriction, or jam. The subsequent final climb observed could have been achieved without power by trading speed gained in the preceding descent for height.

However since the pilot did not think that he had suffered a power loss, and if his recollection was correct, the apparent lack of power on the propeller may have been due to his final closure of the throttle and fuel cock in recognition of his inability to control the aircraft sufficiently, as a result of an aileron restriction or jam, to avoid the impending ground impact. The Controller's observations of the aircraft 'twisting and yawing' as it turned left before the ground impact could be consistent with left rudder inputs to oppose a right roll tendency.

Safety recommendations

The condition of the wreckage indicated that the impact had been sufficiently severe to be at the margin of the 'survivable' category. However both occupants did survive, although the pilot died later as a result of complications from injuries probably sustained as a result of the failure, in two places, of his Sutton harness.

Over the years many Tiger Moth aircraft have been fitted with replacement harnesses made from modern synthetic materials. This is especially the case in Australia, where Sutton harness have been prohibited for almost 30 years on such aircraft. This accident has highlighted the shortcomings of

this type of harness, with the result that the following Safety Recommendation has been made to the CAA:

Recommendation 98-40

In order to avoid unnecessary injury to the occupants of vintage aircraft during accidents, and since most Sutton harnesses currently fitted to such aircraft in service are likely to be in a deteriorated condition, it is recommended that all affected aircraft, including the de Havilland Moth series, be the subject of mandatory action by the CAA to equip them with improved modern harnesses.

This investigation revealed the potential for the fuel cock linkage to move, under the influence of vibration, towards the OFF position. As with the Sutton harness issue, this has been recognised by the Australian regulatory authority, which has addressed this problem by means of a simple modification. The following Safety Recommendation has therefore been made:

Recommendation 98-41

It is recommended that the CAA, in conjunction with the Type Design Organisation for the DH 82A Tiger Moth, make available a mandatory modification which ensures that the associated fuel cock linkage resists any tendency to displace due to engine vibration and remains in the ON position, unless otherwise selected OFF.