

# Boeing 757-236, G-BIKW

## AAIB Bulletin No: 3/98 Ref: EW/C97/2/2 Category: 1.1

<b>Aircraft Type and Registration:</b>	Boeing 757-236, G-BIKW
<b>No &amp; Type of Engines:</b>	2 Rolls Royce RB211-535C-37 turbofan engines
<b>Year of Manufacture:</b>	1986
<b>Date &amp; Time (UTC):</b>	10 February 1997 at 1248 hrs
<b>Location:</b>	Manchester Airport
<b>Type of Flight:</b>	Public Transport
<b>Persons on Board:</b>	Crew - 9 - Passengers - 89
<b>Injuries:</b>	Crew - 1 (minor) - Passengers - 1 (minor)
<b>Nature of Damage:</b>	None
<b>Commander's Licence:</b>	Airlines Transport Pilot's Licence
<b>Commander's Age:</b>	46 years
<b>Commander's Flying Experience:</b>	12,700 hours (of which 4500 were on type) Last 90 days - 150 hours Last 28 days - 41 hours
<b>Information Source:</b>	AAIB Field Investigation and Operators' Air Safety Reporting System

The aircraft landed on Runway 24, with a surface wind of 270/20 to 30 kt following a shuttle flight from Heathrow to Manchester. The runway state was given as wet, although it was actually dry along the centre portions and damp at the edges. Auto brake was selected to level 2 with the Commander handling and the First Officer briefed to select reverse idle only.

The landing was normal and after eight seconds, at a speed of 95 kt the autobrake was cancelled by application of moderate pressure on the brake pedals to achieve a rapid exit. A few seconds later a severe vibration was felt through the airframe; the rudder pedals were pulsating violently such that the Commander had difficulty keeping his feet on them. He felt the brakes were also pulling to the right. The aircraft came to a stop beside Rapid Exit X. The First Officer interrogated the Status page on the Engine Indication and Crew Alerting System (EICAS) which showed all brakes to be cold with no warnings.

The fire service attended but could find nothing abnormal. Following an inspection by the airline's maintenance personnel they noted that none of the main tyres had flat spots but there were heavy rubber deposits on the runway for the last 10m from the Right Main Gear. The aircraft was towed to a stand where the passengers disembarked normally. After applying the parking brake on stand, it was noticed that the brake accumulator pressure was nearly depleted. One passenger and the First Officer complained of "whiplash" type neck injuries and they received medical attention.

### **Initial Investigations**

Once on stand all the main wheels were jacked and checks were carried out but no faults were found. The main wheel inner bearing on No 6 was found to be "noisy" and the wheel was replaced. A BITE check was carried out on the autobrake/antiskid control unit; this showed a fault in the 2 to 6 channel. The control unit was changed and following additional anti-skid and brake functional tests, which revealed no faults, a high speed taxi and brake trial was conducted. The aircraft was then flown to Birmingham where 3 landings were performed satisfactorily, but on return to Heathrow some minor vibration was felt through the brake pedals. Further engineering investigation was then carried out.

### **Flight Recorders**

The Operators' Quick Access Recorder (QAR) was used to obtain data for the incident; it contains the same information as the accident FDR as well as some additional parameters. The touchdown speed was 123 kt, the speed brake and reverse thrust were immediately deployed. The initial deceleration was around -0.15G. After eight seconds at around 95 kt, the wheel braking discretises show that the pilot applied manual braking; the brake pressures are not recorded. The deceleration increased then to around -0.25G, before decreasing gradually after 16 seconds to -0.118G. The longitudinal deceleration then increased to -0.452G as the aircraft stopped and there was a slight change in heading recorded of around 4° left and then 9° right.

The brake temperatures were all constant at around 100° except for No 6 which began to increase after the aircraft had stopped. The maximum recorded value was 134° and it was still increasing when the recording stopped 3 minutes after touchdown.

### **Antiskid/Autobrake System**

The antiskid/autobrake system schematic is shown in Figure 1. The antiskid system is designed to prevent wheels skid by limiting hydraulic pressure to the brakes. It senses a rapid reduction in wheel speed as a skid, and releases the brakes. The autobrake system provides automatic braking with the braking level being selected by the pilot. The system controls both normal and alternate brake systems through antiskid valves. Eight normal valves control the individual wheels, four alternate valves control the lateral-pair wheels.

The autobrake system maintains a constant pilot-selected deceleration level during the landing roll, there is no interference with the normal antiskid system operation. There are five levels of autobraking which can be selected, 1 to 4 and maximum. In this case autobrake level 2 was selected. The autobrake can be deactivated either by selecting the switch to OFF or, as in this case, by manual brake application.

Normal braking is provided by the right hydraulic power system, alternate braking is provided by the left hydraulic power system which takes over if right hydraulic pressure is less than 1,500psi.

With both hydraulic systems powered, left hydraulic pressure cannot reach the brake system. The alternate brake selector valve prevents the left system fluid from reaching the brake system when the right system is powered.

### **Subsequent Engineering Investigation**

The investigation focused on the anti-skid system. Both the left and right normal anti-skid modules were changed, following which a system check was performed which showed that a rapid brake application using the alternate (left hydraulic) brake system, with the right hydraulic system depressurised, could produce a vibration which was felt through the pedals. However there was no evidence that the aircraft had been using the alternate system during the incident.

The left normal and left alternate brake metering valves were interchanged and rerigged; there was still significant vibration on the alternate system. The only way that the aircraft alternate system could be active was for the alternate brake selector valve to be causing reversion to the alternate system. The alternate brake selector valve was therefore changed, as were both the left and right alternate brake metering valves. The vibration was still present when the brakes were powered through the alternate (left hydraulic) system; no vibration was demonstrated with the normal (right hydraulic) system.

During the function checks it was also noticed that the accumulator pressure dropped when the alternate (left hydraulic) system was engaged and the brakes exercised. The brake selector valve and the accumulator isolation valve were changed. No. 6 brake and transducer were changed following tests which showed that the vibration could not be reproduced when brake No 6 was disconnected.

A flight test was carried out which showed the brakes to be 'fierce' and a vibration was noted during hard braking through the left pedal on the normal system. Following further functional tests in conjunction with the manufacturer and a bleed of the hydraulic system, a taxi test was carried out using the normal braking system which was found to be functioning satisfactorily, the aircraft was returned to service. No further problems have been reported. The bleed of the hydraulic system revealed large amount of air in the system, introduced during the significant number of component changes, which may have been the cause of the problem on this test flight.

Although the cause of the incident could not be established the following four items were identified:

Failure of the anti-skid/autobrake control unit (Channels 2 and 6). This unit was changed at Manchester after the incident and returned for testing. No fault was found which could account for this incident.

The alternate brake system should not operate until the normal system pressure is below 1,500 psi. The alternate brake selector valve was changed.

Vibration of the brake metering valves was attributed to cumulative wear of all the components in the system and the slight out-of-rig of the normal/alternate interconnect system. System components were changed and rigging performed. This was a hidden defect as the alternate system does not normally function.

The left hydraulic system pressure should not drop when the left hydraulic system is used for braking. The accumulator isolation valve (AIV) was changed. The manufacturers' investigation

concluded that these characteristics were the result of saturation of the left system electric pump during hard and rapid brake pedal application. The resulting pressure droop allows the AIV to shuttle momentarily and a small amount of accumulator fluid to escape into the normal brake system. These characteristics are not experienced during normal aircraft operation when the engine driven hydraulic pumps are used.