

## ACCIDENT

<b>Aircraft Type and Registration:</b>	Boeing 747-400SF, B-HKH
<b>No &amp; Type of Engines:</b>	4 Pratt and Whitney 4056 turbofan engines
<b>Year of Manufacture:</b>	1991
<b>Date &amp; Time (UTC):</b>	31 May 2010 at 0700 hrs
<b>Location:</b>	London Heathrow Airport
<b>Type of Flight:</b>	Commercial Air Transport (Cargo)
<b>Persons on Board:</b>	Crew - 3                      Passengers - None
<b>Injuries:</b>	Crew - None                      Passengers - N/A
<b>Nature of Damage:</b>	Failure of end attachment fittings of right wing gear support beam and damage to surrounding panels
<b>Commander's Licence:</b>	Airline Transport Pilot's Licence
<b>Commander's Age:</b>	36 years
<b>Commander's Flying Experience:</b>	7,660 hours (of which 1,694 were on type) Last 90 days - 73 hours Last 28 days - 15 hours
<b>Information Source:</b>	AAIB Field Investigation

## Synopsis

The flaps were slow to retract when the crew selected them after landing. Subsequent inspection revealed damage to panels surrounding the inboard flaps on the right wing and that the outboard end fitting of the right wing landing gear support beam had failed. The manufacturer was aware of the potential for water ingress behind the main bushing in the end fitting to lead to corrosion, and subsequent cracking, and had issued an Alert Service Bulletin in November 2009 detailing inspection requirements and remedial actions.

## History of the flight

The aircraft was operating a freight service from Delhi to London Heathrow. The flight and landing were reported

as routine by the crew and analysis of the recorded flight data did not reveal any anomalies. During taxiing after landing the crew observed that the wing flaps were slow to retract and after shutdown a 'FLAP CONTROL' status message was displayed. This was recorded by the crew in the aircraft's technical log.

During post-flight inspections by an engineer, damage was identified to wing panels above and below the inboard flaps on the right wing and the flaps appeared out of alignment (Figure 1). Further investigation showed that the outboard end fitting of the wing landing gear support beam had failed. The aircraft was withdrawn from service for further inspection and repair.



**Figure 1**

Rear view of aircraft, showing misalignment of inboard flaps

### **Other aircraft damage**


Following the failure of the outboard fitting, the wing support beam was able to move slightly within the 'gate' fitting, which caused damage to panels above the beam and hydraulic pipes beneath the beam. The inboard flap track is partly mounted on this beam and its movement caused misalignment of the right inboard flaps, leading to damage of the adjacent fairing panels when the flaps contacted them during retraction.

### **Description of failed components**


The outboard end fitting on this aircraft consisted of two high strength steel plates fastened to the wing landing gear support beam by seven bolts (Figure 2). The end fitting is used to attach the beam to the rear wing spar

using a gate fitting assembly. The design of the fitting specifies that the mounting holes in the plates are lined with bushings and all parts are plated to prevent corrosion. The bushes are a tight interference fit and installed with sealant to prevent moisture ingress.

Both fittings on the right wing had failed due to cracks radiating from the main bore of the fittings (Figure 3a and 3b). Significant areas of corrosion were apparent in the bore close to the cracks.



**LEFT WING LANDING GEAR (WLG)**  
(RIGHT WLG OPPOSITE)



**LEFT WLG GATE FITTING**  
(RIGHT WLG GATE FITTING OPPOSITE)



*Figures by courtesy of Boeing*

**Figure 2**

Illustration showing location of failed component  
(left wing shown but actual failure on right wing)



**Figure 3a**

General view of failed forward fitting, right wing



**Figure 3b**

General view of failed aft fitting, right wing

The fittings on the left wing were inspected using the inspection technique detailed in the manufacturer's Alert Service Bulletin (747-57A2331) and the forward fitting was found cracked (Figure 4).

### Examination of failed components

The failed components from the right wing were removed from the aircraft and taken to a specialist forensic metallurgical laboratory for detailed examination. Extensive corrosion was found in the main bore of the fittings. This had allowed the initiation and the development of cracks which had propagated extensively through a 'fatigue' mechanism before separation occurred. It was not possible to determine how long the failure had taken to propagate before final failure occurred. There was no evidence to suggest that

the material properties played a part in the failure and the end-plate material appeared to comply with the design specification. There was evidence of cadmium on both the fitting and the main bush. There was evidence in the main bore of the fitting of smearing of the bush material on the fitting, indicating that the bush had rotated in the fitting in service.

The cracked forward fitting from the left wing was returned to the manufacturer for examination. Detailed analysis confirmed that the parts had been manufactured to specification apart from the large bushing, which showed no evidence of the plating which is now required. However, up to September 1989 it was not required that the bushing should be plated and it is possible that this fitting was manufactured before this date. The



**Figure 4**

Close up of forward fitting, left wing,  
showing bushing, corrosion around main bore and crack

manufacturing records that would have confirmed this had not been retained. Evidence did show that the large bushing had rotated in the fitting and as a result the sealant was dislodged allowing moisture ingress into the joint.

### **Aircraft history**

This aircraft was delivered as a passenger-carrying aircraft to the original operator in January 1991. At the end of 2005 it was transferred to the current operator who converted the aircraft to a freighter configuration, in accordance with a manufacturer-designed scheme and it resumed flying operations in July 2006. It had flown a total of 69,040 hours and 12,861 cycles at the time of the accident.

### **Previous type history of similar issues**

The aircraft manufacturer had been aware of corrosion in the end fittings of wing landing gear support beams in earlier production aircraft of this type. This issue was addressed in a Service Bulletin (747-57-2244) which became the subject of a Federal Aviation Administration (FAA) Airworthiness Directive (89-15-07). These provided inspection, rework and terminating action for the end fittings. The revised design was incorporated into subsequent production aircraft, including this one.

More recently the manufacturer had become aware that the problem was recurring and in November 2009 issued Alert Service Bulletin 747-57A2331. This superseded the terminating action described in 747-57-2244 and included detailed instructions for inspecting the end fittings and, dependent on the findings, instigated repeat inspections or rework of the end fittings to improve corrosion resistance. Timescales for the completion of these tasks were given dependent on the configuration of the aircraft. This particular aircraft required initial

inspection within 8 years of construction or within 18 months of the issue of the bulletin, whichever was the later; the latest compliance date in this case was therefore May 2011.

### **Maintenance history**

The last inspection of the end fittings, before the accident on 31 May 2010, was a detailed visual inspection conducted as part of a '2C' check, in February 2009. The inspection found the fittings to be in a satisfactory condition.

The investigation team identified that the sealant applied externally to the seven attachment bolts appeared to have been replaced at some stage in the aircraft's life. Despite an extensive search of the current operator's electronic aircraft records, and the previous operator's paper records, the record of this work could not be found.

### **Discussion**

The outboard end fittings of the right wing gear support beam failed due to cracks, propagating from corrosion pits in the main bore of the fitting, reaching a critical length. The manufacturer had been aware of a similar issue on earlier production aircraft of the same type and had instigated design improvements which were incorporated into later aircraft, including B-HKH. These improvements included better corrosion protection in the form of plating to all parts, sealing and an increased interference fit of the bush within its bore to prevent rotation.

There is evidence to indicate that the main bush in both wing fittings had rotated and it is likely that this movement broke the fillet of sealing compound, which allowed moisture ingress into the joint, leading to the corrosion.

The manufacturer's current Service Bulletin (747-57A2331) details inspection procedures and either rework or replacement schemes to remedy and upgrade any deteriorated fittings that are identified.

### **Safety Actions**

Following this accident, the manufacturer issued a multi-operator message to inform operators of the event

and to recommend that they perform the inspections detailed in SB 747-57A2331. Using the results of these inspections the manufacturer will review the inspection thresholds and make adjustments if required.

The FAA has given contingent approval for the above SB and a Notice of Proposed Rulemaking (NPRM) to mandate the SB is expected to be issued shortly.