

Piper PA-28-180 Cherokee, G-BASJ

AAIB Bulletin No: 2/97 Ref: EW/G96/11/09 Category: 1.3

Aircraft Type and Registration:	Piper PA-28-180 Cherokee, G-BASJ
No & Type of Engines:	1 Lycoming O-360-A4A piston engine
Year of Manufacture:	1972
Date & Time (UTC):	23 November 1996 at 0930 hrs
Location:	Bristol Airport
Type of Flight:	Private
Persons on Board:	Crew - 1 - Passengers - 3
Injuries:	Crew - None - Passengers - None
Nature of Damage:	Fire damage to engine and cowlings
Commander's Licence:	Private Pilot's Licence
Commander's Age:	33 years
Commander's Flying Experience:	89 hours (of which 87 were on type) Last 90 days - 2 hours Last 28 days - None
Information Source:	Aircraft Accident Report Form submitted by the pilot

The aircraft had been left outside in freezing temperatures overnight and required de-icing before being boarded by the pilot and passengers. The engine was primed as usual for a cold start, but it did not start upon operating the starter motor. The pilot attributed this to a combination of the cold temperature and the battery, which he considered was delivering less than maximum power. Further attempts were made to start the engine, and included additional priming. However, it was apparent that the battery was becoming seriously depleted. When a final attempt resulted in a backfire from the engine, it was decided to summon help from the flying club. Following the backfire, a small amount of smoke was seen issuing from the engine bay, and so the electrical and fuel systems were selected off and the occupants then evacuated the aircraft.

After the evacuation, some smoke was still visible, and so the pilot recovered a fire extinguisher from the aircraft and discharged it into the engine bay. However this had little effect and a fire ensued. The Airport Emergency Services were called and they extinguished the fire, which was confined to the engine bay.

A subsequent examination of the aircraft revealed no obvious defect, such as a disconnected or broken fuel line, that could have accounted for the fire. The flying club concluded that the incident had occurred due to over-priming of the engine, causing excess fuel to collect in the induction system with subsequent ignition as a result of the backfire.