

# Piper PA-34-200-2 Seneca, G-BCDB

**AAIB Bulletin No: 9/97 Ref: EW/G97/05/15Category: 1.3**

<b>Aircraft Type and Registration:</b>	Piper PA-34-200-2 Seneca, G-BCDB
<b>No &amp; Type of Engines:</b>	2 Lycoming IO-360-C1E6 piston engines
<b>Year of Manufacture:</b>	1974
<b>Date &amp; Time (UTC):</b>	25 May 1997 at 1119 hrs
<b>Location:</b>	Bristol Airport
<b>Type of Flight:</b>	Private
<b>Persons on Board:</b>	Crew - 1 - Passengers - None
<b>Injuries:</b>	Crew - None - Passengers - N/A
<b>Nature of Damage:</b>	General damage to underside of fuselage; damage to propellers and possible engine shock load
<b>Commander's Licence:</b>	Private Pilot's Licence with IMC, Night and Instructor Ratings
<b>Commander's Age:</b>	70 years
<b>Commander's Flying Experience:</b>	1,359 hours (of which 15 were on type)  Last 90 days - 6 hours  Last 28 days - 3 hours
<b>Information Source:</b>	Aircraft Accident Report Form submitted by the pilot

The pilot was carrying out an ILS approach, in VMC, to Runway09 at Bristol Airport. The aircraft was vectored to the intermediate approach at 3,000 feet amsl; the pilot felt that he had been vectored close to the airfield and so he selected 25° rather than the usual 10° flap in order to facilitate a more rapid descent when he was turned onto final approach. During this descent, power was reduced and, as expected, the landing gear warning horn sounded.

The pilot reported that when the aircraft established on the localiser, it was only slightly below the glide slope. He was told to change frequency to 'Tower' but received no reply to his first call; the frequency was reselected and contact established. By this time the aircraft was significantly above the glide slope and so he reduced power to increase the rate of descent; the landing gear warning horn again sounded until the glide slope was regained some time later. The pilot was so preoccupied with regaining the glide slope that he omitted his final checks which he normally did at 1,000 feet.

The warning horn again sounded as he closed the throttles in the flare but he had become used to hearing it and by the time the significance occurred the aircraft had made contact with the runway.

The pilot, in a frank and comprehensive report, said that he had under 5 hours instrument flying on the Seneca. He trained at Bournemouth Airport and was used to being established on the localiser about 2 nm before intercepting the glide slope. The more hurried approach at Bristol coupled with the radio problem which led to the aircraft to be well above the glide slope, left him with little spare capacity to cope with the change to his normal routine.