

# **Socata TB10 Tobago, G-HALP, 23 November 1996**

**AAIB Bulletin No: 4/97 Ref: EW/G96/11/14 Category: 1.3**

## **INCIDENT**

<b>Aircraft Type and Registration:</b>	Socata TB10 Tobago, G-HALP
<b>No &amp; Type of Engines:</b>	1 Lycoming O-360-A1AD piston engine
<b>Year of Manufacture:</b>	1981
<b>Date &amp; Time (UTC):</b>	23 November 1996 at 1615 hrs
<b>Location:</b>	Barnet Golf Club, Nr Elstree, Hertfordshire
<b>Type of Flight:</b>	Private
<b>Persons on Board:</b>	Crew - 1 - Passengers - 1
<b>Injuries:</b>	Crew - None - Passengers - None
<b>Nature of Damage:</b>	Minor damage to left-hand wing from contact with a small tree during ground roll
<b>Commander's Licence:</b>	Private Pilot's Licence with Night Rating
<b>Commander's Age:</b>	53 years
<b>Commander's Flying Experience:</b>	2,385 hours (of which 2 were on type)
	Last 90 days - 35 hours
	Last 28 days - 10 hours
<b>Information Source:</b>	Aircraft Accident Report Form submitted by the pilot

The aircraft had been undergoing repairs for corrosion to the wings at a CAA approved maintenance organisation, following a five-year period during which the aircraft had flown for about 2 hours. The pilot reports that extensive pre-flight inspections had been performed, including the draining down and refilling of the fuel tanks and particular attention was paid to the alternator system, which had previously 'dropped off line' during one of two short flights from Elstree. The intention was to wait for a fine weather day to allow for a return cross-country flight to North Weald.

The pilot reports that the flight to North Weald, a distance of some 20 nm, was uneventful with the exception of the circuit breaker 'popping' for the 'Comm 2' radio: this radio remained inoperative and

the circuit breaker was not reset a second time. However, as the aircraft was departing from North Weald the primary radio failed and the alternator warning light indicated that the alternator was 'off line'. The pilot made several attempts to reset the alternator but these were unsuccessful and he suspected that there was a problem with the battery. He continued the climb but switched off electrical equipment, with the exception of the electric fuel pump, so as to conserve battery power. The pilot limited the climb to 1,400 feet QNH in order to remain below the Stansted CTA and then turned off the electric fuel pump.

About 7 nautical miles from the departure airfield the engine suddenly lost power without faltering or rough running, although the propeller continued to turn in fine pitch. The pilot reported that he immediately selected a field for an emergency landing, applied carburettor heat, selected the electric fuel pump ON and changed fuel tanks. The annunciator panel light for the fuel pump was flickering and a further attempt to bring the alternator back on line was successful; shortly afterwards the engine developed full power again, with the ammeter showing a healthy charge from the alternator. The pilot climbed and resumed the cruise at 2,000 feet QNH, now clear of the Stansted CTA.

The pilot established radio contact with Elstree, notifying the watch officer that he would need a priority landing due to the electrical fault and descended to 1,500 feet to keep sight of the emergency landing fields along the track. After a further 5 miles the problem recurred, with sudden power loss and heavy distortion, and then loss, of the radio. The electric fuel pump was still ON from the previous power loss and the pilot again applied carburettor heat. This time the pilot only had a short time to attempt the restart because of the necessity of finding a suitable landing site and the engine did not regain power. The lack of time and the radio problem limited the pilot to a brief emergency transmission: the aircraft call sign followed by "Emergency landing".

The pilot performed the close-down checks on the engine but judged none of the available fields to be suitable for a forced landing, due to trees, pylons or livestock. The one field which did appear favourable was too close and the pilot, with no flap available due to the lack of electrical power, could not establish a suitable rate of descent but he managed to land on a golf course, landing across a fairway to avoid trees and a pond. The pilot considered the landing reasonable with damage limited to the left-hand wing due to the wing striking a shrub and a marker post.

The account of the passenger, also the holder of a PPL, broadly confirms that of the pilot. She recalls that, as he was finishing his pre-flight checks, the pilot had asked her to check the fuel drains and that the fuel samples had been clear and consistent with 100LL AVGAS. She had not been requested to check the fuel levels in the tanks and did not do so as the fuel caps were locked. Her description of the flight was similar to that of the pilot. She had no ready explanation as to the cause of the engine's loss of power but commented that the symptoms would have been consistent with interruption of the fuel supply to the engine and also that, at the time of the accident, the temperature and dew point "were within a couple of degrees of each other".

The ground engineer from the maintenance organisation was present at the golf course on the following day to recover the aircraft. At this stage there were several gallons of fuel in the aircraft tanks and the engineer reports that the engine started easily for taxiing approximately one mile to an area of hardstanding where the aircraft could be dismantled. The fuel was drained before the wings were removed and the fuel did not show any signs of contamination.

The pilot comments that, in the near future, the aircraft will be reassembled and further tests conducted to determine the cause of the engine's loss of power.

