

# Agusta A109A II, G-TBGL

AAIB BulletinNo: 6/2000

Ref:EW/G99/11/01

Category:2.2

## INCIDENT

<b>Aircraft Type and Registration:</b>	Agusta A109A II, G-TBGL
<b>No &amp; Type of Engines:</b>	2 Allison 250-C20B turboshaft engines
<b>Year of Manufacture:</b>	1988
<b>Date &amp; Time (UTC):</b>	3 November 1999 at 0945 hrs
<b>Location:</b>	Field near A4133, near Droitwich
<b>Type of Flight:</b>	Private
<b>Persons on Board:</b>	Crew 1 - Passengers - 1
<b>Injuries:</b>	Crew None - Passengers - None
<b>Nature of Damage:</b>	Autopilot Control Unit wiring loom chafed
<b>Commander's Licence:</b>	Private Pilots Licence (helicopters)
<b>Commander's Age:</b>	52 years
<b>Commander's Flying Experience:</b>	1,020 hours (of which 125 were on type) Last 90 days 49 hours  Last 28 days 18 hours

**Information Source:** Aircraft Accident Report Form submitted by the pilot

On a VFR flight from a private location near Lyneham to HalfpennyGreen, when passing to the west of Gloucestershire Airfield, the pilot noticed that the Horizontal Situation Indicator (HSI) was indicating a heading failure. The autopilot was not in use at this stage and the pilot was therefore unconcerned. In the area of Malvern, the pilot engaged the autopilot and Heading Hold, however the helicopter would not maintain heading and so the autopilot was disengaged and the pilot considered that the HSI was unserviceable. Approaching Droitwich the Stability Augmentation System (SAS) 1 warning light illuminated and the SAS auto-disconnected. Within the next minute the Inverter 1 warning light illuminated indicating failure of the No 1 inverter. The pilot reduced speed and as he did so Inverter 2 warning illuminated. The pilot could then smell burning and so informed ATC at Halfpenny Green that he was making a precautionary landing. During the descent the passenger noticed smoke appearing from below the instrument panel. The pilot switched the electrics master and battery switches to OFF and landed the helicopter in a field of stubble to the west of Droitwich. The smoke dispersed and the smell of burning reduced. The pilot shutdown the engine and informed Halfpenny Green that they had landed without damage or injury.

The helicopter was later flown VFR with the autopilot and SAS systems disabled to the maintainers for investigation and repair. Investigation identified chafing of the insulation on some of the conductors in a loom connecting to the Autopilot Control Unit, installed on the instrument panel. The loom had been in contact with a duct behind the instrument panel. The wiring was repaired and rerouted away from the ducting and a power supply rectifier was replaced, after which the systems tested satisfactorily.

