

Europa, G-BWYD, 30 December 1997

AAIB Bulletin No: 4/98 Ref: EW/G97/12/17 Category: 1.3

Aircraft Type and Registration:	Europa, G-BWYD
No & Type of Engines:	1 Rotax 912-UL piston engine
Year of Manufacture:	1997
Date & Time (UTC):	30 December 1997 at 1350 hrs
Location:	Kemble Airfield, Gloucestershire
Type of Flight:	Private (Training)
Persons on Board:	Crew -2 - Passengers - None
Injuries:	Crew - None - Passengers - N/A
Nature of Damage:	Minor damage to exhaust tail pipe, distortion of landing gear operating lever with elongation of attachment bolt holes, one propeller blade sheared off at hub
Commander's Licence:	Basic Commercial Pilot's Licence with Instructor Rating
Commander's Age:	70 years
Commander's Flying Experience:	12,267 hours (of which 73 were on type) Last 90 days - 63 hours Last 28 days - 24 hours
Information Source:	Aircraft Accident Report Form submitted by the pilot

The co-owner of the aircraft was receiving some re-familiarisation training on the aircraft, which had recently been repaired following a landing accident at Biggin Hill in August 1997. The sortie was to include circuits flown from grass Runway 22, the wind being 220°, 12 to 15 kt. During the downwind checks on the first circuit, the pilot selected the landing gear DOWN and the instructor confirmed the selection by observing illumination of the green gear down indication light on the instrument panel and checking engagement of the associated safety latch on the gear selector lever. The subsequent landing touchdown was normal, although there was an initial 'skip' caused by an undulation in the grass surface. Towards the end of the landing roll the instructor noticed the right wing dropping, and suspected a failure of the right outrigger. However, before he could react there was a loud bang in the cockpit and the aircraft sank onto its underside. Following a short groundslide, during which one of the propeller blades broke off at the hub, the aircraft came to

a halt and the pilot selected all switches to OFF. It was then noticed that the landing gear selector lever was in the forward, ie UP position, although not in its gate.

Following the incident, the aircraft was raised by a mobile crane and the landing gear was lowered. The aircraft was then pushed off the grass onto a taxiway prior to recovery to a hangar. Once on the tarmac, the cockpit was occupied in order that the brakes could be applied as the aircraft was manoeuvred down a slope towards the hangar. However, after a short distance, the landing gear again collapsed, this time with the selector lever remaining in the DOWN position.

On this type of aircraft, the landing gear consists of a single retractable mainwheel, in addition to a tailwheel and two outriggerwheels under the outboard sections of the wings. The retraction lever is attached directly to the gear operating linkage, which incorporates an over-centre mechanism. The flaps and outriggerwheels are attached to the same linkage. The function of the safety latch is to prevent inadvertent gear retraction whilst on the ground. The latch is attached to the retraction lever and is designed to rotate under its own weight into the guide slot. A positive action is required to move the latch out of the slot, which then allows the retraction lever to be moved out of the gate. The gear operating mechanism, together with details of the safety latch, are shown in the attached diagram. (This aircraft had been modified so that a green light illuminated when the gear was selected DOWN, however the switch that operated the light was mounted on the mainwheel mechanism, as opposed to the safety latch, and thus was not capable of providing confirmation that the gear was 'locked').

Following consultation with the repair organisation, it was considered that a possible explanation was that the safety latch may not have been fully engaged prior to the landing, as the retraction lever was found out of the DOWN gate after the incident. (However the instructor recalled that the position of the safety latch prior to the landing appeared no different to that on previous occasions). In the event of the aircraft landing (or taxiing) on undulating surfaces, flexing of the landing gear system induces a tendency for the linkage to rebound from its over-centre stop. This can in turn move the retraction lever, unless the safety latch is in position. It was thought that three previous incidents involving landing gear collapse on this aircraft type had been caused by incomplete engagement of the safety latch. It was considered unlikely that the gear could collapse with the latch correctly engaged without causing substantial damage to the retraction lever gate structure.

The landing gear retraction lever was later submitted to the AAIB for examination and it was observed that elongation had occurred in two of the three bolt holes that were used in attaching the lever to the main gear mechanism (see diagram). The elongation was of the order of 1.5 mm and although some of this had occurred as a result of the incident, the presence of file marks in the bores indicated that the holes had been 'opened out' at some earlier stage. It is possible that this had been done in order to facilitate fitting of the lever. The fact that one hole was round suggested that the lever had been assembled to the landing gear linkage by means of a bolt through this hole, with alignment of the other two holes being achieved by filing their bores. The result was a poor joint which had relied on flank friction to lock the parts together, as evidenced by indentations surrounding the holes where the associated washers had dug into the side of the lever. The indentations took the form of deep smears around the elongated holes as the joint had slackened in service, and had pivoted about the non-elongated hole. The amount of free play arising from the elongated holes, although small, could nevertheless have allowed the main gear mechanism some additional movement, under the influence of ground undulations, away from its overcentre stop.

It is possible that some distortion was caused to the landing gear linkage during this latest incident so that when the aircraft was subsequently raised, and the gear lowered, the mechanism did not

achieve its over-centre condition. Thus when the aircraft was placed on the ground again, the gear may have initially been prevented from collapsing only by the safety latch holding the gear selector lever in its DOWN gate. The subsequent gear collapse may therefore have been due to the additional loads imposed by the weight of the occupant inducing distortion of the gear selector lever whilst it was retained in its DOWN gate by the safety latch.