

CEA DR360, G-AZIJ

AAIB Bulletin No: 10/97 Ref: EW/G97/05/11 Category: 1.3

Aircraft Type and Registration:	CEA DR360, G-AZIJ
No & Type of Engines:	1 Lycoming O-320-D2A piston engine
Year of Manufacture:	1971
Date & Time (UTC):	9 May 1997 at 1445 hrs
Location:	Near Guernsey Airport, Channel Islands
Type of Flight:	Private
Persons on Board:	Crew - 1 - Passengers - 1
Injuries:	Crew - None - Passengers - None
Nature of Damage:	Fabric detached from underside of right tailplane
Commander's Licence:	Airline Transport Pilot's Licence with FI Rating
Commander's Age:	50 years
Commander's Flying Experience:	5,500 hours (of which 250 were on type) Last 90 days - 100 hours Last 28 days - 30 hours
Information Source:	Aircraft Accident Report Form submitted by the pilot and Inspection by the AAIB

The aircraft was on a flight from Quimper to Guernsey at 1,000 feet in good flight conditions with no turbulence and about 10 miles from Guernsey when the occupants heard a "bang" from the rear of the aircraft. The aircraft immediately yawed to the right and the right wing dropped. The pilot regained control but could feel vibration through the control column. He slowed the aircraft to 80 kt and advised Guernsey ATC that he had a potential control problem. The occupants could see no damage on the wing but could not see the rear of the aircraft. A successful landing was made after gentle manoeuvring an uneventful approach.

When the aircraft was examined after landing it was found that almost all of the fabric covering the underside of the right tailplane was missing. The tailplane was removed and sent to a repair agency on mainland UK where it was examined by the AAIB, the remaining covering being removed for closer examination.

The front (spanwise) edge of the missing section had formed abutt-joint with the edge of the fabric which remained. This remaining fabric covered the top surface and was wrapped around the leading edge and along the underside to a distance of 5" and around the trailing edge, overlapping the missing underside covering where it was glued to the trailing edge structure. The departing fabric had ripped rearwards leaving remnants of the underside covering at the root and tip. The butt-joint had been very close fitting. The edge of the remaining fabric was a cut edge (ie not the manufactured edge at the side of a roll) as could be seen from the free edges of the filaments and the occasional small step in the cutting line. At either end of the butt-joint, where the fabric wrapped around the tip and the root, the missing section had been slightly overlapped by the remaining fabric. No reinforcing tape had been used to cover the butt-joint or any of the other fabric joints. There was no rib-stitching or tape reinforcement along the rib glue lines.

The stabilator had been recovered in June 1994 with Ceconite 101. All of the contact surfaces had been coated with three coats of 20% thinned Super Seam adhesive. In the technique described by the fitter, while the final coat was still wet or tacky, the fabric would have been applied and rubbed with a finger or cloth wetted with thinned (30 to 35%) Super Seam until the "wetted" appearance of the fabric showed that adhesive had penetrated and filled the weave. The fabric was primed with three coats of Rand-O-Proof the first of which was mixed with 20% thinned Super Seam and a polyurethane paint was used for the final colour coats (white). After a short period in service defects in the paintwork became evident and it was agreed with the owner that this would be rectified at the annual inspection in February 1996. When he started this work the fitter found that he was able to prise the paint off the surface and all of it was removed in this way. He cleaned the surface with a thinner soaked cloth and repainted with a polyurethane paint.

The factors which were considered relevant to the detachment of the under side fabric were the presence of the butt-joint without overlap or tape reinforcement on the leading edge underside in the area of maximum aerodynamic suction and also the integrity of the adhesion of the fabric to the structure. Procedures for covering Robin aircraft with polyester fabrics are described in Service Bulletin (SB) No 43 Revision 1 and a manufacturer's procedures manual is available for the Ceconite material.

Avions Robin SB 43 describes the rib-stitching of certain areas of the wing but states that, "There is no stringing (sic) on control surfaces." It does not prescribe fabric layout but advises a "fabric-fabric overlap of at least 70 mm (2.75") at the leading and trailing edges". The glueing process is given as a "Procedure used during manufacture" for use "on all unvarnished woods". The process is simply described as 2 coats of 20% thinned adhesive on the wood followed by 2 coats of 35% thinned adhesive on top of the attached fabric.

Ceconite 101 is the heavier of two grades described in the procedure manual, being the equivalent in weight of cotton TSO C-15 (approximately 4 oz per sq yd) but stronger and more durable. (The weave of the fabric is composed of interwoven bunches of polyester filaments; the filaments are not twisted into threads.) The glueing method is described in the procedure manual as follows:-

"For maximum strength, care must be exercised to obtain good bonds. First, apply 'Super Seam Cement' liberally to both surfaces. (Sufficient 'Super seam Cement' must be used to penetrate and completely encase each fibre.) Then, using your hands, join the surfaces as the cement becomes tacky. Finally, go over the outside of the joint using thinned cement. - - -"

The objective is to achieve good adhesion of the cement on to the structure with a thick coating which can be brought to penetrate the weave from below and encapsulate all the fibres. This

process is assisted by application of thinned adhesive from the outside surface of the fabric. If adhesive is applied predominantly from the outside it may penetrate the fabric but not make a good bond with the wood or adhesive surface below. A distinct change in the translucence of the fabric shows when the adhesive has penetrated the weave.

On G-AZIJ the wooden surfaces left by the lost fabric were slightly glazed, presumably by the remaining adhesive. There was no sign of any of the wood itself having been lifted or removed as the fabric detached. The remaining fabric was removed to be examined for indications of the quality of the bond and the tailplane was released for repair.

The fitter prepared a sample piece using his normal technique. This supported a 13.5 lbs load on the 1-foot square sample without failing. A piece of fabric was then torn off and examined microscopically together with a sample from G-AZIJ where the fabric had been stuck to a rib and a third sample which was obtained from another Robin aircraft. In all three cases the separation of the fabric from the structure occurred at the interface between the fabric and the glue. No glue was left on the weave and a clear imprint of the weave was left in the glue surface on the wood. This appears to be a logical place for the separation to occur as the glue does not adhere to the filaments but merely encapsulates them and its load bearing area here is at a minimum; reduced to the aggregate area of the individual fingers of glue which penetrate the weave. It is often said that it is an indication of a good bond if wood is lifted with the fabric when it is peeled. There may be some variation of penetration of the glue between the filaments as distinct from mere penetration of the weave which would affect the strength of the adhesion of the fabric with the best adhesion producing this effect. A number of other (crashed) aircraft were examined but none showed any lifting of the wood with the fabric except where the wood had been damaged. As a result of this investigation, therefore, and given the information available, it could not be shown that the adhesion of the fabric was a factor in the detachment of the stabilator fabric additional to the exposed butt joint.

The fitter identified the work as his own but was at a loss to understand or explain why he had introduced a butt-joint into the covering at that location and without any covering. (Good practice would have required a covering over the joint that wrapped around the leading edge to terminate on the top surface.)

The covering and painting of the stabilator in 1994 was not recorded in the aircraft log book. However, the logbook entry describing the other work carried out at that time did refer to worksheets held by the maintenance company and those contained a record of the recovering and repainting work. The Licensed Aircraft Engineer (LAE) who had signed the worksheets did not hold the rating (Category 'B' Aeroplanes, Para. 5.1 of BCAR) which qualified him to certify the fabric covering of a complete aerofoil. The log book entry, which did not specifically list this work, had been signed by an LAE who was so qualified. The repainting of the stabilator in 1996 was recorded on a "snag sheet" with a fitter's signature showing that it had been accomplished but without any certification that it was fit for release to service. The corresponding log book entry did not contain any reference to the repainting.