

# Kolb Twinstar MK3 (Modified), G-MYNY, 21 July 1996

## AAIB Bulletin No: 10/96 Ref: EW/G96/07/21 Category: 1.3

<b>Aircraft Type and Registration:</b>	Kolb Twinstar MK3 (Modified), G-MYNY
<b>No &amp; Type of Engines:</b>	1 Rotax 582 piston engine
<b>Year of Manufacture:</b>	1994
<b>Date &amp; Time (UTC):</b>	21 July 1996 at 1800 hrs
<b>Location:</b>	Wolds Farm, Wolds Lane, Wolvey, Leicestershire
<b>Type of Flight:</b>	Private
<b>Persons on Board:</b>	Crew - 1 Passengers - 1
<b>Injuries:</b>	Crew - Minor Passengers - Minor
<b>Nature of Damage:</b>	Substantial damage to forward part of pod, landing gear collapsed
<b>Commander's Licence:</b>	Private Pilot's Licence
<b>Commander's Age:</b>	44 years
<b>Commander's Flying Experience:</b>	236 hours (of which 28 were on type) Last 90 days - 26 hours Last 28 days - 8 hours
<b>Information Source:</b>	Aircraft Accident Report Form submitted by the pilot and telephone enquiries

The aircraft had just taken off from a grass airfield and climbed to a height of about 800 feet agl when the engine suddenly stopped. The pilot selected a field for a forced landing straight ahead and made a successful touch down, at about 50 mph airspeed, in the intended field. During the landing run, the aircraft crossed a tractor track; this had a high ramp, formed by tractor wheels, contact with which threw the aircraft back into the air and slewed it some 45° to the right. The aircraft fell heavily back onto the ground and subsequently slid into a hedge where it struck a concealed tree stump. The occupants were able to get out of the wreckage unaided.

Immediately after the accident, the pilot checked that the fuel was selected 'on' and that fuel was present in the carburettors. He also checked that the electrical system was switched on and functioning. Later examination of the engine revealed that the rear cylinder 'big end' had seized.

Several similar seizures of Rotax 582 engines have been reported and in an earlier AAIB Bulletin (12/95, page 55) a report on an engine seizure on a Renegade Spirit drew attention to this problem. The text and figure used are repeated in an updated form below.

'Although no statistics appear to be available, the Popular Flying Association advise that there is a history of big-end failures on Rotax 582 engines due to worn bearings. This is particularly the case for engines installed in heavier aeroplanes and when used in the training role when extended running at high power is required. The largest service centre for Rotax engines in the UK, to which the engine was sent for examination, has devised an instrument for testing the combined big/little-end bearing clearances which they say has proved extremely effective in predicting failures before they occur.

Called the 'Cyclone Conrod Bearing Clearance Tester' the device is illustrated in Figure 1. Essentially it is a dial gauge mounted on an extension tube which screws into the spark-plug holes and bears on the piston crown at top dead centre. A syringe is used to suck/blow the piston up and down and the difference in gauge readings is converted into combined bearing clearance. It is recommended that this check be performed every 12.5 flight hours when the plugs should be removed for inspection in accordance with the Rotax service schedule. Maximum wear figures are given with the instrument but records should also be kept so that any trend can be detected in advance. It is understood that the Popular Flying Association agree that this device has been effective in preventing failures of this nature and published an article entitled 'KNOW YOUR BIG END WEAR' in the December 95/January 96 edition of their magazine *Popular Flying*.'




Figure 1 The Cyclone Conrod Bearing Clearance Testerfor Rotax Engines