

PA-28-161, G-BSPZ

AAIB Bulletin No: 1/97 Ref: EW/C96/10/3 Category: 1.3

Aircraft Type and Registration:	PA-28-161, G-BSPZ
No & Type of Engines:	1 Lycoming O-320-D3G piston engine
Year of Manufacture:	1985
Date & Time (UTC):	16 October 1996; at approximately 1305 hrs
Location:	18 nm North West of Perth, Scotland
Type of Flight:	Private
Persons on Board:	Crew - 1 - Passengers - 1
Injuries:	Crew - Fatal - Passengers - Fatal
Nature of Damage:	Aircraft destroyed
Commander's Licence:	Private Pilot's Licence
Commander's Age:	68 years
Commander's Flying Experience:	473 hours (of which 95 were on type) Last 90 days - 12 hours Last 28 days - 3 hours
Information Source:	AAIB Field Investigation

History of the flight

The pilot had planned to fly from Edinburgh Airfield to Perth Aerodrome with his wife as a passenger. The weather forecast was for isolated rain showers with associated hill fog, with good visibility away from the showers and a moderate southerly wind. At about 1200 hrs, prior to departure, the pilot made a telephone call to Perth to confirm the weather details and was told that there was light rain with a cloud base of 2,000 feet, the visibility was 30 km and the surface wind was estimated at 160°/10 kt. Before take-off the pilot copied the latest weather at Edinburgh which was reported as: recent rain showers with a few clouds at 1,400 feet, scattered cloud at 1,800 feet and broken cloud at 4,500 feet, the surface wind was 140°/15 kt with the direction variable between 100° and 190° and with gusts to 25 kt, the QNH was 993 mb

The pilot was cleared for a 'Kelty' departure and took off at 1242 hrs from Runway 08 at Edinburgh. The Kelty departure is the normal visual routing for aircraft leaving Edinburgh when clearing to the north. At 1248 hrs the pilot reported overhead Kelty, he was then instructed to call when leaving the

control frequency. At 1250 hrs he told Edinburgh ATC that he was leaving the frequency and would now call Perth. He told Perth that he was at Kinross (a prominent feature 15 nm south of Perth) at 2,000 feet, estimated arriving at Perth in 15 mins and requested an update on the weather and the runway in use. He was told that the weather conditions were as briefed at 1200 hrs and that Runway 16 was in use: the pilot acknowledged this message.

At about 1320 hrs the airfield manager at Perth attempted to call G-BSPZ by radio. He also contacted the local ATC agencies and airfields, but discovered that no one had spoken to that aircraft. He then informed Edinburgh ATC that the aircraft was overdue. The Rescue Co-ordination Centre at RAF Kinloss initiated overdue action at 1339 hrs and a search and rescue operation commenced. After an extensive search of the expected route from Kinross to Perth and the surrounding area, the two rescue helicopters were sent to an area 15 nm to the northwest of Perth following an analysis of radar returns that might have been from the missing aircraft; the wreckage was found in that area, in remote and hilly country, at 1724 hrs.

Analysis of recorded secondary radar data from the radar head at Lowther Hill, in Dumfries and Galloway, confirmed that initially the aircraft had followed a ground track entirely consistent with the Keltie departure from Edinburgh Airport and then a direct route to Perth Aerodrome. However, at 1253 hrs, when 8 nm from Perth on a bearing of 200° and at 2,200 feet amsl, the aircraft turned left onto a track of 308°. This track was maintained until 1257 hrs when the radar return faded from radar cover. From Mode C information the aircraft appears to have maintained an altitude of between 2,200 feet and 2,400 feet amsl over ground that is generally 300 feet to 400 feet amsl and in an area that was reported to be clear of significant cloud. No further radar returns from this aircraft were then displayed until 1302 hrs when a single return appeared as a direct continuation of the previous track and having apparently maintained a constant groundspeed. It was then at an altitude of 2500 feet amsl. The position of this single, final return was within 2 nm of the crash site which was on a further continuation of the aircraft's track.

The aircraft had struck the side of a hill at an altitude of 2300 feet; much of the surrounding high ground was above 2,000 feet and a spot height of 2,641 feet was less than a quarter of a mile from the wreckage. The immediate area had been in cloud for most of the day and throughout the afternoon there had been prolonged heavy rain with the cloud base approximately 500 feet below the level of the crash site.

Other pilots who were in the area at about the same time reported the cloud base between Edinburgh and Perth as 2,200 feet with excellent visibility such that Keltie was clearly visible whilst climbing out from Perth. They also commented on the heavy showers visible over the hills to the north west (the area of the crash site) and the Ochill Hills (to the west of Kinross).

Pilot Experience

The pilot had obtained his Private Pilot's Licence in 1982 whilst a member of the Dundee Fying Club. His subsequent flying was carried out in light, single-engine aircraft, mainly within Scotland. In February 1996, after completing an approved course of instrument flying, he gained a CAA rating which provided him with a limited ability to fly on instruments in poor weather (IMC Rating). He had flown between Edinburgh and Perth many times, including 15 times in the previous 3 months, and he reportedly knew the local area very well.

Pathology

Post mortem examination of the pilot did not reveal any medical condition which was likely to have contributed to the accident.

Impact Parameters

The aircraft had crashed, at an altitude of 2,300 feet, into rising ground that was covered with heather and strewn with rocks at position 56° 31'N, 003° 52.5'W, approximately 1 mile SW of Lock Freuchie. At the point of impact there was an upslope of some 15°, with no cross-slope, and analysis of the impact ground marks suggested that the aircraft had been in controlled flight, with the wings level and the nose in a slightly high attitude, immediately prior to striking the ground. There was clear evidence from damage sustained by the fixed pitch propeller that it had been rotating under a reasonably high power level and analysis of several propeller slash marks in the ground at the point of impact, suggested that the aircraft's ground speed had been in the region of 135 kt. If the likely tailwind is taken into account then this speed equates to an airspeed of approximately 110 kts. Just prior to striking the ground the aircraft had been on a track of 310°M, a track that would have taken the aircraft over a ridge some half mile before the point of impact, and whose elevation was the same as that of the accident site.

Wreckage Examination

Examination of the wreckage at the site, and later after its recovery to the AAIB at Farnborough, indicated that the aircraft had been complete and intact prior to the accident, and was configured with the flaps fully retracted and with both the cabin and baggage doors closed. Albeit shattered, the windscreens were recovered and showed no evidence of impact with any bird. The collision with the rising ground had torn away the landing gear, the underside of the fuselage and cabin floor back to a position just forward of the tailplane, and ruptured both wing fuel tanks. There was evidence of damage to surface vegetation from fuel splashing along the wreckage trail but there had been no fire. Refuelling records for the aircraft showed that it had taken on 81 litres of AVGAS100L two days before the accident, resulting in full tanks (giving approximately 4 hours duration) immediately following which it made one flight of 40 minutes duration. The aircraft crashed on its next flight, two days later. Subsequent to the initial impact, the aircraft tumbled over the ground for 350 feet, shedding various airframe and engine components, before coming to rest on fairly level ground, with the airframe broken into several large elements all loosely attached by sections of skin and wires. Both front seats had broken free from the cabin floor, but remained within the fuselage, and the engine, firewall and instrument panel had stayed together as a unit. Owing to the absence of a post-impact fire, it was possible to examine the aircraft's engine, instrumentation and flight controls, fuel and electrical systems. This examination did not reveal any pre-accident defects that might have relevance to this accident. It was noted, however, that the carburettor air heat control was set at 'Cold' and the pitot heat selector switch was 'Off', although a functional check of the pitot heater showed it to have been serviceable.

All of the radio/navigation equipment and the flight instruments were removed and taken to an overhaul agency for inspection and, where possible, test. Here it was established that the artificial horizon, direction indicator, altimeter, airspeed indicator and vertical speed indicator were all serviceable prior to the accident, all of these instruments performing within, or very close to, the normal requirements for accuracy. The aircraft was fitted with dual VHF radio/VOR units, and single ADF, DME and transponder units. All were found selected to ON. These were functioning, together with their indicator units where appropriate, with no significant defects being found. All these units had incandescent type display panels and required electrical power to produce an indication of the selected frequency. These frequencies are retained in a memory when the unit is

unpowered and thus, after loss of electrical power during the impact sequence, any rotation of these selector knobs on these units should not have changed the last selected frequency. The last selections determined were as follows:-

Active, MHz Standby, MHz

Radio 1 119.8 Perth TWR 121.2 Edinburgh APP

Radio 2 132.075 Edinburgh ATIS 120.6 Cumbernauld TWR

Nav 1 110.4 Perth VOR (OBS set 035°) 108.9 Edinburgh ILS

Nav 2 112.5 St Abbs Head VOR 110.4 Perth VOR

(OBS set 310°)

DME 117.9 Mayfield

ADF 341 KHz Edinburgh - EDN 368 KHz Edinburgh - UW

The transponder was selected to code 7000, with mode C selected, and radio unit No 1 was the active unit. The 310° selected radial from the St Abbs Head VOR passes very close to the site of the accident, and also closely paralleled the aircraft's radar track from 8 nm south of Perth towards to point of impact.

Aircraft Documentation

The aircraft was registered in the Transport Category (Passenger) and was being flown to Perth for maintenance, specifically for a 100 hour/62 day check, in accordance with the CAA agreed manufacturer's maintenance schedule. The aircraft's documentation was examined and found to be in order with the following minor exception that the previous maintenance check had been carried out 64 days prior to the date of the accident. No evidence, however, was found to suggest that this two day exceedance of the calendar maintenance period was a factor in the accident, further more the aircraft had not flown on the day preceding the accident flight. The aircraft's Certificate of Airworthiness was valid, and due for renewal by 25 October 1996.