

Robinson R22 Beta, G-BOEY

AAIB Bulletin No: 9/97 Ref: EW/C97/1/2 Category: 2.3

Aircraft Type and Registration:	Robinson R22 Beta, G-BOEY
No & Type of Engines:	1 Lycoming O-320-B2C piston engine
Year of Manufacture:	1988
Date & Time (UTC):	16 January 1997 at 1806 hrs
Location:	Redhill Aerodrome, Surrey
Type of Flight:	Training
Persons on Board:	Crew - 1 - Passengers - None
Injuries:	Crew - 1 fatal - Passengers - N/A
Nature of Damage:	Aircraft destroyed
Commander's Licence:	Student pilot
Commander's Age:	29 years
Commander's Flying Experience:	130 hours (of which 118 were on type) Last 90 days - 46 hours Last 28 days - 17 hours
Information Source:	AAIB Field Investigation

History of flight

The student pilot, a Nigerian national, was undergoing the nightflying phase of a formal course for the award of a United Kingdom Commercial Pilot's Licence (Helicopter), (CPL(H)). He had been briefed for a solo circuit detail. The surface wind was calm, the visibility was 4,000 metres in haze, the temperature was +2°C and the QFE was 1006 mb. An aftercast gave the dew point as +2°C.

Shortly before 1800 hrs, the pilot took over the aircraft on a 'rotors running change' and called for permission to hover taxi to the holding point of Runway 08. At 1804:30 hrs, he was given clearance to line up; permission to take off was given about one minute later. The Duty Instructor reported that the helicopter carried out a 'normal night towering take off' to about 75 feetagl; his attention was then drawn away from 'EY'.

The evidence of two witnesses, who were just to the north of the take-off flight path, indicated that the helicopter was only about 100 feet agl as it approached the M23 motorway; it should have been at least 400 feet agl at this point. It was in a level attitude and appeared to be flying normally, in an easterly direction. As it crossed the motorway, it turned right and began to descend. It then pitched steeply nose down and they heard the sound of an impact shortly afterwards. One of the witnesses noted a regular and, to her, unusual sound from the helicopter which continued to the point of impact; another witness also reported hearing a similar unusual sound.

Another witness, who was travelling south on the motorway, saw a helicopter pass from right to left across the path of the car in which he was travelling. He was mainly aware of the white and red lights but was able to say that it appeared to be flying horizontally. Once it had crossed the motorway, it started a manoeuvre which looked like a turn to the right, however, it immediately pitched forward, 'cockpit down and tail in the air', and then disappeared from view.

Radar data

Three primary returns from the Gatwick Watchman radar, were recorded in the area of the accident; the first at 1806:16 hrs and the last at 1806:24 hrs. From these the track of the helicopter was estimated to be about 090° and the ground speed about 51 kt. The minimum height at which the Gatwick Watchman will 'see' an aircraft in this area is about 100 feet agl; the returns were all from the area where the witnesses saw the helicopter at a height which was visually estimated to be about 100 feet agl.

Examination of the wreckage

The helicopter had struck the ground in a level field immediately to the east of the M23 Motorway whilst travelling in a direction of about 130° magnetic; the ground was part frozen and fairly hard. At impact, the aircraft had been steeply nose down and the forward ends of both skids had broken off and remained embedded at the point of impact. The angles of entry and remainder of the skid ends indicated that the aircraft had struck the ground about 25° nose down, with a roll attitude about 20° to the right and slightly yawed to the right. As a result of the impact, it had yawed further to the right and rapidly pitched further nose down. The forward part of the cabin was shattered completely at initial impact and the pilot was thrown out. Apart from the fragments of the cabin, the only significant component which had become detached and remained close to the initial point of impact was the outer two feet of one main rotor blade.

Each of the main rotor blades had struck the ground to the right of the aircraft, the two strikes almost overlaying each other. Their position, relative to the first mark of impact of the rotor hub, indicated that they had occurred before the rotor head had struck the ground. These two strikes were the only evidence of main rotor ground strikes.

After initial impact, the ground marks indicated that the aircraft had then tumbled and rolled across the field for about 15 metres before coming to rest in a hedge and ditch which bounded the field. There was some smell of fuel at the accident site shortly after it had occurred, but the fuel tank had been split open and very little fuel remained in it. There was no evidence of any pre or post impact fire.

Examination of the wreckage on site revealed that both the main rotor blades had bent upwards over the length between $\frac{1}{3}$ and $\frac{1}{2}$ span, with 'crippling' of their upper surfaces. Both blades were also slightly bowed backwards, from just outboard of the root to within 3 feet of the tip, with crippling of

the trailing edge. Whilst one blade had remained intact, the other had bent 90° downwards just outboard of the root end, with a failure of the upper skin at this position, and the outboard two feet of the blade had detached in a 'tip aft and trailing edge down' direction relative to the inboard portion of the blade. The overall damage to the main rotor was consistent with some rotation at impact but without significant energy.

Although the tail boom had been broken into three parts, the empennage and tail rotor were undamaged. Examination of the failures in the tail rotor drive shaft showed them all to be the result of bending, with only slight evidence of rotation of the shaft during the failure process. The cabin section had been completely crushed afterwards and the engine had thrown forward, distorting its mountings.

The aircraft was transported to the AAIB at Farnborough for more detailed examination.

Detailed examination

Examination of the flying controls revealed no evidence of any pre-impact disconnection or other failure. Evidence of their positions at the time of impact was consistent with the collective lever having been fully up and the cyclic control fully aft. Evidence of contact caused by impact crushing indicated that the throttle control had been at, or very close to, the fully open position at the moment of impact. The carburettor heat control was found extended to about 1/4 of its travel from the 'cold' setting.

Examination of the drive train did not reveal any evidence of pre-impact failure or restriction. There was, however, little evidence of persistent rotation of the drive train as the aircraft's structure had distorted at impact; this lack of evidence was particularly apparent where the flanges of the drive shaft flexible couplings had become trapped in the distorted structure. Similarly there was only slight abrasion, indicative of rotation, on the engine cooling fan duct and the fan itself bore very little evidence of post impact rotation on its vanes. The freewheel mechanism was still functioning correctly and the main drive belts were in good condition. Comparison of the condition of the driven surfaces of the belts with other used belts showed that there was no significant evidence of slip against the pulleys. Because the clutch mounting had been severely distorted and the electric actuating mechanism disrupted, it was not possible to establish the belt tension which had been applied by the clutch.

The fuel supply and breather systems were examined and found to be free of pre-impact defects; the fuel selector was found in the 'on' position.

The engine induction and exhaust systems had been severely damaged in the impact and the carburettor broken from the manifold through the butterfly spindle bearings. There was no damage to give conclusive evidence of butterfly position at impact. The carburettor intake temperature sensing system had been severely disrupted and its pre impact condition could not be established. The magnetos, although damaged, had not shifted as a result of the impact and both were capable of generating energetic sparks at a relatively low speed.

During strip examination of the engine it was noted that two of the cylinders (Nos 2 & 3) had reduced compression and a third (No 4) had virtually no compression. After the cylinders had been removed from the crankcase, it could be seen that the combustion spaces all had encrustation consistent with prolonged lean mixture running. It was also noted that the piston crowns had the

appearance of having been operating at higher temperatures than is usual in this type of engine, particularly in the areas which came closest to the valve ports.

Leak testing of the combustion spaces indicated that all three of the cylinders with low compression had poor sealing of the inlet valves. After removal of the valves, inspection showed that the No 4 inlet valve seat, uniquely, had a single piece of foreign matter adhered to it and the general condition of that seat was more degraded than that of the other inlet valves. It was also observed that the deposits on the wall of the inlet tract to the No 4 cylinder appeared qualitatively different from the deposits of the other three cylinders, as did the deposit adhering to the back of its inlet valve head. This latter deposit appeared very brittle and a sizeable piece of it, from close to the stem, had detached. The No 4 cylinder and inlet valve were sent for physical and chemical analysis of these deposits together with those from No 3, they being considered a representative example of the remainder.

The foreign matter on the No 4 valve seat was analysed and compared with a sample of accident site mud taken from the base of the engine sump where the carburettor had broken off. This showed them to be of very similar composition and indicated that the engine was still turning sufficiently at impact for mud to be drawn up the inlet tract.

The deposits from the inlet tract walls and the backs of the valve heads from the Nos 3 & 4 cylinders were subjected to physical and chemical analysis. This showed that the deposit on the back of the No 4 valve head could be replicated in consistency and composition by heating some of the deposit from the No 3 valve head. The deposits from the two inlet tracts were found to be chemically similar and softened at the same temperature when heated; the deposit from the No 3 tract, however, gave off considerably more sublimate. This indicated that the No 3 inlet tract had probably been operating at a significantly lower temperature.

Pilot's flying experience

The course allowed for up to 25 hours fixed wing flying over a 5 week period, the remaining hours required to achieve the minimum 150 hours for the CPL(H) being flown in the R22. The student pilot started flying the Slingsby T67 on 10 April 1996 and finished on 17 May 1996 when he had a total of 12 hours.

He started helicopter flying on 28 May 1996 and went solo on 5 July 1996, after 16:25 hours. The night flying phase of the course started on 6 January 1997 and he flew again on the 13 and 14 January. His total helicopter flying before the accident flight was 117:30 hours, which included 2 hours dual and 3 hours solo at night.

The pilot had been assessed as a keen, hard working student who prepared well for each flight. His last periodic report indicated that he knew the required techniques and could produce good results. It was predicted that he would have successfully completed the course to CPL(H) standard.

Medical and pathology

The pilot had a medical examination on 25 March 1996 and met the required standard for a Class 1 medical certificate; for a commercial pilot under 40 years this is valid for 12 months from the end of the month of issue.

Post mortem examination revealed no pre-existing medical condition which would have contributed to the accident.

Analysis

The characteristics of the accident and the condition of the wreckage were all consistent with low rotor energy and a lack of engine power at the time of impact. The aircraft had, however, just completed the previous detail with no apparent engine power problems and had been observed to have lifted off normally on the accident flight. The possibility of mishandling was considered but the pilot's recent experience of solo night flying suggested that, in the absence of unusual circumstances, this was unlikely.

Although the witness evidence indicated that the aircraft never achieved an altitude of more than about 100 feet, at the estimated take-off weight the aircraft should have been able to achieve a relatively high rate of climb with the engine power normally available in the prevailing conditions. This, together with the unusual and regular sound reported by two witnesses, suggested an engine power problem. However, any loss of power must have occurred suddenly since an apparently normal 'towering' takeoff had been made immediately before the witnesses saw and heard the helicopter.

The examination of the helicopter and strip of the engine did not reveal any fundamental faults or mechanical failures.

The weather on the night of the accident (100% humidity at +2°C) was conducive to carburettor icing and the helicopter had been running for some time at a low throttle setting whilst the crew change had been taking place, shortly before this take off. The carburettor would be at its most vulnerable to icing in such conditions; ice build up occurring around the butterfly and affecting the engine's ability to be accelerated. However, since the engine had been accelerated for hover taxiing and then further accelerated to achieve the towering take-off, it would not appear to have accumulated significant induction ice whilst in this low power state. It appears, therefore, unlikely that carburettor ice would accumulate at a rate which could seriously affect engine power after about 1 minute of high power flight, particularly with a significant amount of carburettor heat applied, as was indicated by the position of the carburettor heat control.

However, use of hot air to the carburettor at high power is known to carry a risk of detonation if the intake air temperature limitations are not adhered to strictly. The use of carburettor heat at power demands above flight idle is sanctioned by the engine manufacturer on the basis of the carburettor temperature probe system being fitted and operative. Although it was not possible to ascertain the pre-impact serviceability of the system, the pilot on the previous detail reported that it seemed to him to be working correctly. The appearance of the combustion spaces indicated persistent lean mixture running which inferred that the engine was habitually, but not unusually, hot running; the carburettors for the R22 type engines are set-up to give a leaner mixture than that used for most applications of the manufacturer's engines.

The presence of a friable deposit, with a piece missing, on the back of the head of No 4 inlet valve suggested a potential mechanism for an abrupt decrease of engine power. It is possible that the piece of deposit which broke away from the valve head may have become lodged between the inlet valve and its seat. This would have allowed burnt gas into the inlet manifold and grossly affected the inlet mixture to all cylinders. The occurrence of the friable deposit suggested the presence, for some time, of the deteriorated valve seat observed during examination of the engine, which had led to a

hotter than usual inlet valve in the No 4 cylinder. The reduction of volatile matter in the inlet tract deposits of that one cylinder was considered consistent with significant combustion gas blow back into the inlet tract in the short term.

The radar returns indicated that the helicopter had not climbed above about 100 feet agl until clear of the airfield, indicating that the power loss probably occurred shortly after the transition from the apparently normal towering take off to the initial climb. If a reduced performance had been recognised at the onset, the prudent solution would have been to land immediately while the helicopter was still over the airfield. However, this would have required an immediate decision; to the student pilot there would almost certainly have been a period of confusion during which he may have wondered whether he had made an error of omission.

During this period, the aircraft would have flown beyond the airfield boundary where the pilot would then have been confronted by a generally featureless blackness beyond the brightly illuminated strip of the busy motorway. In the reduced power situation, the pilot would have had to reduce the collective pitch and, consequently, power demand, in order to maintain the rotor energy. It is not possible to say whether he had made an unsuccessful attempt to land beyond the motorway or that the power loss had led to a decay in rotor RPM and a subsequent loss of control.