

# Boeing 747-238B, G-VJFK, 28 April 1996

**AAIB Bulletin No: 9/96 Ref: EW/C96/4/10 Category: 1.1**

**Aircraft Type and Registration:** Boeing 747-238B, G-VJFK

**No & Type of Engines:** 4 Pratt & Whitney JT9D-7J turbofan engines

**Year of Manufacture:** 1974

**Date & Time (UTC):** 28 April 1996 at 1326 hrs

**Location:** Near London Heathrow Airport

**Type of Flight:** Scheduled Public Transport

**Persons on Board:** Crew - 20 Passengers - 306

**Injuries:** Crew - Nil Passengers - Nil

**Nature of Damage:** Loss of right hand 'off-wing' escape slide, minor damage to inboard flap upper surface and aft fuselage

**Commander's Licence:** Air Transport Pilot's Licence

**Commander's Age:** Unknown

**Commander's Flying Experience:**

Last 90 days - 158 hours

Last 28 days - 78 hours

**Information Source:**

AAIB Field Investigation

## **History of flight**

The aircraft departed from Runway 27R at 1326 hrs for a flight to the USA, following a period of some 17 days of third party contracted maintenance at London Heathrow airport. The take off proceeded normally but during the early stages of the climb one of the cabin crew seated near door R4 heard an unusual 'whooshing' sound. She reported what she had heard to the senior cabin crew member who in turn reported it to the commander. At about the same time a security guard at an airport control post and a person driving along the M25 saw an object fall from the aircraft. Both witnesses reported their observations and the driver stated that the object had fallen 'outside' the M25. These messages were forwarded to Heathrow ATC who in turn alerted the flight crew that a yellow coloured object had fallen from the aircraft. A check of the flight deck did not reveal any unusual warnings or anything amiss (there are two warning lights on the flight engineer's panel to indicate off-wing slide deployment and neither was illuminated). With no other indications of abnormality such as airframe vibration or unusual handling qualities, the commander chose to continue the flight and await a more accurate description of the object before deciding whether to proceed or divert. Meanwhile ATC had initiated a debris check of the runway which proved negative.

A lorry driver in the Blackthorne Road area of Poyle (about 1 nm from the end of the runway) had also seen the object fall from the aircraft and he watched it descend; he described it as resembling a large package and saw it fall into a tree, breaking two branches. He recovered the object onto his lorry and reported the event by telephone to the Heathrow police at 1336 hrs. They relayed the information to ATC that a lightweight object which appeared to be an aircraft's escape slide had fallen in the Poyle area.

The Heathrow police contacted their colleagues in the Thames Valley force to inform them that the object had probably landed within their operational area. Engineers from the operator, police officers and a member of the Heathrow Airfield Operations Safety Unit then departed to locate the object. Whilst they were en-route the commander contacted both ATC and his company by radio to ask if the object had been identified. On hearing that it had not, he decided to continue the flight.

The object was located at 1450 hrs and positively identified at 1530 hrs by the company engineers as the right hand side off-wing slide assembly. Positive identification reached the commander by HF radio shortly afterwards. He discussed his options with the company staff and they asked him to return to Heathrow to have the aircraft repaired.

At 1610 hrs ATC were informed by the operator that the flight had reached longitude 30° West and was returning to Heathrow. Shortly before 1830 hrs the cabin crew thought they heard another 'whooshing' noise from the vicinity of door 4L. This too was reported to the commander but again there were no warnings of slide deployment on the flight deck. At this point the commander became concerned by the possibility that the left hand slide might deploy and become entangled in the empennage; consequently, he declared an emergency and restricted the airspeed to 270 kt maximum. The aircraft had been airborne for over five hours and there was no need to jettison fuel.

Heathrow ATC brought the emergency services to a high state of readiness for the landing and vectored the aircraft for a straight-in ILS approach to Runway 09L. The flight crew added 5 kt to VREF and flew a normal approach without noticing any unusual vibrations or handling characteristics. The landing at 1855 hrs was uneventful except for a smoking brake unit noticed by the fire service. After their inspection, which revealed that the smoke was due to extraneous grease on the brakes, the aircraft taxied to the stand where the passengers and crew disembarked normally.

### **Technical examination**

As the aircraft taxied to its stand, it was apparent that the door for the right-hand off-wing escape slide was open and the tire slide pack was missing (Figure 1). There was minor damage to the upper surface of the inboard section of trailing edge flap, attributable to the slide pack as it departed its housing, and minor damage to the aft fuselage. The area of the fuselage-wing fairing just aft of the slide housing carried soot marks, indicating that the pyrotechnic 'cool gas generator', which inflates the slide when activated for emergency egress, had fired and was operating as the slide pack departed from the aircraft.

### **Recent maintenance**

The aircraft had just returned to service following third party contracted maintenance at London Heathrow. This work had been for a scheduled '5C' check and, within the total work packages supplied by the operator of G-VJFK, two work cards dealt with the off-wing escape slide compartment. One card, part of the 5C check, required a visual check of the condition and security of the system, an inspection check and lubrication of the cables. The other work card implemented Service Bulletin SB 747-25-2501, recurring every 730 days, which required detailed inspection of the firing cable to the cool gas generator on each side of the aeroplane.

The maintenance records show that the work was performed on 14 April and the duplicate inspection had been performed on the Service Bulletin portion of the task: no duplicate inspection was required for the 5C task. A Ground Occurrence Report had been raised by the Technician performing the work, concerned with fasteners missing from the left-hand firing cable and this report had been forwarded to the CAA as a Mandatory Occurrence Report.

### **Description of the Off-wing slide system**

The off-wing escape slide is provided to allow rapid movement from the overwing door ('Door 3') to the ground in emergency conditions. The slide is operated from the overwing door and includes a 'system integrator' mechanism (Figure 2) because of the requirement to inhibit the slide operation for maintenance, or when the slide is operated from outside the aircraft. This system integrator is located just forward of the slide compartment (Figure 1) and has a small access door. After maintenance or inspection, the latching operation on the main door is performed by moving the latch lever on the system integrator and the final operation is closure of this small access door.

In operation of the slide, a mechanical signal through the system integrator unlatches a series of four door latches ('Hartwell' type) along the upper edge of the slide compartment door: the door is hinged along its lower edge. These latches operate from latch sliders attached by coupling shafts to the system integrator and the latch mechanism is connected to two pyrotechnic deployment thrusters. Operation of these thrusters rotates the compartment door and slide pack outboard, actuating the inflation mechanism for the slide. The inflation may be by stored gas bottle or cool gas generator (as in G-VJFK) and the gas flow induces ambient air to inflate the slide through two injector pumps.

On the Flight Engineer's instrument panel there is one illuminated caption for each of the off-wing slide compartment doors ("Land R WING ESCAPE DR"). When properly rigged, this caption is lit by a microswitch detecting incomplete latching of the appropriate door. The caption circuit has the usual "Press-to-test" function of the caption bulbs but no means of testing the microswitch. There is also a physical 'Positive latching indicator', an indicator pin, normally painted red, mounted just forward of the aft door latch (Figure 1): this is designed to provide an external verification of the latching mechanism.

The operating instructions for the system integrator are displayed on a decal on the inside of the access door (Figure 2). This decal includes six checks after latching and prior to closing the access door, with a baulk on the access door providing the final check.

In some 747-100/-200 fleets the off-wing slide system was removed when the overwing door (Door 3) was deleted. In some of these aircraft the overwing door was later reinstated but this has generally been with the provision of 747-400 doors, where the off-wing slide is incorporated into the door itself. For maintenance organisations accustomed to servicing aircraft with 747-400 standard doors, as in this case, the off-wing slide system would only be seen during third party maintenance work.

### **Further technical examination**

Examination showed that the right-hand cool gas generator had fired and the left-hand generator had not. Neither of the thrusterson the right-hand side had fired, indicating that the opening of the door had not been initiated by mechanical signal through the system integrator.

Further detailed examination of the latching mechanism on the right-hand side showed that, although slightly worn, the bayonets which mated with the door latches were in good mechanical condition, as were the latches themselves. The latch sliders were found, however, in an intermediate position, neither fully latched shut nor fully open, but around the middle of the range between these positions: the effect was that the latch jaws would allow the bayonets to enter and allow the door to remain, apparently locked, in the vertical position but would not retain them against outboard pressure. Operation of the latching mechanism showed that, following the maintenance instruction and using a 1/4" drive wrench on the latch lever, a false but distinct detent was reached after approximately 90° of latch lever rotation and that this appeared to be the end of the mechanism's travel. It took a deliberate further action to overcome this false detent and reach the fully latched position. It was also noted that, with the door unlatched, the positive latching indicator pin could be pushed flat with the fuselage and would remain in this position. At some time the original red paint had been oversprayed with white paint and there had not been renewed.

The cause of the 'false detent' was investigated. It was found that the indicator pin mechanism was stiff due to the indicator pin's spring being improperly located.

The investigation of the failure of the "R WING ESCAPE DR" caption to illuminate after the departure of the off-wing slide showed the microswitch, mounted on the latching mechanism, to be out of adjustment and giving no indication as to the position either of the latching system or of the door. The microswitch on the left-hand side also proved to be out of adjustment.

The Inspection/Check instructions in the Maintenance Manual and on the inside of the access door are very similar and call for a check that the caption on the Flight Engineer's panel is extinguished after latching: there is no equivalent procedure in this sequence for checking that the caption is illuminated with the door unlatched. It is likely, therefore, that the microswitches had

been out of adjustment for some time representing an unexpected dormant failure within the warning system.

### **Human factors**

The maintenance technician who performed the work was well-regarded by his employer and considered conscientious, a view reinforced by his having raised the MOR on the left-hand slide system. The technician confirmed that he had performed the work with "hard" (*ie* paper) copies of the Service Bulletin and Maintenance Manual pages and that, after the system appeared to latch "with a positive clunk" (actually the false detent) the six checks detailed on the access door appeared to be satisfied, including the check that the indicator pin was flush.

Analysis of the six checks (Figure 2) showed that one does not alter with latch position and another represents, as noted previously, a dormant failure of the system for illuminating a warning caption at the Flight Engineer's panel. With the remaining four checks, including the indicator pin, the design of the system integrator made it very difficult to detect a 'nearly latched' condition, as found in this mishap. Finally, with the mechanism in the 'nearly latched' position, the physical baulk on the access door did not interfere with the latching mechanism and thus allowed closure of the door.

### **Previous occurrences**

A number of previous instances of in-flight losses of off-wing slides have been reported and further instances of the compartment door being found unlatched after flight. The airframe manufacturer reports some 30 in-flight losses in the previous 20 years, generally following maintenance, and further reports the causes as improper closing or latching, incorrect indications of latching and improper rigging.

Following the incident, the operating airline, the maintenance organisation and AAIB have discussed with the aircraft manufacturer the unexpected dormant failure within the warning system. The manufacturer has undertaken to correct this. AAIB have recommended that the FAA and CAA should monitor progress and ensure that the resulting changes are fully promulgated.