

Boeing 747-136, G-AWNB, 19 February 1996

AAIB Bulletin No: 7/96 Ref: EW/C96/2/1 Category: 1.1

Aircraft Type and Registration: Boeing 747-136, G-AWNB

No & Type of Engines: 4 Pratt & Whitney JT9D-7turbofan engines

Year of Manufacture: 1970

Date & Time (UTC): 19 February 1996, at approximately 1411 hrs

Location: Aircraft parking bay T9, London Heathrow Airport

Type of Flight: Public Transport

Persons on Board: Crew - 18 Passengers - 348

Injuries: Crew - None Passengers - None

Nature of Damage: No 1 engine was removed to be examined for thermal shock effects following the use of water to extinguish

the fire

Commander's Licence: Airline Transport Pilot's Licence

Commander's Age: Not applicable

Commander's Flying Experience: Not applicable

Information Source: Aircraft Accident Report Form submitted by the pilot

History of the Incident

The aircraft had originally been tasked to operate a scheduled service to Chicago on the previous day but had been withdrawn from service when a fuel leak was found close to the junction of the No 2 engine pylon and the wing. After rectification, the aircraft was returned to service and tasked to carry out a scheduled service to New York Kennedy Airport. The fuel load for the flight was 122.2 tonnes and this had been originally uplifted for the Chicago service.

The weather conditions included a surface wind of 010°/10kt, with reported gusts up to 30 kt, temperature 3°C and visibility of 30 kms. Passenger boarding was carried out through gate T9 at Terminal 4 and engine start was to be accomplished in the standard order of Nos 4, 1, 2, 3 during aircraft push-back into taxiway block 121/120. At the completion of the push-back the aircraft was facing north-east with the wind coming from its front left quarter. Engine starting was conducted using fuel enrichment due to the low temperature and No 4 engine started normally. No 1 engine did

not start on the first two attempts, therefore the ignition circuit breakers were pulled and reset by the crew. The third start attempt was successful. Nos 2 and 3 engines were then started without further difficulty.

On completion of the push-back the tug was disconnected from the aircraft but remained in the vicinity until the engine starts were completed. Prior to leaving the aircraft, the dispatching ground engineer noticed an apparent fuel leak from the No 2 engine pylon, so he requested assistance from the engineering control who sent the duty ground engineering supervisor to the aircraft. At 1419 hrs the flight crew informed Ground Movement Control (GMC) of a problem and asked if they could remain on the taxiway whilst an inspection was made. On examination, the ground engineering supervisor observed a running leak, which he confirmed as fuel, coming from the No 2 engine pylon and flowing via the wing leading edge to the wing under surface and from there to the fuselage underbody fairing and the left-hand body-gear doors. He advised that the engines should be shut down and the aircraft towed back onto Stand T9 to allow further engineering investigation. At 1429 hrs the crew advised GMC that they were returning to Stand T9.

When the aircraft had been repositioned onto the stand, the engineering supervisor approached from the direction of the tail and saw that there was a fire in the jet-pipe of No 1 engine. The effect of the gusting wind was to blow the flames forward through the intake and laterally in the direction of the No 2 engine. This information was passed to the flight crew who were advised to ground motor the engine to blow out the fire. The flight crew had been unaware of the fire because the engine fire detection system is designed to detect a fire within the engine cowlings and does not have fire detectors in the area of the jet-pipe. At about 1433 hrs, as the fire had not been extinguished, the engineering supervisor recommended to the flight crew that they request the assistance of the Aerodrome Fire Service (AFS) and continue to dry motor the engine until assistance arrived. The AFS, alerted by ATC at 1434 hrs, arrived at the aircraft at 1437 hrs.

The commander next advised his company operations control that he wished to evacuate his passengers through the airbridge; he did not want to use the aircraft door slides because this would place the passengers on the ground in a hazardous area. The hazard comprised the fire in No 1 engine jet pipe and the pooled fuel on the ground from the leak in No 2 engine. Prior to this call from the flight crew, the airline operations control had advised the dispatcher, who had been responsible for the departure of the flight, that the aircraft was returning to the stand and she was to attend to its requirements. When she arrived back at the stand the ground crew signalled to her that she was to position the jetty back to the aircraft door. She confirmed this by going down to the apron and speaking to the ground crew and then returned to the jetty and drove it up to the L1 door of the aircraft.

In the meantime, a two-man 'Checker' team from the Airfield Operations Safety Unit (AOSU) had arrived at the parking area having heard the call for the AFS on the GMC radio frequency. AOSU is a unit of HAL, which is a company within BAA plc. AOSU provides inspection and monitoring teams for the runways, taxiways, and apron areas; it provides a bird dispersal team and when necessary provides aircraft marshallers. The role of AOSU in an aircraft incident is to lead local authority services to the scene, and to assist with passenger handling. Its principal function is best described as ensuring that the emergency services can carry out their duties without impediment. They were immediately approached by the engineering supervisor who asked them to ensure that the AFS had been notified. One of the team confirmed that the fire service was on its way. He then instructed that the rear of the apron should be kept clear to allow access by the AFS and that the jetty should be kept clear of the aircraft. The engineering supervisor then went up into the jetty and told the dispatcher that Heathrow Airport Limited (HAL) personnel (ie 'Checker') had instructed

that the jetty was to be kept clear of the aircraft. Having received this instruction, the dispatcher drove the jetty away from the aircraft once more. She then contacted her operations controller on the internal telephone system, which was available in the jetty, and asked what was happening. The controller told her to put the jetty back to the aircraft as the commander wished to evacuate his passengers. Once the jetty had been repositioned at the L1 entrance, the dispatcher opened the aircraft door in preparation for the evacuation. By this time a police constable had arrived in the jetty and so the dispatcher instructed him to lead the passengers up into the terminal building arrivals level. Some of them had arrived there before the remainder were met by the Terminal Duty Manager, who took over the direction of the passengers, and led the way to the departures lounge. The subsequent evacuation of the aircraft was orderly and calm and there were no injuries to passengers or crew.

Safety Recommendations

The following safety recommendations are made:

96-12

The CAA, in consultation with the HSE, should make a formal assessment of the use of airbridges for the purposes of an emergency evacuation while an aircraft is parked on a stand. The assessment should consider the safety aspects in the light of existing and proposed airworthiness requirements together with the arrangements for the handling of passengers in airside and landside areas. Appropriate guidance should be issued to airport users.

96-13

The CAA should consult with aerodrome operators, airport users and handling agents on the appropriate duties of handling agents during passenger boarding until such time as the aircraft moves off under its own power and during passenger disembarkation. Manuals and Emergency Orders should define the precise period of responsibility that exists towards a flight. The provision of adequate communications between all the agencies involved should be ensured.

Engineering investigation

The fire in No 1 engine had been seated in the jet pipe and did not cause any damage to the aircraft. The engine was removed to be examined for thermal shock effects following the use of water to extinguish the fire. The fire may have resulted from the presence in the hot section of the fuel residue from the two failed starts. Two components, the Fuel Condition Actuator (FCA) and the Fuel Pressurising/Dump Valve, whose malfunction could have caused an excess of residual fuel on shut-down after the failed starts, were removed for investigation and no abnormalities were found during their test and strip examination. Prior to removal of the FCA its interconnection to the Start Lever in the cockpit was checked and found to be correct.

After the fuel leak was seen during the Pre-departure Check on 18 February 1996 the aircraft's fuel load was reduced and it was removed from service for rectification as a "casualty"; no specific work schedule was raised for the rectification but all the actions taken were recorded in the aircraft's Technical Log.

The collector system within No 2 Main Fuel Tank terminates in a single pipe which emerges from the tank through the wing's front spar into the top of the pylon. The engine Shut-off Valve

is positioned in the pipe inside the tank and fuel in the pipe is pressurised by boost pumps in the tank. The pipe end is flanged inside the tank and a threaded fitting projects through the spar and is secured by a nut (with washer) which seats onto the front face of the spar. The outboard end face of the threaded fitting is step grooved to take an O-ring in the inner groove and to accept the end of the next section of pipe in the outer groove to form a rigid coupling. When the outer knurled collar of the rigid coupling is tightened (specified by hand) a small clearance exists between it and the nut securing the threaded fitting at the spar. On G-AWNB, immediately outboard of the rigid coupling there was another pipe connector, a flexible coupling. Access to these fittings is made difficult by the close proximity of the engine air supply duct, control cables, electrical supply leads and other wiring looms.

When the aircraft was received by the engineering team no leak was visible. The initial fuel contents in No 2 tank of 30,000kg were increased by internal transfer until, at about 35,600kg, a leak again developed. It was found to be coming from around the nut on the threaded fitting at the spar. Fuel was again transferred out of No 2 tank so that a repair could be begun. The rigid coupling was undone to allow the nut on the threaded fitting to be backed off. It was found that, though this nut was not loose, its untightening torque was low. The nut, washer and spar face were cleaned and re-assembled with a sealant. The rigid coupling was re-assembled with a new O ring and wire locking was correctly applied to the knurled retaining ring. As the sealant applied to the spar required some time to cure, a leak check was not carried out at this time and the following Action was entered in the Technical Log:

"Leak traced to front spar (sic) at eng feed (not pipe leaking), large lock nut backed off and sealant applied, nut repositioned and tightened, packing replaced..... Sealant applied 04-45 hrs"

[Note: the "packing" referred to the O-ring in the rigid coupling].

A new Defect entry was entered in the Technical Log to cover the deferred leak check as follows:

"Check #2 pylon/front spar at eng fuel feed pipe for leak after sealant cured. (Will require 35,000 kg plus to leak check)"

In addition to the verbal handover briefing to the incoming team who would complete the work, an Airworthiness Hand-over Report was also written as follows:

"Fuel leak #2 pylon:- Fuel leaking from front spar at #2 eng. feed pipe. Connection dismantled and area cleaned/dried. Sealant applied and connections re-assembled.

A/C on 11.00 E.T.S., leak check when sealant cured if satis. overwing & underwing panels to refit and seal"

The oncoming shift carried out the work and recorded the actions in the Technical Log.

"Fuel redistributed #2 tank filled to 37,000 kg. No leak evident from fuel feed pipe."

The process of filling the No 2 tank to more than 35,000 kg, raising the fuel level above that of the pipe at the front spar allowed the sealing around the pipe to be checked for leaks but it did not provide a check on the integrity of the seal in the rigid coupling which had been disturbed. To check the seal the coupling would have to be pressurised by the fuel pumps.

Inspection following the incident on 19 February 1996 discovered a leak at the rigid coupling. The rate of flow was not high. However, it is possible that, before push-back, some fuel may have gathered inside the wing (in front of the spar) and flooded out when the aircraft was moved giving the appearance of a larger leak than actually existed. From slight residues on the underside of the wing it could be seen that fuel had been seeping from underside panels in front of the front spar. The O-ring seal removed from the rigid coupling was found to be intact, undamaged and of the correct part number. It is required to be lubricated at assembly but whether it had been adequately coated with lubricant could not be determined. During the inspection an engineer noticed a further seepage of fuel around a joint at the bottom spar flange where sealant on the outside surface had become detached. The tank was fully drained, purged and the sealing of the front spar repaired from inside before the aircraft was returned to service.