

Gardan GY80-150, G-ATXF

AAIB Bulletin No: 9/97 Ref: EW/G97/06/03 Category: 1.3

Aircraft Type and Registration:	Gardan GY80-150, G-ATXF
No & Type of Engines:	1 Lycoming O-320-A3B piston engine
Year of Manufacture:	1964
Date & Time (UTC):	7 June 1997 at 0900 hrs
Location:	Near Alderney Lighthouse, Channel Islands
Type of Flight:	Private
Persons on Board:	Crew - 1 - Passengers - None
Injuries:	Crew - None - Passengers - N/A
Nature of Damage:	Aircraft sank and not recovered
Commander's Licence:	Private Pilot's Licence
Commander's Age:	54 years
Commander's Flying Experience:	196 hours (of which 89 hours were on type) Last 90 days - 45 hours Last 28 days - 24 hours
Information Source:	Aircraft Accident Report Form submitted by the pilot and further enquiries by the AAIB

History of the flight

The pilot intended to fly to Montelimar in France to attend a fly-in for Gardan Horizon aircraft. His original plan had been to depart Popham, Hampshire at 1800 hrs the previous evening, but strong winds of 20 kt minimum were forecast and he decided to delay the flight until the following morning.

At 0700 hrs the next morning he filed a VFR flight plan for the first sector of the route which was to Jersey where he intended to refuel. As a synoptic weather chart for the route was not available at Popham that early in the morning, he decided to plan his route using a 10 kt headwind and estimated his flight time as 1 hour and 30 minutes. This would have been equivalent to a ground distance of 121 nm and was a reasonably accurate assessment of the actual distance to Jersey. The surface wind at Popham at that time was given as light and variable.

The pilot stated that his version of the Gardan Horizon has a maximum fuel capacity of 35 gallons. The pilot used a Universal fuel gauge and a chart, which had been constructed by the previous owner of the aircraft, to determine that he had a total fuel load of 16 gallons which at a consumption rate of 7.5 gallons per hour he interpreted as an endurance on departure of some two hours. The pilot later stated that he was reluctant to fuel the aircraft to its full capacity as he believed it had a tendency to siphon fuel through the tank vents when full. In addition he considered the aircraft fuel gauges to be highly inaccurate when the tanks were less than half full.

The engine was started at 0815 hrs and the aircraft was taxied out without undue delay for a take off on Runway 21. After takeoff, the pilot observed that the top latch of the door had sprung open; this was not an uncommon occurrence in this aircraft, and so he carried out a circuit of the airfield and landed back on Runway 26. After landing, he closed the door and taxied around for a further take off on Runway 26, finally getting airborne for Jersey at 0837 hrs.

The first part of the flight was flown at 1,000 feet until south of the Needles at which stage a climb was made to 2,000 feet. At 0943 hrs radio communication was established with Jersey Zone when the aircraft was radar identified at 50_N which is the northern boundary of the Channel Islands Control Area (CTA).

At 0947 hrs, the pilot called ATC to request a diversion to Alderney as he required to refuel due to the head winds. Permission was granted for the diversion and he was cleared under Special VFR (SVFR) maintaining 2,000 feet direct to Alderney on his own navigation. The controller suggested a heading of 230°. At 0949 hours control was passed to Alderney at which time the aircraft was 13 nm from the airfield. At 1000 hrs Alderney cleared the aircraft to report on final approach for Runway 26, the surface wind being 180_/18 kt. Less than a minute later the pilot made a MAYDAY call to the effect that his engine had failed, he was running out of fuel and was then one mile to the north of the island. After being cleared to land on any runway he then advised that he would have to ditch the aircraft.

During the glide to the surface, the pilot saw a fishing boat towards which he turned the aircraft and ditched within 200 yards of it along the swell. It took at least a minute for the water level inside the aircraft to equalise with that outside and so allow the pilot to open the door. During this time he was able to unfasten his harness and generally prepare himself. Once he had opened the door he stood on the wing and attempted to retrieve his flight bag, however, the aircraft then pitched steeply nose down and sank. The pilot then inflated his life jacket and swam clear; he was rescued by the crew of the fishing boat less than eight minutes later.

Flight Planning

The wind at 2,000 feet altitude at the time of the flight was 200_/30 kt. Although the track to Alderney was not always directly into the wind, analysis of the radar data (obtained by the AAIB for the flight) allows an estimation of the average overall ground speed as 72 kt. On occasion the aircraft's ground speed fell to as little as 58 kt. For a direct route to Jersey from Popham via the reporting point ORTAC, the total distance is approximately 123 nm which, at an IAS of 90 kt and 10 kt of headwind, would take 1 hour and 31 minutes. However, using a headwind of 20 kt or the average ground speed of 72 kt that has been calculated for this flight, the flight time would have been 1 hour and 44 minutes. Taking into account the extra circuit that was flown at the beginning of the flight, which took 22 minutes from engine start to final take off for Jersey, minimum fuel required without reserves would have been 2 hours and 6 minutes. Given a calculated consumption of 7.5 gallons per hour this is equivalent to 16.8 gallons. The pilot calculated that he had 16 gallons

on board at engine start. In summary, the consumption of 22 minutes of fuel endurance before the start of the flight had reduced the planned fuel reserves to only 8 minutes. This calculation being based on the pilot's estimated time en route of 1 hour and 30 minutes, allowing for a 10 kt head wind, and a reserve of 30 minutes.

In the event, the engine ran for 1 hour and 46 minutes before stopping which would indicate that the actual consumption rate was closer to 9 gallons per hour, assuming that the assessment of a departure fuel state of 16 gallons was accurate. Taking account of the pilot's estimate of 140 lbs of baggage on board the aircraft, an increase in the usual fuel consumption might be expected.