

# DHC-8-311, G-BRYR

## AAIB Bulletin No: 11/97 Ref: EW/C97/5/3 Category: 1.1

<b>Aircraft Type and Registration:</b>	DHC-8-311, G-BRYR
<b>No &amp; Type of Engines:</b>	2 Pratt & Whitney PW-123 turboprop engines
<b>Year of Manufacture:</b>	1992
<b>Date &amp; Time (UTC):</b>	8 May 1997 at 1230 hrs
<b>Location:</b>	Paris Charles de Gaulle Airport
<b>Type of Flight:</b>	Public Transport
<b>Persons on Board:</b>	Crew - 4 - Passengers - 17
<b>Injuries:</b>	Crew - None - Passengers - None
<b>Nature of Damage:</b>	None
<b>Commander's Licence:</b>	Airline Transport Pilot's Licence
<b>Commander's Age:</b>	28 years
<b>Commander's Flying Experience:</b>	3,123 hours (of which 1,440 hours were on type) Last 90 days - 179 hours Last 28 days - 55 hours
<b>Information Source:</b>	AAIB Field Investigation

## History of Flight

On the day of the incident the crew were scheduled to operate five sectors; from Edinburgh to Bristol and then via Plymouth, Jersey, and Paris back to Bristol. The flight departed Edinburgh at 0600 hrs. On lining-up for take-off from Bristol at the beginning of the second sector, the commander noticed that the rudder pedals seemed stiff to operate, however this did not cause him undue concern and he continued with the take off. The stiffness disappeared during that sector and was not felt again until the aircraft departed from Paris on the final sector of the day.

After a short delay for air traffic clearance, the flight departed from Charles de Gaulle airport at 1220 hrs for Bristol. The wind on departure was 240 / 32 kt and Runway 27R was in use, consequently there was a crosswind from the left of approximately 16 kt. After take off the commander, who was the handling pilot for the sector, found that he was unable to move the rudder

pedals. During the subsequent climb to Flight Level (FL) 100, the landing gear and flaps were retracted with no noticeable effect on the rudder pedals, which remained immovable. Control of the aircraft was passed to the first officer who confirmed the condition. Rudder trim was applied and movement was confirmed on the trim indicator. The flight deck switchlights for the two rudder hydraulic actuators were then checked to ensure that they were not illuminated and to confirm filament integrity. Had either switchlight been lit, this would have indicated a failure of the respective rudder power control unit actuator linkage; however neither was illuminated. The autopilot was then selected successfully. In addition to relieving the pilots of the physical control of the aircraft, this also served to confirm that the yaw damper was operating because yaw damper failure would have prevented autopilot coupling.

After confirming that there was no appropriate emergency drill in the aircraft Quick Reference Handbook (QRH), the crew advised Paris ATC that they had an emergency situation and requested diversion to an airfield which had a suitable into-wind runway. ATC suggested a diversion to Beauvais which is approximately 30 nm north-west of Paris Charles de Gaulle airport, for a landing on Runway 23. The surface wind was given as 240 /12 kt. On approaching Beauvais, the crew decided to delay their landing until the arrival of the full fire service cover. As that day was a public holiday in France, the fire service from the nearby town had to be called out to provide full cover, and this resulted in a 35 minute delay before a landing could be made.

During this delay, the crew were able to check their landing distance requirements. As Runway 23 was wet, they calculated that the landing distance required would be 992 metres. Although Paris ATC had advised that Runway 23 was 1,500 metres long, the flight documents for the runway showed that there was only 1,105 metres available for landing, the remainder being declared unusable. In addition, there was no runway instrument approach aid nor approach lighting available for this runway. As the runway was also slightly narrower than usual at 40 metres, the commander decided to carry out an approach to Runway 31 which was 2,430 metres long, 45 metres wide, with high intensity approach lighting and an instrument landing system (ILS). By this time the surface wind was 240 /12 kt with gusts up to 16 kt.

The crew then found that they were unable to tune the ILS using the frequency promulgated on their approach chart and on checking this with ATC they were informed that the frequency had been changed. It was later ascertained that the company which produced the chart had not promulgated the change in time for the amendment to have been incorporated in the manual prior to this flight. Having set the correct ILS frequency, the crew then carried out an uneventful approach and landing.

### **Flight Data Recorder Information**

The Flight Data Recorder (FDR), a Loral Fairchild F800 serial number 4494, was removed at Beauvais and returned to the AAIB. From the 25 hours of recorded data, which was divided into 6 tracks, there was valid data on track No 5 and part of No 6. This covered 7 complete flights, but did not include the incident flight. Part of a flight was recorded on track No 3, ending mid-cruise, and the most recent data was on track 4. The replay showed no signal on track 1: this was investigated by the overhaul agency, and it was found that a small build up of magnetic oxide had accumulated on the recording head, causing loss of signal. For the remainder of the transcription the data was in synchronisation, but it was not possible to convert the data into meaningful values. This suggested that there may have been an intermittent acquisition problem, since the FDR was working at intervals during the 25 hour period.

A new FDR was fitted to -YR at Beauvais; a replay of this following the aircraft's flight to Plymouth showed no problems with the data. Subsequently, a number of additional readouts from this aircraft have been analysed without difficulty.

### **Description of the rudder system**

The commander and co-pilot's rudder pedals are connected, via rods and bellcranks, to a duplicated cable system under the floor. The two sets of rudder pedals are linked by an interconnect strut. The cables come together at a mixing quadrant approximately halfway along the fuselage, from which a single cable system runs to the rudder input quadrant in the fin. A rod from this quadrant forms the input to a summing lever assembly, which also takes inputs from the (electric) trim actuator and autopilot rudder servo. The latter component also serves as the yaw damper actuator and the arrangement of the linkage is such that yaw damper/autopilot inputs to the rudder are not fed back to the rudder pedals. However, trim operation does result in rudder pedal movement. The summing lever assembly also incorporates a feel spring assembly, consisting of two springs, which provides artificial feel to the rudder pedals. Two spring strut assemblies connect the summing assembly output levers to each of two hydraulic actuators, which in turn are attached to the rudder. The spring struts each have an associated cam and microswitch assembly such that, in the event of a jam in an actuator or its linkage, the resultant cam motion causes illumination of the corresponding RUD 1 or RUD 2 powered flight control shut-off switch light on the glareshield. When the switch is pushed to the Off position, the jammed system is depressurised and the pressure in the serviceable system is doubled to 3000 psi.

Finally, the rudder is equipped with a gust damper. This consists of a hydraulic cylinder and piston assembly, and has an internal spring loaded valve which opens when aircraft hydraulic system pressure is applied, thus allowing fluid to transfer from one side of the damper piston to the other during normal rudder movement. When system pressure is removed, the valve closes and the unit reverts to damper mode.

### **Examination of the aircraft**

The airline's engineering personnel examined the aircraft at Beauvais and after finding no fault with the rudder system, cleared the aircraft for a non-revenue flight to Plymouth, which was the main engineering base. The rudder control system was then subjected to a detailed examination, with the AAIB in attendance.

Consideration of various aspects of the system design in relation to the symptoms, ie the restricted/jammed pedals, ought to have provided an indication as to the likely location of the problem. For example, in the event of a complete mechanical jam involving the hydraulic actuators, the gust damper, or even the rudder itself, the rudder pedals would still be capable of being moved, although this would simply deflect the feel springs. Furthermore, an actuator jam would cause a RUD 1 or RUD 2 caution light to illuminate. The absence of any such indications suggested that there was no problem with either the actuators or the hydraulics system. Additional confirmation of hydraulic system integrity and freedom from mechanical jams in this area was provided by the fact that the autopilot remained engaged, with the aircraft responding to inputs. It was therefore concluded that the restriction or jam had probably occurred upstream of the summing lever/feel spring assembly.

The trim system was apparently effective, as the aircraft responded to small trim inputs, with confirmation provided by the trim indicator. However, the latter is signalled by a potentiometer

within the trim actuator, as opposed to movement of the rudder. In the event of a 'rigid' mechanical jam, the trim actuator output rod simply deflects the feel springs, with no output from the summing lever assembly to the hydraulic actuators. (This was confirmed by pinning the cable quadrant immediately ahead of the summing lever assembly and operating the trim system). Subsequent to the incident, the commander could not be certain as to whether any rudder pedal movement occurred as a result of trim operation. The fact that the aircraft responded to trim inputs indicated that the trim system was operational. However, actual rudder movement was likely to have been small and it was possible that the trim actuator achieved this movement by a combination of limited system movement against the jam and localised cable stretch.

The examination at Plymouth consisted of a complete visual inspection of the system, which was achieved by removing all external access panels, together with the seats and floor panels. The only noteworthy feature found was a contact mark made by the end of one of the feel springs on the summing lever mounting bracket. It was found that the spring end would almost contact the bracket if the rudder pedals were held in the neutral position with full left trim applied: such a condition is unlikely to have occurred in flight. However any actual contact, although undesirable, would have exerted an insignificant force on the rest of the rudder system.

The cable tensions were checked and found to be satisfactory. Finally, one of the hydraulic actuators was changed, as a small amount of free play was found on one of the valve input links, and the gust damper was also changed as a precaution. The aircraft was then released back into service.

On 2 June another rudder restriction occurred, which was described as "rudder operation very stiff at high speed, [together with] more than usual rudder force required during landing phase". After an otherwise uneventful landing at Newcastle, an inspection again failed to find any defect in the rudder system. By this time, the airline had acquired a spare summing lever/feel unit and this was fitted to the aircraft before it was returned to service. However, two days later "more force than usual" was reported to have been required on the rudder pedals at low speed whilst on approach to Bristol. As in the previous incidents, no fault was found on the ground and so the aircraft was once again cleared for a flight to the maintenance facility at Plymouth for further investigation. On this occasion, the cables were loosened so that they could be slipped off the pulleys and quadrants. This enabled an assessment to be made as to whether the latter were able to move freely on their bearings. No problems were found, apart from some minor binding of a 'paxolin' guide pulley against a sheet metal diaphragm.

Consideration was given to the possibility of environmental factors, such as ice, being responsible for the restrictions, despite the fact that the aircraft was not known to have flown through significant precipitation prior to any of the incidents. The summing lever/feel unit that had been removed from the aircraft at Newcastle was placed in a freezer for two hours in order to establish whether the component was affected by frozen moisture within the bearing grease. It was found that the unit operated normally on removal from the freezer. However, during the examination of the feel unit it was noted that the springs differed in appearance in that the coils of one of them were 'opened out' at one end. Reference to the aircraft manufacturer indicated that this was a dual-rate spring, the other being single-rate. This condition was likely to have existed since the unit had been manufactured, and probably resulted from a spring vendor supply problem. The result of the dissimilarity would have been slightly different pedal forces either side of the neutral position, although these had clearly not been detectable to the extent that pilots had made any comment.

The cables aft of the mixer quadrant were replaced as a precaution, although in fact no fault was found with the existing cables. The hydraulic actuator that had not been changed following the initial incident was also replaced at this time, and the aircraft was once again returned to service.

The aircraft operated normally until 19 June, when a further incident of stiff rudder pedals occurred, once again during an approach to Bristol. Yet again, the problem could not be reproduced on the ground. Having already replaced so much of the system, it was decided to disassemble the rudder pedal linkages beneath the flight deck floor, ahead of the cable run. It was during this operation that the bearing bushes at the base of the commander's left rudder pedal were found to be badly worn. A diagram of the area is presented at Figure 1 where it can be seen that the vertically orientated tubes that carry the pedals are welded to short, horizontal sections of tube. The bushes are inserted into the ends of the latter, with the assembly rotating on a steel pivot shaft attached to the aircraft structure. The shaft also carries two brake control levers. It was noted that, under hand pressure, the bearings felt "tight" in comparison with the equivalent components on the co-pilot's side, which were found to be in good condition.

The worn bushings were removed and new components inserted into the ends of the tube. However, it was then found that the pivot shaft could not be inserted through both sets of bushings in the rudder pedal tube, although it fitted easily into either end. Suspecting the tube was distorted in some way, the operator decided to scrap the rudder pedal assembly and pivot shaft, which was then sent to AAIB for a detailed metallurgical examination.

The bearing bushes were found to be commercially available items made from mild steel strip. The inner (bearing) faces were coated with sintered bronze, and this in turn was coated with a film of lead-impregnated PTFE. It was found that the surface coating on the bearings had worn non-uniformly into the bronze at intervals around the circumference, such that in the worst affected position, a total of 0.010 inch of PTFE and bronze had been worn away. In places the coating had been wiped into 'ridges'. The bearings in the commander's right rudder pedal tube, and in the brake control levers, were found to be in good condition. A photograph of one of the worn bushes is shown at Figure 2.

The bushes had been an interference fit in the rudder pedal tube, the ends of which had been counterbored to a depth equal to the width of each bushing. Thus the inner edge of each bushing abutted a machined edge within the bore of the tube. When the counterbored surfaces were measured at several locations, it was apparent that the counterbore axes were not aligned with each other. The degree of misalignment could not be quantified due to the difficulty of establishing a datum, as the tube itself was neither round nor straight. This accounted for the difficulty encountered when the pivot shaft was inserted into the rudder pedal tube following the bush replacement. There must have been a similar degree of difficulty in inserting the shaft into the tube with the original bearings when the rudder pedal assembly was built by the aircraft manufacturer. Forcing the shaft through the tube would have had the effect of pre-loading the assembly in a manner which tended to straighten out the misalignment in the tube, and to bend the pivot shaft. This in turn would have led to high contact stresses between the bearing mating surfaces over part of the circumference, leading to excessive and uneven wear.

The pivot shaft outer surface was scored and worn to varying degrees in the locations occupied by the bearings, including the brake control levers (see the photograph at Figure 3). The shaft was plated with cadmium, a soft metal, and it was apparent that this had been worn away, exposing the steel substrate in places. In other areas it had 'balled up' and appeared to contain quantities of PTFE from the bearings. It is probable that material generated as a result of the wear in the bearings

was responsible for the intermittent restrictions experienced in the rudder system. The 'balling up' or 'galling' process would have caused lumps of material to have become wedged between the moving surfaces, thus hindering relative motion until such time as they migrated out of the ends of the bearings. Although it seems unlikely that such a process could have resulted in a complete jam, it is possible that pilots could perceive a restriction as a jam, bearing in mind there would have been an understandable reluctance to apply excessive pressure on the pedals in case the restriction was suddenly overcome, thereby causing a large and sudden rudder deflection.

The use of two soft materials, in this case the bronze/PTFE and the cadmium plating in a bearing, was considered to be dubious engineering practice due to the possibility of galling. The rudder controls of the Dash 8's predecessor, the Dash 7, utilised a similar design concept although the components are not interchangeable. It was noted that the pivot shaft on this aircraft was chromium plated, which provides a smoother and harder bearing surface.

It was concluded that the series of incidents that occurred to G-BRYR probably resulted from a combination of the misaligned bearing recesses in the commander's left rudder pedal tube and the soft cadmium plating on the pivot shaft. This would have led to locally high contact stresses within the bearing, resulting in excessive wear and galling.

### **Previous occurrences**

The aircraft technical records contained one other case of rudder pedal stiffness, which occurred on 30 September 1996. No associated fault was found and there was no reported recurrence until the Paris incident on 8 May. The aircraft manufacturer stated that they were not aware of any similar incidents associated with the Dash 8 series of aircraft, of which there are currently in excess of 450 in service, which have accumulated more than 7.8 million flight cycles. The lead aircraft has flown 44,500 flight cycles, compared to approximately 11,200 achieved by G-BRYR at the beginning of May 1997.

### **Future action**

Notwithstanding the absence of similar incidents on other aircraft, the manufacturer is proposing to change the surface finish on the pivot shaft from cadmium to chromium. The modified components will be incorporated on new production units and will be interchangeable with the existing part. In addition, the manufacturer has issued an In-Service Activity Report (ISAR) which advises operators of the problems that occurred on G-BRYR, and requests that any similar experiences be reported to them. The ISAR also suggests appropriate troubleshooting action.

### **Postscript**

On 21 September 1997 another Dash 8 aircraft, G-BRYI, belonging to the same operator, suffered an event in which the rudder pedals jammed in the neutral position during a take-off roll at Bristol. The take off was aborted and as the aircraft decelerated through 50 to 60 kt, the rudder pedals abruptly freed and operated normally thereafter. Subsequent investigation revealed that the commander's rudder pedal pivot shaft was worn in places, although the associated bearing bushes appeared to be in better condition than those from G-BRYR. In addition, some corrosion was found on some of the feel unit components.

On 8 October 1997, another incident occurred to G-BRYR when rudder pedal stiffness was experienced whilst attempting to keep the aircraft straight during take off. This led to the take off

being abandoned at 60 kt. The recently replaced pivot shaft on the commander's side, which had achieved only 1082 hours since installation, showed evidence of rubbing, together with a 'dusty' deposit. The component was reinstalled after being polished to a smooth condition.