

Gulfstream Aerospace AA-5B, N28397, 23 November 1996

AAIB Bulletin No: 8/97 Ref: EW/C96/11/6 Category: 1.3

Aircraft Type and Registration:	Gulfstream Aerospace AA-5B, N28397
No & Type of Engines:	1 Lycoming O-360-A4K piston engine
Year of Manufacture:	1977
Date & Time (UTC):	23 November 1996 at 1204 hrs
Location:	Denham, Middlesex
Type of Flight:	Private
Persons on Board:	Crew - 1- Passengers - None
Injuries:	Crew - Fatal - Passengers - N/A
Nature of Damage:	Aircraft destroyed
Commander's Licence:	Private Pilot's Licence
Commander's Age:	46 years
Commander's Flying Experience:	1,948 hours (of which 1,011 were on type) Last 90 days - 23 hours Last 28 days - 5 hours
Information Source:	AAIB Field Investigation

History of the Flight

On the day of the accident the pilot intended to practice circuit flying at Denham airfield having not flown this aircraft since 14 September 1996. The weather was ideal for his planned flight with clear skies and excellent visibility, the temperature was +5_C, the dew point -1_C and the surface wind was 290_/10 to 15kt. Runway 24 was the runway in use; it has an asphalt surface and is 2,555 feet long. The pilot requested taxi clearance at 1120 hrs and was cleared for take off at 1126 hrs. He then completed a number of circuits which included touch and go landings, full stop landings and at least one go-around. Throughout this period the aircraft behaviour and all RTF transmissions were normal.

The pilot completed a full stop landing and requested clearance to taxi, via the grass, to the holding point of Runway 24 for a further take off and circuit. On the subsequent take off, at 1204 hrs, the

aircraft became airborne at the usual position, about half way along the runway. The acceleration and the initial climb appeared to be normal. At an estimated height of 150 to 200 feet the engine stuttered briefly and then stopped abruptly. The aircraft immediately commenced a turn to the left with a rapidly increasing bank angle and at this stage there was a brief, indecipherable radio call from the pilot. With the bank angle now approaching 90° the nose of the aircraft snapped down sharply and the aircraft entered a vertical descent and impacted the ground on the adjacent golf course about 100 metres from the end of the runway.

The fire crew on duty had witnessed the take off and subsequent crash and were already on their way to the fire truck when the crash alarm was sounded. On arrival at the crash site, approximately one minute later, one of the fire crew determined that the pilot had been fatally injured whilst the other member of the fire crew discharged a fire extinguisher over the port wing which was visibly leaking fuel; there was no fire. A post mortem examination of the pilot did not reveal any condition which may have led to pilot incapacitation.

Pilot's background

The pilot had completed his PPL training in 1985 on an AA-5A and had begun flying the AA-5B the same year. He was one of a syndicate of three pilots that had purchased N28397 in 1991. His flying, mainly out of Denham Airfield, had been accrued at a constant rate of about 180 hours per year and since 1992 this had been shared between the AA-5B, a Cessna 172 and a Beech Baron.

The aircraft had last been flown on 26 October 1996 by another pilot from the same syndicate for a total flying time of one hour and 25 minutes. Prior to that flight it had been topped up with 60 litres of AVGAS but the pilot, who had conducted his own refuelling, could not be certain about the fuel state either after refuelling or at the end of the flight; there are no records of any subsequent fuel uplift.

Significant aircraft design features

The two fuel tanks in this type of aircraft are integral with the wing structure. They are bounded by the light gauge wingskins which form the continuous top and bottom surfaces and leading edges, together with closure ribs bonded to the skins at inboard and outboard ends of the tank stations and bonded vertical webs at the rear. (Main wing bending is carried by large diameter tubular spars which pass through the tanks and are positioned at approximately wing mid-chord). The tanks are positioned with their inboard closure ribs approximately 9 inches outboard of the wing roots. The outboard closure ribs are attached by a number of fasteners to the inboard ribs of similarly constructed drybays immediately outboard of the tanks.

Two fuel pipes pass through each of the inboard closure ribs. Each pipe connects to a finger strainer inside the tank positioned to collect fuel from points close to the forward and rear of each tank respectively. The two pipes from each tank supply fuel to one of two sumps positioned within fairings inboard of each tank below the plane of the tank bottom skin. Each sump contains a drain valve at its lowest point. Individual fuel pipes then route from the lowest points on the rear faces of these sumps to a common selector valve positioned on the centre line of the aircraft and operated by a rotary lever in clear view of the pilot.

The fuel selector has three positions, the corresponding lever positions being annotated respectively BOTH OFF, LEFT TANK and RIGHT TANK. They are selected in the above sequence by rotating the selector lever clockwise. Two electrically operated fuel gauges are positioned side by

side above the selector in such a way that the selector lever points at the contents gauge appropriate to the selected tank. A single fuel pipe then routes to the carburettor via the electric pump and the engine driven pump.

Initial site examination

The impact site showed clear evidence that the aircraft had struck the ground at a steep nose down angle whilst banked to the left on a heading more than 180° to the left of the runway centre line and approximately 150 metres south of it. Initial impact had occurred on the nose and left wing. The ground impact impression produced by the propeller, together with the nature of the damage to its blades, showed that it was either stationary or revolving very slowly at the time. The force of the impact caused the forward fuselage to telescope and break away from the engine bulkhead, allowing the majority of the fuselage, wings and tail to rebound and come to rest a short distance from the engine which remained with the bulkhead close to its initial impact point. The absence of engine and bulkhead coupled with the largely undamaged state of the main landing gear allowed the remainder of the aircraft to come to rest in a steep nose down attitude.

Examination of the flap actuator indicated that approximately one third of the total flap extension was set at the time of impact. The fuel selector was found in the BOTH OFF position.

Examination of the fuel tank areas approximately one and a half hours after the accident revealed no evidence of fuel in either tank. Considerable fire extinguishant powder was visible on and around the left tank which was heavily disrupted by the impact of the leading edge with the ground. The right tank had suffered no damage as a direct result of ground impact although some distortion was present at the outboard end of its leading edge where the inboard rib of the dry bay was attached to the outboard tank closure rib. This tank rib was distorted by tension in the fasteners attaching it to the adjacent rib as a result of ground impact and damage to the leading edge of the dry bay. In the process of inflicting this damage fasteners had pulled out of the outboard closure rib of the tank creating small punctures.

Subsequent detailed examination

The wreckage was taken to the AAIB facility at Farnborough. A total of 120 milli-litres of fuel were recovered from the drainpoint of the right sump with the remaining aircraft structure mounted horizontally on trestles. Very little fuel was recovered from the left tank sump. At no time during the lifting and transport from the accident site was any fuel seen to escape from the aircraft.

The right tank was then filled with three gallons of kerosene and no leakage was noted. Only when the aircraft was tipped forward to a nose down angle approaching that at which it came to rest after the impact was any kerosene observed to flow from the areas of the broken fasteners in the outboard closure rib of the tank.

It is known that constituents of aviation petroleum fuel will cause a staining of vegetation to become evident a few days after being spilt on the latter. This characteristic has been useful on many occasions in estimating approximate pre-impact fuel distribution in crashed aircraft tanks after they have been disrupted and the fuel lost. Some days after the accident the ground at the accident site was examined for such staining. Considerable staining was observed in the ground area identified as having been occupied by the left tank immediately after the impact together with signs of a residue of the fire extinguishant used. Careful examination of the area known to have been occupied by the right tank revealed a complete absence of any such staining.

An examination of the profile of the inboard leading edge area of the right wing (*ie* the boundary of the fuel tank) and the inboard tank boundary rib revealed no evidence of the 'hydraulic' type bulging distortion normally evident in the forward part of a tank containing fuel when subjected to rapid deceleration.

Examination of the available elements of the fuel system revealed no evidence of pre-impact damage. The engine and carburettor were subjected to strip examination. The magnetos were run on a test rig and the ignition harnesses and plugs were tested. No defects were found in any of these items other than those consistent with impact effects.

Tests on a similar aircraft

Another AA5B aircraft was flown at identical weights and in similar weather conditions. Two full power take offs were timed from brake release to an height of 150 feet and the mean time for this event was 40 seconds. Whilst on the ground the throttle was then advanced to full power and the fuel selector moved to the BOTH OFF position, the engine ran for 12 seconds before stopping abruptly.

The position, orientation and movement range of the fuel selector were examined. It was concluded that its characteristics made it very unlikely for it to have moved from either of the selected tank positions to the BOTH OFF position as a result of impact forces.

Summary

A loss of engine power undoubtedly occurred, although no mechanical or electrical explanation for that loss has been found. There is little doubt from the evidence that at the time of the impact the right fuel tank was effectively empty. A sudden loss of engine power in the climb is consistent with the final take off having occurred with the selector set to the RIGHT TANK position with virtually no fuel remaining in that tank.

Fuel tank gauge systems of this design are insufficiently accurate to enable one tank to be used to the minimum quantity before selecting the other tank. Similarly, calculations based upon the initial contents and subsequent fuel consumption would also have been insufficiently accurate to guarantee a safe re-selection of the left tank. Although the fuel selector was found in the BOTH OFF position tests carried out on a similar aircraft make it clear that the aircraft could not have become airborne and climbed on a normal flight path to a height of 150 to 200 feet had the take-off run commenced with the selector set to that position.

It is probable that the take-off run began with the fuel selector set to the RIGHT TANK, which was virtually empty. Fuel starvation occurred during the initial climb and the pilot moved the fuel selector to BOTH OFF as part of the emergency drill for an Engine Failure After Take off. The pilot then attempted to turn back towards the airfield but had insufficient height to execute this manoeuvre.