

Mainair Flash 2 Alpha, G-MTLA

AAIB Bulletin No: 1/97 Ref: EW/C96/7/8 Category: 1.4

Aircraft Type and Registration:	Mainair Flash 2 Alpha, G-MTLA
No & Type of Engines:	One Rotax 503 piston engine
Year of Manufacture:	1987
Date & Time (UTC):	17 July 1996 at 1608 hrs
Location:	Rhuallt near St Asaph, Denbighshire
Type of Flight:	Private
Persons on Board:	Crew - 1 - Passengers - Nil
Injuries:	Crew - Fatal - Passengers - N/A
Nature of Damage:	Aircraft destroyed
Commander's Licence:	Private Pilot's Licence Aeroplanes (Microlights)
Commander's Age:	35 years
Commander's Flying Experience:	135 hours of which all were on type. Approximately 10 hours had been flown in the last 12 months Last 90 days - Not known Last 28 days - Not known
Information Source:	AAIB Field Investigation, assisted by the British Microlight Aircraft Association (BMAA)

History of the flight

The pilot, who owned G-MTLA and had kept and operated it from the North Wales Microlight Centre for two years, had recently bought a new propeller. He arrived to fit it early on the afternoon of the day of the accident. A colleague watched as the pilot fitted the propeller and carried out a full power engine run which appeared satisfactory. Following this, the two men fitted a camera bracket to the starboard wing tip and connected the wing to the trike unit. The pilot then commenced his daily check which he habitually did using a printed check list. Thereafter, he was seen having a hot drink before refuelling the aircraft and donning his flying suit and helmet; he seemed to be well and looking forward to trying out his new propeller. He was seen to start the engine and taxi to the eastern end of the field where he appeared to be completing his pre take-off checks. The subsequent take-off was normal and he headed out to the North West and climbed to an estimated height of 1,500 feet agl. During the initial climb, the aircraft was seen to encounter some light turbulence but this appeared to be easily corrected; at height, the pilot carried out some normal

manoeuvres while staying close to the operating field. At the time, the weather was excellent with a clear sky and a light surface wind.

There were various witnesses who were aware of the last moments of the flight. All agreed that the aircraft was flying at approximately 1,000 feet agl. One witness, who has flown in microlight aircraft as a passenger, reported that she was about 600 yards away from the Microlight centre and saw the aircraft approach and undertake a very tight turn; it maintained this turn through approximately 540° before there was a loud crack and the left wing folded up. G-MTLA descended in an increasingly rapid spiral before impacting the ground. One other witness, who was approximately one mile away from the operating field, stated that he watched the aircraft flying over and that the engine suddenly stopped at the same time as the pilot seemed to lose control. The attention of other witnesses was drawn to the aircraft by either a loud crack or the engine note changing; these noises happened close together and there was some confliction as to which came first. However, all the close witnesses confirmed that the left wing folded up early in the sequence and that the aircraft entered a steep spiral to the left from which it did not recover; the witness who had seen the pilot fit the propeller also saw the right wing fold up soon after the left wing folded. As the aircraft descended, there was no engine noise. Additionally, bits of the aircraft were seen to fall to earth subsequent to the impact.

The post mortem examination of the pilot did not reveal any medical condition which may have contributed to the accident.

Aircraft description

The Manair Flash 2 Alpha is a flex wing aircraft with the engine and propeller mounted behind the trike unit which has provision for two occupants. Control of the aircraft in flight is accomplished by the movement of the wing relative to the trike. The wing is a simple tubular aluminium wire braced structure supporting a fabric cover, which is stiffened and profiled by battens. It is pivoted at the top of a monopole which forms part of the trike structure. The pilot controls the wing by movement of an 'A' frame which is attached under the wing at its apex and braced by fore, aft and lateral rigging wires; the lower transverse bar is positioned ahead of the front seat position such that it can be readily grasped by both hands. To pitch the aircraft up the bar is pushed forward, and to pitch the aircraft down, the bar is pulled back. Roll control is achieved by lateral movement of the same bar. When moved fully forward the bar contacts the front strut and rearward motion of the bar is limited by contact with the front pilot's chest.

At the time of the accident, the aircraft had a Permit to Fly expiring on 28 March 1997. The permit applied to the aircraft as defined in the Type Approval Data Sheets (TADS). At the time of the last inspection, however, the owner was informed that replacement of one of the propeller blades was advisable. He elected to buy a new propeller of a different design. It is reported that this propeller was found to be of a diameter such that insufficient clearance existed between the tips of the blades and the rear flying wires. The owner accordingly reduced the diameter from 62 inches to 60 inches. The new propeller type had not been approved for incorporation on this aircraft type and it was therefore a requirement that a Major Modification Form was filled in and submitted, (to the CAA or other organisation approved by the CAA) so that approval could be granted and the modification incorporated in the appropriate TADS. These documentary procedures were not followed.

Aircraft operational information

The aircraft is certified for non-aerobatics flight only. The maximum bank angle is 60° and the maximum pitch angle is 30°. Additionally, positive loading must be sustained at all times.

The aircraft manual includes the following statement:

'WAKE TURBULENCE

As an aircraft flies it leaves behind it severely disturbed air. Avoid flying, taking off or landing closely behind another aircraft, and be particularly careful of flying into your own wake turbulence. It is very easy to fly into your own wake during 360° turns and the effect can be quite violent. Microlights have been rolled as much as 90° turns by flying into their own wake. If you already happen to be in a bank, the potential results are self evident. Wake turbulence is greatest at high G loadings, during turns or slow flight.'

Wreckage examination

The wreckage was subjected to an initial examination by BMAA personnel before being dismantled and subsequently transported to AAIB at Farnborough for detailed examination. This revealed that the wing structure had failed initially in a negative-load direction and the control bar had moved forcibly forward into the front vertical member, causing both these tubes to fracture. The sequence of the major wing failure and the collision between tubes could not be determined from examination of the wreckage. There was no evidence that any of the bracing wires had contacted the propeller before the structural failure. No evidence of pre-existing material defect was present in any of the failed areas of the structure or the bracing wires.

The BMAA Inspector was aware that the pilot intended to fit the new propeller and had issued to him the appropriate major modification form to complete before the aircraft was flown with the new propeller. Furthermore, the aircraft would have to be officially inspected prior to flight. However, during the post accident investigation, the propeller was found to be correctly attached and, although extensively damaged in the ground impact, was free of any evidence of pre-impact failure. All other paperwork connected with G-MTLA was found to be in order.

After the accident, and following discussions with AAIB, the Civil Aviation Authority contacted the manufacturers of the machine to establish whether they had data on the pitching moment characteristics of this wing design in the region of the zero lift incidence angle. They reportedly responded that no such data was available but the characteristics of the aircraft presented no hazard, provided it was flown in accordance with the limitations specified and also that the aircraft complied in all respects with the requirements of BCAR Section S, the airworthiness requirements for microlight aeroplanes. This document requires that a microlight must demonstrate a positive slope of control force with flight speed, with airspeeds ranging from the recommended approach speed to V_{ne} , which implies the full range of incidence normally anticipated throughout the flight envelope. There is, however, no requirement to demonstrate that the slope of control force against speed remains positive over an incidence range from that appropriate to V_{ne} to the zero lift incidence. The CAA intends to review this issue before the next revision of BCAR Section S which will be aimed at demonstration of a positive slope of control force against incidence, down to zero lift incidence. Such revision, when issued, would only affect new designs.