

Cessna 172P, G-BMZV

AAIB Bulletin No: 5/97 Ref: EW/C96/11/5/025Category: 1.3

Aircraft Type and Registration:	Cessna 172P, G-BMZV
No & Type of Engines:	1 Lycoming O-320-D2J piston engine
Year of Manufacture:	1981
Date & Time (UTC):	21 November 1996 at 1353 hrs
Location:	Nr Compton Abbas Airfield, Dorset
Type of Flight:	Private
Persons on Board:	Crew - 1 - Passengers - None
Injuries:	Crew - 1 fatal - Passengers - N/A
Nature of Damage:	Aircraft destroyed
Commander's Licence:	Private Pilot's Licence
Commander's Age:	42 years
Commander's Flying Experience:	See text
Information Source:	AAIB Field Investigation

History of flight

The aircraft took off from Bournemouth International Airport at 1311 hrs and, at about 1350 hrs, joined the circuit for Runway 26 at Compton Abbas. The surface wind was calm and the weather was CAVOK; the grass runway surface was wet.

No witnesses were found to the aircraft's approach or initial landing roll. It was first reported as it passed abeam the clubhouse, travelling at a relatively high speed along the runway. When it was about 90 metres from the end of the runway the engine power was heard to increase. It continued along the ground in a gentle left turn into the adjacent stubble field. After some 30 metres it became airborne and tracked left towards a small copse, adopting a steep nose-up pitch attitude. The left wing then dropped and the aircraft descended rapidly to crash in a steep nose down attitude.

Pilot's flying experience

The pilot started flying in May 1988 and gained a PPL in December 1991. He had flown a total of 104 hours, all but 30 minutes of which were on Cessna 150 type aircraft or variants of that type. Over the previous 90 days he had flown 6 hours, 3 of which were during the previous 28 days. His last flight before the accident was on the 18 November 1996 when he successfully completed a

checkflight with a flying instructor. His log book showed that he had landed at Compton Abbas on six occasions, the last of which was in January 1994.

Medical and pathology

Post mortem examination revealed no pre-existing medical condition which could have contributed to the accident.

Compton Abbas airfield

Compton Abbas is a licensed airfield situated on a hill top, 810 feet amsl, 3 nm south of Shaftesbury. The landing distance available on Runway 26 is 803 metres and the surface condition was generally good with areas where holes or ruts have formed. The grass surface was wet, however, the pilots of other aircraft which arrived shortly before the accident reported that they had no braking problems. The ground falls away steeply to both the east and west of the airfield.

Impact features

The aircraft had struck the ground in an adjacent field on a heading of about 345° (magnetic) having turned some 275° to the left. Ground marks indicated that at first contact with the ground, the heading was about 020°, with the remaining 35° of left turn occurring during impact. The aircraft had been nearly vertical in pitch at impact, with the left wing low. There was no significant 'throw' of the wreckage indicating that the ground speed was very low, however the vertical speed had been high enough to cause major disruption to the nose of the aircraft. There was evidence of high engine power from the condition of the propeller. The flaps were set at about 30°, which on this particular aircraft represented the maximum available. The pilot had received fatal head and neck injuries in the impact, and both the front seats had moved forwards as far as the distortion to the front of the cabin would permit. Although the seats had moved forward, they had remained attached to their seat rails. The pilot's seatback was in a partially collapsed position as examined, however the mechanism was undamaged and photographs confirmed that, immediately after the accident and before the wreckage had been disturbed, the seat back had been upright.

Detailed examination

The flying control runs were checked and it was found that the associated cables and chains had remained on the column system; the aileron control system had been intact until the wing was removed, although it was distorted around the columns. The aileron system could only be partly functioned due to the distortion of the nose which had caused the yoke to jam. The elevator system was intact, but due to distortion of the fuselage and floor around the column, it could not be moved after the impact. The rudder cables were intact and connected, but the structural damage precluded functioning of the rudder pedals. The flaps had been selected to 30° and were found at that position. Although the flap electrical system could not be functioned, no associated faults were found. This aircraft type is capable of performing a go-around manoeuvre with full flap selected and one person on board. It was found that slight nose down elevator trim was selected, but it could not be determined if this was an impact feature. The wheels, brakes and associated discs were visually satisfactory. The discs had a light tarnish from the use of extinguisher. The left brake functioned when the brake pedal was depressed, however the right brake did not operate due to loss of hydraulic fluid. This was found to be due to internal damage to a flexible hose which had been crushed in the impact. No other defect was found associated with the right brake.

As previously stated, the front seats had both moved forwards in the impact. The seats are normally prevented from moving fore and aft by two pins in each seat which engage in holes in the seat rails, and which can be removed by means of a lever to allow the seat position to be adjusted. The seats are prevented from vertical disengagement from the seat rails by retaining claws. In the case of the unoccupied passenger seat, one pin was bent rearwards with corresponding damage to the rail, and the other pin had no damage. This indicated that at least one of the right seat pins had been engaged at impact, but that the impact forces had been sufficient to force the seat out of engagement, even though it was not occupied. On both seats the claws were still engaged. On the pilot's seat the pins were both bent slightly forwards, not aft, and there was no corresponding damage to the rails. The forwards bending could not have occurred in the impact since it would have required the seat to have been loaded in a aft direction. This forwards bending was attributed to previous careless adjustment of the seat, probably over a period of time. The rails had no damage other than impact damage, except for a very slight 'burr' on the rear edges of holes 5 and 6 (numbering from the front of the rails). Both rails were in fairly good condition, but some wear patterns were evident.

Dimensional checks of the holes were carried out in accordance with the information contained in Airworthiness Directive (AD) 87-20-03 R2, which requires the holes to be measured in the fore and aft plane, 0.020 inch below the surface of the rail. The AD states that the nominal diameter is 0.28 inch and that if the wear dimension exceeds 0.36 inch, the rail must be subject to repetitive inspections. If the wear dimension exceeds 0.42 inch, the rail must be rejected. On the pilot's seat rails the greatest wear had occurred around holes 4, 5, 6 and 7. The diameter of these holes was difficult to measure, due to distortion of the rails in the impact, but the maximum dimension in any direction was less than the 0.36 inch specified in the AD.

A close examination of the geometry of the pins of the left seat showed that they were bent through about 4° in one case and over 6° in the other. They also had conical tapers on the last 0.25 inch, amounting to some 5° taper angle on each side of the pin, and local wear patterns. AD 87-20-03 R2 also showed that the minimum permissible seat pin engagement in the rail was 0.15 inch, after all vertical seat movement is taken into account. As supplied by the manufacturer, the pin engagement would have been in excess of these minimum dimensions, and on the seat in question a total engagement of about 0.31 inch was measured, although this made no allowance for free movement vertically. When the seat pins were inserted in the rails up to the wear marks on the pins, about 0.05 inch of free play was observed in the fore and aft direction. The pin engagement mechanism was found to exert a combined force of around 35 lbs on both pins, to keep them engaged.

Data supplied by the Cessna Aircraft Company showed that the pins fitted to the pilot's seat were of a design which had been changed in 1983. The modified new pins were chamfered on the sides only, so that the 0.15 inch of engagement, as specified in AD 87-20-03 R2, gave good penetration of the parallel edges of the pin into the rail holes. In the light of this information, this AD is not appropriate to seats with pre-1983 pins, as the engagement criteria therein would leave the pins engaged only by their tapered sections. As manufactured by Cessna, the pin engagement (pre-1983) was about 0.31 inch. This allowed only about .063 inch of engagement of the parallel portion of the pin, less any reduction for vertical movement of the seat, and wear.

Examination of other aircraft

Several other Cessna 172 aircraft were examined, including a similar aircraft of the same operator's fleet. On that aircraft it was found that the left seat had a pin which was slightly bent forwards, by perhaps 2°, *i.e.* in a similar direction to the pilot's seat pins on the crashed aircraft. It was also noted that, with the seat normally positioned and the diagonal safety strap adjusted for comfort, a pilot's

head could come very close to the left pillar and windscreen. With the seat slid back until the feet were barely on the rudder pedals, the yoke and throttle could be pushed forward, if the pilot leaned forward, but it could be difficult to reach the flap lever.

Modification action

Cessna Single Engine Service Bulletin SEB 89-2, Revision 2, dated 4 September 1992 and entitled "Pilot seat secondary stop installation" described a modification to fit a secondary seat stop to the pilot's seat. The purpose of this modification stated in SEB 89-2 was as follows:

"The secondary seat stop is designed to assist in providing an additional margin of safety by limiting the aft travel of the seat in the event the primary latch pin is not properly engaged in the seat rail/track. Seat slippage could result in the pilot not being able to reach all the controls and subsequently losing control of the airplane".

This modification restricts free movement of the seat to the rear to a maximum of 4 inches, unless the pilot operates the stop assembly and releases the locking pins together. This Service Bulletin states that compliance is "Mandatory", with embodiment to be accomplished within 400 hours or 12 months, however it is not mandated by the UK CAA. The Service Bulletin also states that "FAA approval has been obtained on technical data in this publication that affects airplane type design"; and "For Reims Aviation Airplanes; DGAC approval has been obtained on technical data in this publication that affects airplane type design." This SEB 89 was originally issued on 14 April, 1989. Revision 1 was issued on 26 October, 1990.

This question of regulatory response to manufacturers' Service Bulletins which strongly recommend modification action on their products also arose during the AAIB Inspector's Investigation of the accident to Piper PA-31-325 C/R Navajo, G-BMGH, which suffered a serious loss of control in flight, due to detachment of its right engine following loss of a propeller blade, and conducted a forced landing 4 nm southeast of King's Lynn, Norfolk, on 7 June 1993 (Aircraft Accident Report 6/94). This 1994 report included the following finding:

(ix) The presence of the fatigue cracking from one of the grease nipples holes in the right propeller hub was not detected during a mandatory visual inspection of this hub 10.35 hours before this accident due to the inadequacy of the visual inspection requirement in FAA AD No 89-22-05. This AD had not been revised to reflect the introduction of eddy current inspection by the propeller manufacturer, or to reflect the latter's strong recommendation to replace such hubs with an improved design.

This report also included the associated Safety Recommendation:

4.3 The CAA and FAA should seriously consider issuing Airworthiness Directives to make manufacturers' strong recommendations to replace components a mandatory requirement where it is apparent that failure to replace such components could result in a potentially major hazard to the safety of affected aircraft.

(Safety Recommendation No 94-30, made September 1994).

Discussion

The lack of damage to the left seat rails and the absence of rearwards bending of the associated pins indicated that the pins had not been properly engaged in the rails at impact. The forward bending found on these pins could not have occurred during the impact if they had been properly engaged. It follows that either (a) something very unusual happened to them during the flight, forcing the seat rearwards or (b) they were bent before the commencement of the flight. The conclusion that the pins were bent before the start of the flight is supported by the similar damage found on the other aircraft in the same fleet. It was considered that the most likely reason for this type of bending was associated with previous adjustment of the seat rearwards, when the pin had been allowed to engage and arrest the aft motion of the seat. This damage may have occurred on a single occasion, or may have accumulated over a period.

It was not possible to determine if the seat pins had been properly engaged during the accident flight. Failure of the seat pins to fully engage is often due to obstruction of the holes, but no evidence of such obstruction was found. If the pilot's seat locking was properly engaged during the flight, the evidence clearly indicated that the associated pins had disengaged, however, before impact. It is relevant, therefore, that the highest loads on the seat can be generated during braking. The loads which a pilot can generate on foot pedals are in the order of several hundred pounds and could be capable of releasing the seat pins, given the engaging force from the springs and the combined taper and bend angles. In view of the unremarkable nature of the flight until the go-around at Compton Abbas, it was concluded that the pilot's seat had moved rearwards during the landing roll. It would thus appear that the pilot was unable to bring the aircraft to a halt in the remaining runway distance available and so initiated a go-around. The subsequent apparent over-pitching of the aircraft would be consistent with his loss of control due to aft displacement of the seat.

In the light of these findings, the following Safety Recommendations are made:

96-84: In order to restrict sudden inadvertent aft movement of pilots' seats on Cessna 172 aircraft with the attendant possibility of over-pitching of such aircraft the CAA, in conjunction with the FAA, should expedite the following:

- (1) re-assessment of the seat track pin engagement dimensional criteria for Cessna 172 aircraft fitted with the pre-1983 type pins and formulation, in conjunction with the manufacturer, of urgent corrective action to achieve safe and reliable seat position locking in service.
- (2) a review of the status of Cessna SEB 89-2 Revision 2 with a view to making the embodiment of the secondary seat stop mandatory, as clearly intended by the manufacturer in this Service Bulletin of 1989.
- (3) alert associated aircraft maintenance engineers of the potential for deflection of seat track locking pins to occur in service and require associated inspection and replacement of any bent pins found pending the outcome of (1).
- (4) alert Cessna 172 pilots of the need for care when adjusting their seat positions on the associated tracks in order to avoid bending of the seat track locating pins.

97-11: The CAA and FAA should seriously consider issuing Airworthiness Directives to make manufacturers' strong recommendations to modify components a mandatory requirement where it is apparent that failure to modify such components could result in a potentially major hazard to the safety of affected aircraft.

