

# Piper PA-28RT-201T, G-BNZG, 20 June 1996

## AAIB Bulletin No: 11/96 Ref: EW/G96/06/29 Category: 1.3

<b>Aircraft Type and Registration:</b>	Piper PA-28RT-201T, G-BNZG
<b>No &amp; Type of Engines:</b>	1 Continental TSIO-360-FB1 piston engine
<b>Year of Manufacture:</b>	1980
<b>Date &amp; Time (UTC):</b>	20 June 1996 at 1044 hrs
<b>Location:</b>	Sleap, Shropshire
<b>Type of Flight:</b>	Private
<b>Persons on Board:</b>	Crew - 2 - Passengers - None
<b>Injuries:</b>	Crew - None - Passengers - N/A
<b>Nature of Damage:</b>	Damage to cowling, nose landing gears doors and propeller
<b>Commander's Licence:</b>	Commercial Pilot's Licence
<b>Commander's Age:</b>	28 years
<b>Commander's Flying Experience:</b>	1,950 hours (of which 120 were on type) Last 90 days - 150 hours Last 28 days - 66 hours
<b>Information Source:</b>	Aircraft Accident Report Form submitted by the pilot

The aircraft was engaged on a circuit training detail with the student handling. The instructor reported that, on the first approach to land, the student was controlling the airspeed well and that he was following a 3° glidepath. He further added that all three landing gear locked-down green lights were illuminated. Touchdown on the main wheels on Runway 05 was gentle at approximately 60 kt and the nose was lowered. However after rolling some 30 metres on all 3 wheels, the crew realised that the nose landing gear was slowly starting to collapse and the propeller contacted the ground.

The instructor took control and shut down the aircraft systems as it rolled to a stop with the nose on the runway. There was no fire and the aircraft was evacuated without difficulty. Upon examination, it was found that the downlock hook (see diagram) had broken and that the roller upon which it engages was badly bent. It was evident that the distorted roller had contacted the exterior surface of the hook and caused its detachment, there being no evidence of pre-existing cracks in the hook.

fitting which was recovered from the runway. It appears possible that the roller may have been bent for some time, but still able to enter the hook. On this occasion it is postulated that it might have rotated and been presented to the hook in an adverse orientation, causing the damage. The maintenance company could not explain how the pin distortion had occurred, but recalled another occurrence on a different aircraft where a stone, or a piece of concrete, had lodged in the mechanism and led to a similar effect.

Since the detached part of the hook contained the striker plate for the microswitch controlling the green downlock light, it appears that the hook must have been in its correct orientation during the final approach, although possibly close to failure. A pilot on the previous flight of this aircraft reported that he did notice that the nose gear green light momentarily went out during taxiing, but as it had re-appeared he did not think it worthy of comment.