
Department for Transport

AAIB Bulletin S2/2006

SPECIAL

ACCIDENT

Aircraft Type and Registration:	Socata TB10, G-BNRA
No & Type of Engines:	1 Lycoming O-360-A1AD piston engine
Year of Manufacture:	1987
Date & Time (UTC):	16 February 2006 at 1120 hrs
Location:	Nottingham Airport (Tollerton), Nottinghamshire
Type of Flight:	Training
Persons on Board:	Crew - 2 Passengers - None
Injuries:	Crew - None Passengers - N/A
Nature of Damage:	Propeller blade shed; propeller and drive flange separated from engine; crankcase damaged and engine partly separated from mounting structure
Commander's Licence:	Commercial Pilot's Licence
Commander's Age:	41 years
Commander's Flying Experience:	2,198 hours (of which 10 were on type) Last 90 days - 90 hours Last 28 days - 30 hours
Information Source:	Aircraft Accident Report Form submitted by the pilot; debris plot made by the maintenance company; photographs of damaged aircraft; examination of failed propeller components and of maintenance documentation by AAIB.

This bulletin contains facts which have been determined up to the time of issue. This information is published to inform the aviation industry and the public of the general circumstances of accidents and must necessarily be regarded as tentative and subject to alteration or correction if additional evidence becomes available.

Extracts can be published without specific permission providing that the source is duly acknowledged.

Synopsis

During a touch and go landing, as power was applied a propeller blade detached. The resulting imbalance caused both the crankshaft to fracture (allowing the propeller to be released) and the engine to partly separate from the structure. Metallurgical examination indicated the presence of fatigue in the propeller hub. The location and nature of the fatigue was similar to that described in an existing Service Bulletin, however that document has not yet been classified as mandatory by the FAA. Three Safety Recommendations are made.

History of the flight

The pilot reported that during a touch and go landing, as he applied full power smoothly for takeoff a loud bang was heard, the propeller detached and the engine shook from its mountings. He brought the aircraft to a halt maintaining it level despite asymmetric effects.

Engineering investigation

Analysis of the photographs provided to the AAIB confirmed that the engine had partly separated from the aircraft structure and had become re-orientated both in plan and in side elevation at angles between 30 and 40 degrees to the normal location (Figure 1). The two bladed, constant speed propeller was absent. It was found with one blade missing, alongside the runway close to the point at which the aircraft came to a halt. The missing blade was on the other side of the runway closer to the touch-down point. Two depressions in the paved surface indicated where propeller debris had impacted with considerable force.

This model of propeller is of the variable pitch type in which the blades are located by thrust bearings within a two piece hub (See Figure 2). The hub components consist of an aft casing bolted to the drive flange of the

crankshaft and a forward casing upon which is mounted the cylinder and piston of the pitch change mechanism. The two casings are secured together by a series of bolts whose axes are parallel to that of the crankshaft. The plane of the joint between forward and aft casings coincides with the axes of the blade pitch change bearings.

Examination of the separated components indicated that the engine crankshaft had fractured close to its forward end, as had part of the crankcase casting in which it was located. The isolated blade appeared to have been released as a result of the fracture of part of the hub which carried a blade pitch change bearing and hence the centrifugal blade force.

Examination of the crankshaft fracture face revealed that its condition was consistent with the effects of bending load and exhibited no evidence of fatigue or corrosion. The fracture of the crankcase casting also appeared to have occurred as a result of overload. The hub was dismantled to enable its fracture faces to be



Figure 1

examined under laboratory conditions (Figure 3). It was noted that the pitch change bearing of the blade which remained attached was fully charged with grease, whilst




Figure 2 (left)
Schematic view of propeller hub with separated portion shown in red

those components of the bearing securing the separated blade, recovered from the proximity of the accident site, indicated a marked lack of lubrication.

Initial metallurgical examination of the fracture faces of the hub indicated that although the fracture of the aft section of the casing appeared to be in simple overload, the forward section had a more complex failure mechanism which included some fatigue.

Service Bulletin information

The manufacturer's Service Bulletin HC-SB-61-269 drew attention to '*numerous occurrences of hub fillet cracks, including incidents of in-flight blade separation in Hartzell two blade "compact" series aluminium hub*



Figure 3
Hub fracture faces

propellers'. The failed propeller on G-BNRA was of the type to which this problem applied. The Service Bulletin noted that cracks were typically discovered during inspection following reports of abnormal vibration or grease leakage. The Service Bulletin required visual and eddy current inspection of fillet radii in the general area where unusual fracture surface conditions were observed on G-BNRA. Inspection was to be carried out within 50 flying hours of the receipt of the bulletin and repeated at 100 hour intervals.

The Service Bulletin was issued in April 2005 and the records show that the aircraft had completed approximately 105 hours operation between the end of that month and the date of the accident. There was no indication that the Service Bulletin had been implemented on this propeller.

The aircraft was maintained by a M3 maintenance organisation in accordance with the CAA/LAMS/A schedule which uses a 50 hour/150 hour/annual cycle of inspections. They confirmed that Service Bulletin HC-SB-61-269 had not been implemented on the propeller. During normal aircraft scheduled inspections specific work on the propeller is limited to a general examination and implementation of any applicable Airworthiness Directives. This is the normal procedure for M3 organisations. Eddy current inspection equipment and appropriate expertise is not required and not normally possessed by such organisations.

The Service Bulletin notes that 'Regulatory action is expected'. So far this Service Bulletin has not been the subject of such action. At present, therefore, the Service Bulletin is not mandatory.

The similarity of the position of the unusual fracture face on the hub to the area highlighted in the Manufacturer's Service Bulletin, as well as the absence of grease from the pitch-change bearing of the separated blade, strongly suggest that the failure was of the type which the Service Bulletin is intended to address. The absence of an Airworthiness Directive on the subject has inhibited the ability of maintenance companies and operators to identify the propellers at risk of blade loss and to take steps to prevent such hazardous accidents from occurring.

Safety Recommendation 2006-046

It is recommended that the CAA take immediate action to alert M3 organisations and other relevant maintainers in the UK to the existence and importance of Hartzell Service Bulletin HC-SB-61-269.

Safety Recommendation 2006-047

It is recommended that the FAA take urgent steps to issue an Airworthiness Directive making the inspection requirements of Hartzell Service Bulletin HC-SB-61-269 mandatory.

Safety Recommendation 2006-048

It is recommended that the EASA take urgent steps to issue an Airworthiness Directive making the inspection requirements of Hartzell Service Bulletin HC-SB-61-269 mandatory.