

Agusta Bell 206B, G-BFJW

AAIB Bulletin No: 9/97 Ref: EW/C96/12/2 Category: 2.3

Aircraft Type and Registration:	Agusta Bell 206B, G-BFJW
No & Type of Engines:	1 Allison 250-C20 turboshaft engine
Year of Manufacture:	1973
Date & Time (UTC):	16 December 1996 at 1920 hrs
Location:	Private landing site, Ledbury, Herefordshire
Type of Flight:	Private
Persons on Board:	Crew - 1 - Passengers - 2
Injuries:	Crew - 1 fatal - Passengers - 2 fatal
Nature of Damage:	Helicopter destroyed
Commander's Licence:	Airline Transport Pilot's Licence (Helicopters and Gyroplanes)
Commander's Age:	66 years
Commander's Flying Experience:	13,700 hours approximately (of which over 2,000 hours were on type) Last 90 days - Not known Last 28 days - Not known
Information Source:	AAIB Field Investigation

History of Flight

On the morning of the accident, the pilot left his home near Andoverat approximately 1100 hrs and drove to Bournemouth Hurn Airport where the helicopter was hangared. At about 1330 hrs he flew to the operator's warehouse facility at Ledbury with two senior company executives as passengers. After a 30 minute stopover the helicopter flew to the private home of the owner and chief executive of the company with the owner himself and another senior company executive on board in addition to the original two passengers. This flight was over a distance of approximately five miles and they arrived at the house at 1530 hrs.

The landing area at the owner's home was an unmarked lawn oriented north to south and approximately 35 metres long by 20 metres wide situated at the rear of the house. Tall fir trees lined the western and northern sides of the lawn, and the three storey house was on the eastern side. To the

south the ground sloped away downhill with trees some 80 metres from the edge of the lawn. There was no lighting on the landing area; some illumination came from the room lighting within the house. Because of the obstacles around the lawn, the approach had to be made from the south; the helicopter was then turned in a low hover and left to face south in preparation for the next departure which would also be to the south. A strong southerly wind would preclude use of the landing site.

For the next 3 1/2 hours, the pilot waited while his passengers were involved in a company business meeting. At 1900 hrs, having confirmed that the weather was suitable for the return flight to Bournemouth, the pilot and his two original passengers went out to the aircraft. After the engine had been started and therefore the rotor was turning, the passenger occupying the front left seat remembered that he had left his overnight bag in the house and went back to collect it. When he returned to the helicopter, he put his bag on the rear seat beside his colleague and then strapped himself into the front passenger seat. The helicopter then took off.

The company owner and the remaining executive watched the departure of the helicopter from a ground floor room which looked out directly onto the lawn. The helicopter was seen to climb in the hover to a height of about 20 feet. The anti-collision light, strobe and landing lights were 'ON'. They then saw it move slowly backwards and upwards until one of the main rotor blades was heard to hit a tree. The force of this collision caused the rotor to detach itself and the helicopter was turned and thrown rearwards. The main rotor and the top of the tree were found on the lawn and the helicopter with its occupants still strapped in, was found in the tennis court on the other side of the trees.

One of the eyewitnesses went immediately to the crash scene while the other telephoned for the emergency services. The front seat passenger was found to be dead but the pilot and the rear seat passenger were still alive but unconscious. The first eyewitness to reach the aircraft noted that the anti-collision light was still operating although the landing light was not illuminated. He then opened the forward right hand door and switched off the battery switch and shut off the fuel. He was aware that the fuel had already drained out across the tennis court. There was no fire.

Recovery of the occupants.

Shortly afterwards, the local fire service arrived and after some discussion as to the dangers inherent in the site due to the spilled fuel, one of the firemen assisted the owner in supporting the rear seat passenger who was suspended by his seat harness. Some 10 minutes later the police and ambulance crew also arrived at the scene. After further discussion of the fuel spillage, the pilot was removed from the aircraft. To do this the forward instrument console was broken and pulled clear and he was lifted out through the remains of the front windscreen. He died shortly afterwards without regaining consciousness. The rear seat passenger was then removed in turn. To achieve this the owner stood in the rear section of the helicopter, having first removed a flight bag, and provided support as he was lifted clear. It is believed that this passenger died at about this time.

The crash occurred at approximately 1920 hrs and the telephone call to the emergency services was made almost immediately afterwards. The police were notified by the ambulance service at 1923 hrs. Two fire engines arrived at 1945 hrs followed by the first of four ambulances about 10 minutes later.

Meteorological Information

The Meteorological Office produced the following aftercasts;

At 1700 hrs the synoptic situation showed a light, southerly airstream established over the area. Weather was probably nil although the airstream was producing occasional light rain and drizzle in places. Visibility was about 6 km, QNH 1010 mb, cloud was one to two octas with a base of 1,000 feet, three to seven octas with a base of 1,500 to 2,000 feet, and five to seven octas with a base of 3,500 feet. The surface wind was 160_ /5 kt or less and the temperature was 7_C and the dewpoint 5_C.

By 1900 hrs the weather had changed slightly. Cloud had increased to become scattered to broken cover at 1,000 feet (three to seven octas) and the surface wind had backed slightly to 140_ at 5 kt.

Pilot's experience

The pilot operated in a self-employed freelance capacity and the flight was conducted as a private flight. He was well known and respected for his experience and ability. He had operated into this particular landing site for a number of years and had designed and constructed a visual landing aid which he used to assist him during his approach. This was set up on the lawn close to the north western corner.

His most recent medical examination by a CAA authorised medical examiner had taken place on 1 July 1996 and had included an electrocardiogram and an audiogram. He was found fit at that time and the only restriction to his Class One medical certificate was the mandatory use of correcting spectacles which he was wearing at the time of the accident. The audiogram confirmed a condition of marked high tone deafness in both ears which had been observed some years previously. This hearing loss was at the limit allowable under the International Standards and Recommended Practices which are detailed in Annex 1 (Personnel Licensing) to the Convention on International Civil Aviation for the issue of a class one medical certificate.

Although it has not been possible to locate the pilot's flying log book which would confirm the exact detail of the flying carried out by him immediately prior to the accident, it has been possible to ascertain that his workload was not high and that he appeared to be fit and was well rested.

Examination of the wreckage

Both main rotor blades struck the trunk of a fir tree located approximately 35 metres behind and 8 metres to the right of the take off point, at a height approximately 22 metres above ground level. These strikes produced two successive parallel cuts through the full thickness of the trunk, causing separation of the outermost parts of both blades at positions approximately 1.0 and 1.5 metres respectively from the tip. The residual energy of these separated parts was sufficient to throw them distances in excess of 300 metres. The rotor mast was wrenched heavily forward during the blade strikes, breaking out the main gearbox lower attachment and rotating the mast and gearbox casing forward and downward in its mounting, through approximately 40°; the mast then fractured, and the rotor fell to the ground adjacent to the tree. The direction of main gearbox/mast wrenching was consistent with the blade strikes having occurred in the left rear quarter of the rotor disc, with the aircraft travelling rearward and to the right, in a substantially level attitude, when the blade strikes occurred. Severe in-plane bending deformation was evident on both outer blades which, together with the damage sustained by the tree and the residual energy left in the separated tip sections, was consistent with a high degree of main rotor energy at the time of the strikes.

In light of the significant rotor energy evident at the time of the tree strikes, and having regard to the overall circumstances of the accident (which was not consistent with a loss of

power), examination of the engine was limited to a visual examination together with a specific check for possible loosening of the "B" nuts in the air signal lines to the fuel control unit, all of which proved negative.

The flying control operating systems were examined very closely for evidence of a possible control restriction or malfunction. Each of the linkages between the main rotor blade pitch horns and the swash plate had fractured in overload, consistent with the forces of the tree strikes and the subsequent ground impact. No evidence of obstruction or disconnection was found in the mechanical circuits between the pilot's controls and the main rotor hydraulic actuators, nor in the yaw control circuit or the interconnecting circuits between the pilot's and co-pilot's controls. No pre-impact defects or disconnections were evident in the tail rotor drive shafts and couplings. The tail rotor gearbox was undamaged and turned freely, and the tail rotor blade bearings and pitch links were all undamaged and serviceable.

All of the three hydraulic power actuators were intact but their mountings had fractured in the accident, and the output links to the swash plate were broken. The actuators themselves, however, suffered no significant damage and were function tested by the AAIB at an approved overhaul agency. These tests confirmed that each power actuator was serviceable. With the exception of minor rigging errors attributable to slight impact distortion of the input linkages, each unit operated within the manufacturer's tolerances.

The hydraulic system filter was unobstructed and contained no significant debris. The combined hydraulic reservoir and pump, which is mounted on the forward face of the main gearbox, had been driven downward when the gearbox moved during the tree strikes, partially breaking through the cabin roof and fracturing the pump drive shaft and casing. The reservoir itself was found to be empty, but the aircraft had fallen onto its left side and the reservoir contents would have been expected to drain down onto the ground and to have become mixed with fuel from the ruptured main fuel tank. In addition, several of the flexible hydraulic lines from the reservoir and pump had become trapped between the cabin roof and parts of the main gearbox when the latter was wrenched forward in the accident, severing these lines and providing further potential for fluid loss. A strip examination of the hydraulic pump revealed no evidence of any pre-impact failure or malfunction.

Possible disturbance during the rescue attempts rendered the post-accident positions of switches and controls in the cockpit unreliable. No clear evidence of filament stretching (indicating an illuminated condition), was found on any of the warning caption bulbs on the instrument panel. The panel had not been subject to severe impact forces and consequently the absence of stretching does not, in itself, rule out totally the possibility that one or more warning captions may have been illuminated at the time of impact. The instrument panel lighting filaments also showed no evidence of hot stretching, but similar comments apply. Examination of the two landing light filaments did reveal some evidence of stretching on the filament from the forward lamp, raising a possibility that this filament may have been illuminated at impact; however, the amount of stretching was very slight, and no reliable conclusion could be drawn. The filament from the rear lamp displayed no evidence of stretching, and it is probable that this lamp was not illuminated at impact.

All four doors were examined in detail for evidence of latch engagement and door position at impact. From the pattern of deformation to the doors and frames, and to the internal components of the latch mechanisms, it was possible to confirm that each of the doors had been closed fully, with the latch engaged, at the time of impact.

Analysis

Correlation of the statements by the two eyewitness indicate that the helicopter was flown in a controlled manner up to the time of the accident and that the pilot had commenced a transition to forward flight by tilting the rotor disc forwards. Apparently, this was not done sufficiently to prevent the helicopter drifting backwards until it hit the trees. This failure to tilt the rotor disc sufficiently to complete the transition could be interpreted as a simple misjudgement on the part of the pilot, however his experience and ability would suggest that this was unlikely. Two other possibilities are either that the pilot was subjected to a distraction at the time of transition to forward flight such that he was unaware of the rearwards movement of the aircraft or that he was unable to visually assess that movement.

Examination of the wreckage has failed to provide any evidence to support the theory of distraction. The pilot and his passengers were all correctly strapped in. The only baggage within the passenger compartment was a large briefcase which was secure and the aircraft doors showed no evidence of being unfastened prior to the accident. No technical defect was found with the helicopter. Post-mortem examination of the pilot showed that he was fit and well. Any lesser distraction should have been well within the competence of this pilot to cope with while completing a safe departure.

The towering transition technique for take-off from a restricted area at night is a difficult manoeuvre which requires experience and skill. It is the recommended technique in these conditions. The pilot was aware of the difficulties presented by the site to the extent that he had spent some of his spare time designing and building an approach aid in the form of a pair of metal indicator boards. These were placed at the back of the site and were routinely used by him to assist in his judgement of his descent during the approach. Visual assessment of the descent was made more difficult by the slope of the ground up towards the landing site.

The helicopter landing light was switched 'ON' for the take-off and was found to be unbroken and not lit after the accident. It was customary for the pilot to switch 'OFF' the landing light shortly after take off. The landing area was not directly lit or marked. The only illumination was provided indirectly by the lighting within the rooms of the house. The effect of switching 'OFF' the landing light at about the time of transition to forward flight might have been to cause the pilot to lose some visual acuity until his eyes became accustomed to the dark. It was a dark night with considerable cloud cover and the lights of the house would at that time have been positioned below the helicopter and on the side away from the pilot and therefore out of his field of view. The effect of such a lack of visual clues would be to exacerbate the difficulty the pilot would have had in appreciating the rearward drift of the helicopter, possibly caused by the wind, in what was a very confined area.

Safety Recommendation

Article 90 paragraph 4 of the Air Navigation (No 2) Order states that "the person in charge of any area in the United Kingdom intended to be used for the taking off or landing of helicopters at night".... "shall cause to be in operation".... "such lighting as will enable the pilot of the helicopter:

- (i) in the case of landing, to identify the landing area in flight, to determine the landing direction and to make a safe approach and landing; and
- (ii) in the case of taking off, to make a safe take off."

Article 90 does not apply in the case of this accident solely because the flight was not being conducted for the purpose of the public transport of passengers. Nonetheless, the standard of safety referred to is desirable in all circumstances, especially as in the case of a corporate transport flight such as this, the only reason it is not defined as a public transport flight is because the passengers were not fare-paying but were present onboard by virtue of their employment.

In the circumstances pertaining to this accident, it is possible that the provision of touchdown and lift-off area marking and lighting, to the standard described in ICAO Document 9261 and which in turn would have met the requirements of Article 90 of the Air Navigation (No 2) Order, might have provided the pilot with sufficient outside reference to assess the rearward movement of his helicopter and therefore might have prevented the accident.

As a result of the investigation into an accident involving a privately operated Agusta A109 helicopter which occurred on 27 June 1990, (AAIB reference EW/C1168 published in Bulletin 11/90), the AAIB recommended to the CAA that 'consideration be given to a suitable form of safety audit which would monitor private operators. It is suggested that the British Helicopter Advisory Board (BHAB) might be invited to produce a Code of Conduct for Corporate helicopter operators with the intention that corporate managements would monitor their flight operations more closely in future.' In its closure of the recommendation, in April 1991, the CAA responded: 'The regulation of corporate operations had been under consideration by the Authority prior to this accident; its proposals, one of which was the need for an operations manual, were subsequently endorsed by the Operations Advisory Committee. However, the advent of JAA regulations which override national legislation has made further work on this subject nugatory. The Authority however will represent these views in the appropriate JAA working group tasked with devising rules for regulation of Corporate Transport Operations'.

JAR OPS 4, not yet in draft and for which no promulgation date is currently forecast, intend to deal with General Aviation operations by helicopters, which includes the corporate sector. In the meantime some safety oversight by the national aviation authority (CAA), without prejudice to the JAA's intentions, is considered essential. The following recommendation has therefore been made to the CAA:

Recommendation 97-22

The CAA should re-examine the recommendation made as a result of the accident to Agusta A109 helicopter, which occurred on 27 June 1990 with a view to producing guidance material, such as a Code of Conduct, for Corporate helicopter operators which should take into account all those aspects of public transport operations referred to in the Air Navigation (No 2) Order which are appropriate to a minimum safety standard for corporate operators.