

Piper PA-38-112, G-BOYT, 27 May 1996

AAIB Bulletin No: 8/96 Ref: EW/G96/05/20 Category: 1.3

Aircraft Type and Registration: Piper PA-38-112, G-BOYT

No & Type of Engines: 1 Lycoming O-235-L2C piston engine

Year of Manufacture: 1981

Date & Time (UTC): 27 May 1996 at 1100 hrs

Location: Bangor University Farm Land, Abergynngregyn,

North Wales

Type of Flight: Private

Persons on Board: Crew - 1 Passengers - 1

Injuries: Crew - None Passengers - None

Nature of Damage: Damage to left wing, propeller and noselanding gear

Commander's Licence: Private Pilot's Licence with IMC and Night Ratings

Commander's Age: 42 years

Commander's Flying Experience: 210 hours (of which 136 were on type)

Last 90 days -6 hours

Last 28 days -6 hours

Information Source: Aircraft Accident Report Form submitted by the pilot and examination of the aircraft's engine by AAIB and Lycoming

During a flight from Liverpool to Caernarfon at 2,000 feet, when at a point approximately 5 nm east of Bangor, the pilot heard an unusual noise from the engine. Within a few seconds, this noise and an attendant vibration had increased in intensity to such an extent that the pilot could no longer read the instruments, and so he decided to shut the engine down. Faced with few options for a suitable place to conduct a forced landing, he landed in a field approximately 300 yards in length but, despite the application of brakes, failed to stop before striking a dry stone wall at a speed of approximately 20 mph. The occupants, who suffered minor injuries, evacuated the aircraft unaided, whereupon it became apparent to them that the field was waterlogged.

After recovery, the engine was partially stripped by a maintenance engineer. It was apparent that the No 3 big end bearing had failed, releasing the connecting rod from the crankshaft, and that the No 4 bearing showed signs of having been extremely hot. The engine was then transported to the AAIB at Farnborough where a complete strip examination was carried out. It was established that all damage within the engine had occurred due to a lack of lubrication, despite sufficient oil reportedly being present in the sump immediately after the accident. A strip examination of the oil pump, however, revealed a pre-accident failure.

Oil is supplied under pressure to the rotating elements within the engine from a gear pump at its rear, driven directly by the crankshaft. The pump has two gears, a 'driven' gear and an idler gear, within a close tolerance housing. As the gears mesh when rotating, their action draws oil from the sump by entrapment between the cavities formed between the gear teeth and the housing, and pass it on to the oil gallery under pressure. The strip examination revealed that the driven gear had suffered a single transverse failure between two teeth and was jammed in the housing by a section of the idler gear, which had broken into several sections. Detailed metallurgical examination revealed the following:-

the transverse failure on the driven gear had resulted from a tension fatigue mechanism, initiation having occurred along the root of one tooth. All other failures had occurred due to overload.

both gears were made from iron and had been manufactured by a sintering process.

all thrust faces on both gear teeth were pitted and heavily worn, to such an extent that the meshing teeth could 'hook' together and induce high tensile stresses at the root of each tooth.

This type of oil pump failure involving sintered iron gears has been a known problem affecting a wide range of Lycoming four and six cylinder engines since 1970. Early problems with excessive wear led to Service Bulletins 381 and 385, which changed the Woodruff key drive to a 'flat' shaft drive for the driven gear, but which retained sintered iron gears. This was mandated by FAA Airworthiness Directive (AD) 75-08-09 which, as with all FAA AD's, applied to UK registered aircraft and this was the standard of oil pump on the subject Lycoming O-235 engine. Further problems involving sintered iron gears led to FAA AD 81-18-04, which essentially formalised manufacturer's Service Bulletin 456 (1981), which itself was revised in 1993 to SB 456F, the intention being to remove sintered iron gears from all specified engines and replace them with steel components. FAA AD 81-18-04 called for compliance with SB 456 (or an FAA approved revision or alternate), at "2000 engine hours since new or last overhaul, whichever is later, or whenever the accessory section is removed". In September 1995, mandatory Service Bulletin 524 was issued by the manufacturer and superseded a range of SBs, including SB 456F, relating to the replacement of sintered iron impeller-gears. Compliance time was stated as "within 25 hours of operation for engines which have sintered iron impellers (gears) and have not complied with any revisions to SB's 454, 455 or 456". This Bulletin states that sintered iron gears can be identified by a porous surface finish on the gear faces, but this was not readily apparent on the subject gears as both appeared to have a machined finish on these faces. G-BOYT was imported from the USA in July 1988, with the subject engine installed. Just prior to export, the engine had been overhauled after reaching 2032 hours total time, its American log book recording the fact that all FAA AD's up to 88-14 had been checked and that, amongst many other new parts, new oil pump gears had been installed. No reference was found to gear part numbers and it appeared that the overhaul had been carried out by a licensed mechanic, rather than by the manufacturer or specialist overhaul organisation. At the time of the accident, the engine had accumulated some 2385 additional hours.

Examination of the UK log book for this engine showed that the only reference to the oil pump was that AD 81-18-04 had been complied with an overhaul, this entry being dated 11 October 1988.