

Aerospatiale AS355F1, G-WIRE

AAIB Bulletin No: 11/97 Ref: EW/G97/09/02 Category: 2.2

Aircraft Type and Registration:	Aerospatiale AS355F1, G-WIRE
No & Type of Engines:	2 Allison 250-C20F turboshaft engines
Year of Manufacture:	1984
Date & Time (UTC):	9 September 1997 at 1520 hrs
Location:	Aber Gorge, North Wales
Type of Flight:	Aerial Work
Persons on Board:	Crew - 1 - Passengers - None
Injuries:	Crew - None - Passengers - N/A
Nature of Damage:	Extensive to main rotor blades, mast assembly and right-hand landing skid and to National Grid power-line
Commander's Licence:	Airline Transport Pilot's Licence (Helicopters)
Commander's Age:	47 years
Commander's Flying Experience:	8,045 hours (of which 4,034 were on type) Last 90 days - 123 hours Last 28 days - 49 hours
Information Source:	Aircraft Accident Report Form submitted by the pilot and further AAIB enquiries

The helicopter was being used in support of a power-line refurbishment project in North Wales. It had returned to a site adjacent to a power-line tower (pylon) to collect an underslung load of insulators measuring 3.5 metres in length and weighing 700 kg. This was the second pick-up from the location at which the weather was clear, with visibility of more than 20km, scattered cloud at 2500 feet, and a north-westerly to northerly wind of 15 kt. The insulators had initially been positioned on the other side of the tower but had been moved at the commander's request to give better access and take-off route.

The commander positioned the helicopter with the aid of a marshaller standing approximately 100 metres to the front whilst the ground party connected the load to the 10 metres strop attached to the load hook. At this stage the helicopter was about 15 metres from the tower on a heading parallel to the power-line with the wind from 1 o'clock to 3 o'clock. It was below the level of the

bottom power cables but a vertical lift would have kept it clear of the cables after which the normal procedure would have been to depart with a right turn to the north. The commander assessed that the wind was a steady 15 kt at this time, as had been the case on the earlier pick-up, although gusts to 25 kt had been forecast.

A vertical lift was commenced but, with the load clear of the ground and as the commander was about to begin the transition to forward flight, there was a gust of wind which moved the helicopter to the left. The commander countered with right cyclic but the load had by this time swung to the left which had the effect of moving the helicopter, which was still climbing, further to the left. The commander increased the right control input but the rotor blades struck and severed the bottom power cable.

Vibration and noise were not too severe and control was retained so the commander was able to move the helicopter forward and right. He jettisoned the load clear of all ground crew, and completed a run-on landing after which he shut-down the engines and stopped the rotors normally.

The commander stated that the accident was due to an isolated gust of wind and acknowledged that the load may have been positioned too close to the tower and cables. A nearby Royal Air Force Station confirmed that gusts to 25 kt had been recorded at the time of the accident. The operator's procedures have since been revised to require greater load clearances from obstacles.