

# **Boeing 747-136, G-BBPU**

**AAIB Bulletin No: 6/98 Ref: EW/G98/02/05Category: 1.1**

<b>Aircraft Type and Registration:</b>	Boeing 747-136, G-BBPU
<b>No &amp; Type of Engines:</b>	4 Pratt & Whitney JT9D-7A turbofan engines
<b>Year of Manufacture:</b>	1974
<b>Date &amp; Time (UTC):</b>	8 February 1998 at 0001 hrs (1901 hrs local)
<b>Location:</b>	On take off from J F Kennedy Airport, USA
<b>Type of Flight:</b>	Public Transport
<b>Persons on Board:</b>	Crew - 18 - Passengers - 220
<b>Injuries:</b>	Crew - None - Passengers - None
<b>Nature of Damage:</b>	Landing Gear Bay
<b>Commander's Licence:</b>	Airline Transport Pilot's Licence
<b>Commander's Age:</b>	48 years
<b>Commander's Flying Experience:</b>	13,483 hours (of which 644 were on type) Last 90 days - 185 hours Last 28 days - 55 hours
<b>Information Source:</b>	Aircraft Accident Report Form submitted by the pilot plus telephone enquiries

The Boeing 747's main landing gear trucks (bogies) must be tilted before gear retraction to allow the gear to fit into the retraction wells. A lever latch prevents the landing gear lever from being moved to the UP position until all the TILT sensors indicate that the trucks are tilted. However, the lever latch can be manually moved allowing the gear to be retracted in an emergency. Annunciator lights on the flight engineer's panel provide additional indications of gear, door and truck tilt status.

The aircraft was departing from Runway 13L which requires a low-altitude turn at 300 feet agl to avoid a noise sensitive area. After lift-off the commander, who was handling, instructed the co-pilot to raise the landing gear whilst concentrating on flying an accurate turn at night. The co-pilot attempted to raise the gear lever but it would not move up beyond the OFF position because the latch was engaged. Without consulting the commander, the flight engineer, or the aircraft manuals, the co-pilot immediately withdrew the gear lever latch and raised the gear lever to the UP position.

The landing gear retracted but one red gear light remained ON and one gear door stayed open. The commander decided to climb to medium altitude, jettison fuel, lower the landing gear and return to JFK airport. The landing was uneventful and before clearing the runway the aircraft was inspected and the gear downlocks fitted before it was taxied to the stand.

The co-pilot had initially been unable to raise the landing gear lever because one of the mainwheel trucks had not tilted sufficiently to trigger the TILT sensor. Consequently, this leg did not fully retract and it damaged the gear bay.

The co-pilot was very experienced and could not explain why he reacted as he did, which was out of character. The commander thought that the crew headsets may have been a small contributory factor. The crew were wearing ANR (Active Noise Reduction) headsets which, although they reduce ambient noise, apparently make it more difficult for crew members to hear each other on intercom. The operator is aware of this problem and is conducting trials of a different type of ANR headset.