

# BAC One Eleven 510ED, G-AVMH

## AAIB Bulletin No: 2/97 Ref: EW/C96/5/6 Category: 1.1

<b>Aircraft Type and Registration:</b>	BAC One Eleven 510ED, G-AVMH
<b>No &amp; Type of Engines:</b>	2 Rolls-Royce Spey 512-14E engines
<b>Year of Manufacture:</b>	1968
<b>Date &amp; Time (UTC):</b>	19 May 1996 at 1532 hrs
<b>Location:</b>	100 nm Southeast of Dublin
<b>Type of Flight:</b>	Public Transport (positioning)
<b>Persons on Board:</b>	Crew - 5 - Passengers - None
<b>Injuries:</b>	Crew - None - Passengers - N/A
<b>Nature of Damage:</b>	None
<b>Commander's Licence:</b>	Not relevant
<b>Commander's Age:</b>	Not relevant
<b>Commander's Flying Experience:</b>	Not relevant
<b>Information Source:</b>	AAIB Field Investigation; Information supplied by the Irish Department of Transport, Energy and Communications, the Operator, and the Operator's Maintenance Contractor

The aircraft had been undergoing a major service following its acquisition from another operator. Upon completion of the maintenance work, the aircraft was positioned from its home base, Hurn, to Stansted in preparation for its introduction into service. This positioning flight was also programmed to include checks of the flying controls manual reversion system, and general handling checks.

During climbout from Hurn, the No 1 air system temperature rose through 210° C and thereafter continued to rise until it was registering maximum on the temperature gauge (approximately 300°C). A strong *hot paint* smell also became apparent. No air conditioning system failure captions illuminated. The No 1 air system was isolated, and the temperature started to fall; when the system was reset, however, the temperature rose again and the No 1 system was therefore shut down for the remainder of the flight.

The crew climbed the aircraft to approximately flight level (FL) 190 above cloud, and the manual reversion and handling checks were completed satisfactorily. They then called the company's maintenance base to request instructions regarding the air system overheat, and were asked to continue to Stansted where an associated maintenance organisation could carry out a change

of the No 1 system air temperature control valve (TCV), which is located in the air supply to the air conditioning pack, just downstream from the engine off-take.

Upon arrival at Stansted, it was found that the maintenance organisation did not have the correct TCV in stock. They nevertheless carried out checks in an effort to confirm the source of the problem. No fault could be found, and the aircraft was returned to service as originally planned. After boarding the passengers, the crew requested clearance to carry out power checks at the end of the runway prior to take off, with a view to checking for any recurrence of the air system overheat. During these checks, the No 1 air system temperature again increased above normal and the aircraft was therefore taxied back to the stand where the passengers were disembarked for transfer onto alternative flights. The aircraft was then positioned back to Hurn using the No 2 air system only, with no further problems becoming apparent. At Hurn, the No 1 system TCV was changed and maintenance personnel satisfied themselves that the cause of the overheat had been cured. (A defect investigation of the TCV subsequently revealed that one of the actuator motor bearings within the unit had partially seized, a fault likely to cause intermittent operation of the actuator).

After the TCV had been changed, the aircraft was re-scheduled to position to Connaught (Knock) Airport, with a cabin crew, to take up the scheduled service which it had originally been planned to operate from Stansted. The take-off from Hurn was normal, but during climbout the No 1 cabin attendant came forward to report a *hot* smell in the rear cabin, which by that time was also becoming evident on the flight deck. The flight crew were busy at this time, but they did check the air system temperature indications and noted that they were normal. Shortly afterwards, the first officer went back into the cabin where he noted a slight haze in the cabin atmosphere. However there was still no indication of any air system over-temperature at this stage, and it was concluded that the problem was most probably caused by the dissipation of residues in the air system, originating from the previous overheat. However, later in the flight, approximately 100nm Southeast of Dublin, one of the cabin crew came onto the flight deck and reported that the other cabin crew members were feeling unwell, and were using oxygen. She had not been so badly affected, but had been working in the galley whereas the others were in the cabin. The commander decided to divert into Dublin, partly on safety grounds and partly because of the engineering support available there. The aircraft was descended below 10,000 feet and depressurised, and the ram air valve opened.

Approximately 10 minutes afterwards, at approximately 210 kt and at an altitude of between 3,000 feet and 5,000 feet, the cabin crew came forward and reported a very strong smell of fuel in the rear cabin. The landing approach was continued, and the aircraft touched down without further problems. Once on the ground, the direct vision windows and main cabin door were opened at the first available opportunity in order to ventilate the interior.

Subsequent investigation at Dublin by the company's maintenance contractor, overseen by an Aeronautical Officer from the Irish Department of Transport, Energy and Communications, identified a steady dripping of fuel from a coupling in the main low pressure feed pipe to the No 2 engine, at a point where it passed through the right main landing gear bay. This coupling was in an inaccessible position adjacent to the landing gear attachment to the structure, and had not been subject to any disturbance during the maintenance work which had recently been carried out on the aircraft. Upon dismantling the coupling (an *Avery* type, commonly found on aircraft of this vintage), the large rubber sleeve which forms the seal between the two pipe sections was found to have deteriorated; after replacement of this seal, the joint no longer leaked. A few beads of fuel were also noted on the attachment bolts of the centre tank transfer pump. This leak was cured by replacement of the flange seal.

Functional checks of the air system failed to reveal any tendency to overheat, but when the TCV contact breaker was pulled to simulate a TCV failure, thereby inducing an over-temperature condition in the No 1 air system, the over-temperature thermostat failed to operate. Further investigation revealed that this fault was caused by an intermittent contact in the connection between the wiring and the plug pins at the thermostat connector.

### **Cabin air system**

Air is supplied to the cabin by a pair of independent air conditioning packs, fed by P3 air from their respective engines. Before entering the fuselage ducting which supplies air to the conditioning packs and other services, the high temperature P3 air from each engine is pre-conditioned by a pressure reducing valve and a heat exchanger, the latter cooled by P2 air which is modulated by a temperature control valve to maintain the P3 outlet temperature to approximately 210°C. (It was this TCV which was replaced at Hurn, following the original overheat en-route to Stansted.) The air ducting immediately downstream of this heat exchanger incorporates a temperature transducer which drives a duct temperature gauge on the flight deck, and an overheat thermostat designed to illuminate a warning caption on the flight deck and to close down the system automatically should the temperature exceed 270°C. (It was this overheat thermostat which was found, after the second incident, to have an intermittent plug pin contact.)

The No 1 and No 2 conditioning packs are essentially similar, independent units located in the air conditioning bay in the lower fuselage beneath the wing centre section, on the left and right side respectively. Each comprises a conventional heat exchanger system and air-cycle cold air unit, together with associated control and ancillary equipment. Each heat exchanger matrix is located toward the downstream end of a large divergent/convergent duct, just upstream of the convergent section which discharges to atmosphere via a set of outlet louvres in the belly, positioned just ahead of the main landing gear bays.

The primary supply of cooling air to each main heat exchanger is taken from individual ram air intakes in the belly of the aircraft. At speeds below 165 kt, when the ram air supply may be insufficient and also on the ground, heat exchanger cooling air is supplied by an electrically driven ground cooling fan which takes air from the air conditioning bay (effectively the lower fuselage cavity) and feeds it to both the No 1 and No 2 heat exchangers via a large bifurcated duct. On the ground, a set of louvre panels in the lower fuselage are opened automatically by an electro-pneumatic actuator signalled via the 'weight-on-wheels' switches, providing an additional supply of external air into the conditioning bay to service the needs of the ground cooling fan. A flap valve in the intake section of each heat exchanger duct moves under the influence of the incoming air, to close-off the redundant inlet path.

Should both air-conditioning systems fail, or be shut down, a ram air valve may be opened which connects the cabin main air distribution system to a take-off tapping in the divergent section of the No 2 heat exchanger duct, providing a limited supply of fresh (external) air to the cabin. The ram air system is intended for use only when the aircraft is unpressurised and the aircraft altitude is below 10,000 feet.

### **Cause of the fumes in the cabin**

The fact that there were no over-temperature indications accompanying the second *fumes in the cabin* incident suggests that these fumes were almost certainly residues from the earlier overheat, as the crew concluded. However, it was unclear as to why they did not appear at an earlier stage, and it

is a cause for concern that although these appeared merely residues, they were nevertheless capable of making the cabin crew unwell.

It did not prove possible to identify positively the route by which the fuel vapours entered the cabin. However, it is of note that the smell of fuel first appeared shortly after the aircraft had descended and depressurised, and the ram air valve opened, i.e. about 10 minutes later by the crew's recollection, when they were between 3000 feet and 5000 feet altitude and at about 210 kt. When the ground cooling fan activated, which normally occurs at speeds below about 165 kt, this could have resulted in fuel vapours from the leaking fuel supply pipe in the landing gear bay being drawn through the air conditioning bay, into the fan intake, and thence into the No 2 conditioning pack heat exchanger duct from where they could have found their way into the cabin supply via the ram air valve. The crew recollection was that the airspeed was about 210 kt when the fumes first occurred, i.e. before the fan should have activated. However, it is possible that some fumes nevertheless found their way into the heat exchanger duct before the fan activated, by migrating through inlet trunk of the fan due to small pressure differentials between the various parts of the system, possibly influenced by aircraft configuration and attitude. Alternatively, they may have first appeared a little later than the crew recalled, after the fan had activated. Whichever was the case, the ram air ventilation system appears to have been the route by which the fumes reached the cabin.

### **Overheat protection**

During the original overheat incident en-route to Stansted, the temperature was noted as being approximately 300°C. To achieve these conditions, it would have been necessary for two separate faults to have occurred:-

a TCV malfunction causing the duct temperature to rise to abnormal levels, **and**

a failure of the over-temperature thermostat, preventing the system from detecting the overheat and automatically shutting down the No 1 air system as soon as the temperature exceeded 270°C.

Because the thermostat fault was intermittent, it is possible that the overheat protection fault had cleared itself temporarily by the time the aircraft had returned to Hurn for the TCV change.

The aircraft was originally equipped with two separate over-temperature sensors, a *bulb* type sensor and a thermostat. It is understood that the bulb type was found to be unreliable in service and operators were subsequently given the option of disabling it; the reliability of the thermostat unit alone being considered sufficient to ensure adequate protection. G-AVMH was one of those aircraft (the majority) so modified. The remaining duct over-temperature thermostat is not covered by the press-to-test facility on the flight deck, nor is it subject to frequent inspections. However, it is subject to a functional check carried out during the annual air system inspection.

The lack of regular functional testing, and of a press-to-test facility, introduces a risk of a dormant fault occurring in the overheat detection system, with an attendant risk of a serious overheat. However, in practice a *hot* smell would almost certainly accompany any significant overheat, and would serve to alert the crew to a duct overheat, as it did on this occasion. The duct temperature gauges should then allow the faulty system to be identified and shut down manually.