

Druine D 62B Condor, G-AWFN, 18 May 1997

AAIB Bulletin No: 8/97 Ref: EW/G97/05/10 Category: 1.3

Aircraft Type and Registration:	Druine D 62B Condor, G-AWFN
No & Type of Engines:	1 Rolls-Royce Continental O-200-A piston engine
Year of Manufacture:	1968
Date & Time (UTC):	18 May 1997 at 1900 hrs
Location:	Shobdon Airfield, Herefordshire
Type of Flight:	Private
Persons on Board:	Crew - 1 - Passengers - None
Injuries:	Crew - None - Passengers - N/A
Nature of Damage:	Damage to both wings
Commander's Licence:	Private Pilot's Licence
Commander's Age:	53 years
Commander's Flying Experience:	1,600 (all on type) Last 90 days - 28 hours Last 28 days - 12 hours
Information Source:	Aircraft Accident Report Form submitted by the pilot and further enquiries by AAIB

The aircraft was flown to Shobdon by the owner, where the passenger transferred to the left hand seat for the solo return flight. After completion of the ground checks, the aircraft took off from Runway 27 (grass) and at a height of 30 feet experienced a total engine failure. The pilot elected to land on the parallel Runway 27 (hard) to his left. He decided that he could not stop before the boundary fence and so attempted to touchdown just before the fence and then hop over it. However, the aircraft had insufficient energy remaining and only rose 12 inches before contacting the fence.

Fuel flow checks were carried out after the accident and a flow of 8 gallons per minute was obtained from electric pump, and zero from mechanical pump. A strip inspection of the AC Delco mechanical pump showed that the diaphragm was made of three layers of red rubber moulded over cotton, fitted with a steel push/pull rod; it had no identifying markings and was probably produced as a car part. The push/pull rod was corroded and worn, the end of the slot which housed the engine

driven pump operating arm had completely corroded through and allowed the operating arm to disengage.

An engine overhaul agent stated that Teledyne Continental motors supply new pumps, they also supply kits containing a filter and two washers to enable an annual inspection to be carried out on some pumps to comply with an AD. These have Teledyne part numbers; otherwise no other source of aircraft rated parts was known.

AC Delco are thought not to have produced aircraft rated pump parts for some 15 years, however, some bogus parts to fit AC pumps have been produced in far eastern factories using the same mould identification numbers as the original items.

The electric pump should have provided sufficient fuel on its own, as shown by the flow check. However, its outlet valve, which consisted of a brass disc and a wire circlip, contained a 1/4 inch curl of drill swarf which was free to move and in some positions prevented the outlet valve from opening.