

Pitts S-1E Special, G-BOIH

AAIB Bulletin No: 2/98 Ref: EW/C97/7/7 Category: 1.3

Aircraft Type and Registration:	Pitts S-1E Special, G-BOIH
No & Type of Engines:	1 Lycoming O-360-A4A piston engine
Year of Manufacture:	1989
Date & Time (UTC):	25 July 1997 at 1430 hrs
Location:	Meppershall Airfield, Bedfordshire
Type of Flight:	Private
Persons on Board:	Crew - 1 - Passengers - None
Injuries:	Crew - Fatal - Passengers - N/A
Nature of Damage:	Aircraft destroyed
Commander's Licence:	Private Pilot's Licence
Commander's Age:	38 years
Commander's Flying Experience:	570 hours (of which 193 were on type) Last 90 days - 8 hours Last 28 days - 4 hours
Information Source:	AAIB Field Investigation

The pilot gained his Private Pilot's Licence in 1976. He began to fly competition aerobatics in September 1989 and came fourth at Standard competition level in 1991 flying a Pitts S2A. He won two competitions in 1992 and moved up to Intermediate level in 1993 achieving top three placings in three competitions during that year.

Since 1994, he had flown in aerobatic competitions at Advanced level with a good degree of success. During 1997, the pilot had competed in three Advanced level competitions, winning one and being runner-up in the other two. He had also won a glider aerobatic competition at Standard level. The pilot was intending to compete in the British National Championships taking place from 30 July to 2 August at Sywell Aerodrome.

The pilot's own aircraft, a Pitts S-1S registration G-BKDR, was still undergoing repair at Meppershall after a forced landing accident following an engine failure on 8 November 1996

(reported in the AAIB Bulletin 5/97). In order to continue flying during the repair period, the pilot had arranged the use of G-BOIH. The accident flight was the pilot's eighteenth flight in this aircraft, his log book indicating that aerobatics featured prominently during these flights.

The aircraft was normally based at Benington Airstrip, near Stevenage. On the morning of the accident, the pilot left home in Luton at about 0930 hrs with the intention of flying G-BOIH from Benington to Meppershall in order to clean the aircraft in preparation for the following week's competition flying, before returning it to its base. He also stated his intention to carry out two aerobatic practice sessions during the positioning flights. Fuel was not available at either Benington or Meppershall, so a refuelling stop at Panshanger was also planned for the return sector.

There was no official record of the departure time from Benington. A witness in Baldock noted a Pitts Special 'going fast' and doing continuous aileron rolls but his memory of the timing was not precise. Recordings from Debden Primary Radar were examined in order to establish the precise flight timings but no trace of the aircraft was found.

The aircraft arrived at Meppershall between 1130 and 1230 hrs, while the hangar staff were having lunch. The pilot spent about two hours cleaning the aircraft. At about 1415 hrs, it was the hangar staff tea break and they were sitting outside the hangar watching the pilot preparing to depart. A group of young children were also watching proceedings from a gap in the airfield boundary hedge in front of the hangar.

The aircraft taxied out for departure from Runway 02, which has a 600 metre take-off run with a 100 metre overrun area. About 10 minutes elapsed during which the engine run up was heard. This was out of sight of the observers over the curvature of the strip. Engine power was heard to increase and as the aircraft came into sight over the brow of the hill it was already airborne, being held low to gain speed. About 50 metres before reaching a point abeam the hangar (about 550 metres from the start of the take-off run), the aircraft pulled up sharply into a 45° pitch up climb and completed two continuous rolls to the right while continuing to climb. The aircraft was then seen to continue the roll to a wing's vertical attitude, right wing down. Witnesses reported that the engine noise decayed at this time and the aircraft began to sideslip to the right. It was seen to yaw and roll as if in an incipient spin. It rolled right and pitched down. There was insufficient height to effect a recovery and ground impact followed moments later in a steep nose down/right wing down attitude. The pilot was wearing a full harness which did not fail during the impact, but he sustained fatal impact injuries. Hangar staff rushed to the scene but were unable to assist. There was no fire.

No unusual noises were heard coming from the engine prior to the accident. One witness indicated that he could hear the engine running throughout the final descent. All witnesses agreed that the propeller had been turning just prior to impact. Estimates of the maximum height achieved by the aircraft were between 150 and 250 feet.

Accident site details

The aircraft had crashed close to the end of the grass strip but displaced approximately 60 metres to the right, and had come to rest in a hedge which separated the airfield from a road. The impact was less than 30 metres from a house belonging to the owner of the airfield. The impact area consisted of short grass growing on hard ground, and it was possible to discern impressions made by the leading edges of both upper and lower wings. The pitot probe, which was mounted on the leading edge of the lower left wing, had been driven into the earth before breaking off at its base. This, together with the impact marks, indicated that the aircraft had struck the ground pitched down at an

angle of around 70° on a heading of approximately 290°. The aircraft had apparently then bounced in a south-easterly direction, twisted almost 180° about its longitudinal axis in the process, before becoming balanced on its nose, with the cockpit area leaning against the hedge. The fact that the aircraft moved in a direction that was significantly different to the heading following the initial impact suggested the aircraft had struck the ground in a stalled condition.

The fuselage aft of the cockpit, together with the empennage, were almost undamaged. However, the forward fuselage and cockpit had been considerably compressed, with aft movement of the engine firewall and significant buckling of the floor around the rudder pedals. The wings had been badly damaged, effectively becoming wrapped around the fuselage as the aircraft came to rest.

The mark in the ground caused by the propeller, together with chordwise scuff marks on the blades themselves, indicated that the propeller had been rotating, although the lack of leading edge damage suggested a low power condition at impact.

Following an on-site inspection, the wreckage was removed to the AAIB facility at Farnborough for a more detailed examination.

Examination of the wreckage

An examination of the airframe revealed no evidence of a pre-impact structural failure or detachment. Similarly, the flying control operating system showed no evidence of a pre-impact disconnect, although it was not possible to discount the possibility of a control jam. However, no loose articles, such as tools, were found which could have caused such an event.

The fuel tank, which had split open during the impact, was mounted ahead of the instrument panel, with fuel off-take being via a 'flop tube'. This was a flexible, weighted tube, mounted at the rear of the tank such that the open end of the tube moved with the fuel in response to the applied 'g' forces. The tube was examined for splits which could have resulted in air being entrained into the fuel lines; none was found. Other elements of the fuel system were examined, including the gascolator, which was found to be full of fuel containing a small amount of sediment. The fuel cock was found selected to the open position, and the fuel lines to and from the engine driven fuel pump were primed with fuel.

The fuel was delivered to the engine via a throttle body injector, rather than a conventional float-type carburettor. The essential components of this were a throttle slider moving within a block containing the venturi. The slider was operated by means of a teleflex-type cable, and performed the throttle function by varying the exposed area of the venturi. This arrangement was considered resistant to movement during a sudden impact. Thus the fact that the mechanism was found jammed in the throttle closed position was considered a reasonably reliable indication of the setting at impact. Mixture control was by means of a rotating spray bar positioned across the venturi. As found, the control was free to move and it was not possible to identify the position at the time of impact. However, there was no reason to suppose that it was at anything other than the fully rich setting. The carburettor hot air control box had been severely distorted during the impact, with the position of the moveable flap suggesting that 'cold' air had been selected.

The engine accessory gearbox had suffered no internal failures that could have affected the operation of such components as the engine driven fuel pump or the magnetos. The latter were damaged although it was possible to mount the left-hand unit on a test rig, where it produced sparks on all four high tension (HT) leads. The fuel pump was disassembled, with no defects being found.

The engine was subjected to a strip examination and was mostly found to be in reasonable condition. The exception was a severely worn cam lobe which operated Nos 1 and 2 cylinder inlet valves. Measurement revealed that the amount of wear, and in consequence, the loss of valve lift, was approximately 0.125 inches. The associated cam followers had suffered pitting damage. A small amount of metallic debris was found in the oil screen, with rather more being found in the sump. It is probable that this material originated from the cam lobe. There was no evidence of any lubrication failure elsewhere in the engine. The engine log book recorded more than 2,200 operating hours since the last overhaul.

The loss of valve lift would have been partly compensated for by the hydraulic tappets. Nevertheless there must have been a reduction in the power output of the engine, although it was not possible to quantify this. With a fixed pitch propeller installation, a reduction in maximum power would be most obvious during the take-off roll, when a drop of RPM would be apparent compared to that usually obtained at full throttle. However, the cam wear would probably have occurred over a considerable number of operating hours, and would not have resulted in a large RPM drop (at full throttle) over successive flights.

In the experience of an engine overhaul agent who was contacted on the matter, worn cam lobes in the manner noted above have been encountered occasionally on this type of engine. The wear in almost all cases was confined to the cam operating Nos 1 and 2 inlet valves and/or the cam operating Nos 3 and 4 inlet valves. Each of these cams is in contact with two cam followers compared to the exhaust valve cams, which operate only one valve each. The agent noted that all affected engines had been returned for overhaul, as opposed to investigation for maximum power reduction, thereby suggesting that significant cam wear did not result in any dramatic indications. The cam wear was thought to originate during the engine start cycle, before oil had been pumped round to the cams, thus leading to brief periods of metal-to-metal contact between the cams and followers.

Operational considerations

A post-mortem examination did not find any evidence to suggest pilot incapacitation and there were no indications of the presence of either alcohol or drugs. The pathology report indicated that the nature of the injuries showed that considerable lateral force had been present, with the right-side down. It was considered that the impact was non-survivable.

The weather at the time was good, with a light north-westerly airstream established over the area giving a surface wind from 320° at 10 kt. Therefore, the crosswind component on takeoff was about 8 kt from the left. The visibility was greater than 10 km, with scattered to broken cloud base 3,500 to 4,500 feet. The ambient temperature was +21°C.

Checking of the aircraft's previous flying and refuelling records gave an estimated fuel load on departure from Benington as 43 litres. Because the fuel system consisted of a 'flop' tube fuel tank feed line and no collector tank, the aircraft was subject to an operating limitation (quoted in the Aircraft Flight Manual for the type, but not re-iterated on this aircraft's Permit to Fly) indicating that no low altitude aerobatics are recommended with less than one quarter of a tank of fuel (18 litres) on board. The aircraft would have needed to be airborne for about 45 minutes during the flight from Benington to Meppershall to achieve this minimum. Using straight line tracks with only a 'dog-leg' around the corner of the Luton Control Zone at Baldock and with an allowance for a circuit before landing, the estimated flight time to Meppershall was 15 minutes. It is therefore likely that the aircraft had more than one quarter of a tank of fuel on board at the time of the accident.

A weight and balance calculation was carried out by the AAIB, based upon the calculated fuel state of the aircraft. This indicated that, at the time of the accident, the aircraft was operating well within the permitted centre of gravity envelope and was about 86 lb below the maximum permitted operating weight.

Whilst being highly experienced and accomplished at aerobatics, the pilot did not hold any form of CAA Display Authorisation, nor was any evidence found to suggest that the pilot regularly conducted low level aerobatic manoeuvres. The aerobatic competitions are normally flown at 'medium' levels, with a base of 200 metres (650 feet) at Advanced standard. The pilot's Aresti manoeuvre sequence card was recovered from the instrument panel after the accident. This indicated that his intended 'free' programme sequence for the British National Championships contained a large number of rolling manoeuvres.

The observed flight profile was discussed with a number of other aerobatic pilots with extensive Pitts S-1 experience. All of them expressed the opinion that the speed attained prior to the pull up may have been between 120 to 130 mph, being sufficient for perhaps a single roll, and that the speed would decay with the aircraft in such a steep climbing attitude. Their opinions were that after two rolls, the speed would have decayed to around 80 mph. The recorded stall speed of G-BOIH was 58 mph but incipient spin entry is possible at higher speeds when sideslip is present.

Although no evidence was found to indicate that a flight control abnormality or major engine failure had occurred, the possibility of a temporary control restriction, or some other transient problem causing pilot distraction, could not be totally dismissed.