

Boeing 757-236, G-BIKK

AAIB Bulletin No: 1/98 Ref: EW/G97/09/26 Category: 1.1

Aircraft Type and Registration:	Boeing 757-236, G-BIKK
No & Type of Engines:	2 Rolls-Royce RB211-535C turbofan engines
Year of Manufacture:	1983
Date & Time (UTC):	23 September 1997 at 1443 hrs
Location:	Geneva Airport, Switzerland
Type of Flight:	Public Transport
Persons on Board:	Crew - 8 - Passengers - 124
Injuries:	Crew - None - Passengers - None
Nature of Damage:	Nil
Commander's Licence:	Airline Transport Pilot's Licence
Commander's Age:	47 years
Commander's Flying Experience:	12,800 hrs (of which 4,840 were on type) Last 90 days - 165 hours Last 28 days - 74 hours
Information Source:	Operator's Air Safety Reporting System

The aircraft was operating on a scheduled service flight from Milan Linate Airport to London Heathrow. As the landing gear was being retracted after take-off, an Engine Indication and Crew Alerting System (EICAS) message, 'GEAR DOORS' appeared. The crew recycled the landing gear but this had no effect upon the status of the indication. Some airframe vibration was apparent and this was confirmed by the cabin crew located near the middle of the aircraft. During the climb, the crew consulted the aircraft's Quick Reference Handbook (QRH) which indicated that the only action required was to limit the airspeed to 270 kt and Mach 0.82. They elected to cruise at FL310 and considered the potential drag penalty and fuel implications of continuing the sector with a gear door not closed.

The Hydraulics systems status page indicated that the Left system quantity was lower than the other two systems. The Left system quantity continued to reduce progressively and the Commander, in consultation with the First Officer, elected to divert to Geneva, which was close to the planned route

and had engineering support facilities. An EICAS Hydraulic Quantity warning appeared in due course as the contents reduced further.

The cabin crew were briefed and ATC informed, although no emergency was declared. The crew completed the QRH checklists for Loss of Hydraulic Quantity and Loss of Hydraulic System Pressure Single (Left) System. A landing with 20° Flap was planned in accordance with QRH procedure.

The aircraft was given radar vectors and completed an uneventful ILS approach and manual landing on Runway 05, with gentle manual braking. The Commander planned to exit the runway at a rapid exit taxiway, should nose wheel steering not be available. In the event, there was sufficient hydraulic fluid remaining to allow the nose wheel steering system to function and the commander commenced to taxi the aircraft off the runway.

When the aircraft was about 50 metres along the taxiway, ATC informed the crew that there was smoke coming from the landing gear and that the aircraft should stop in its present position. The Airport Fire Service had been informed of the aircraft's situation and were in attendance on the taxiway. Smoke was observed by the fire crew coming from the landing gear area.

There was no VHF communication link between the aircraft and the fire service. There were some communications difficulties but, using hand signals and attempting to shout messages through the open flight deck DV windows, the Commander ascertained that the fire chief wanted the engines to be shut down. This was complied with and, believing that a fire hazard existed, the Commander initiated a full evacuation of the aircraft.

All of the emergency slides deployed correctly and all of the occupants exited the aircraft without injury. Some passengers were not constrained after the evacuation and strayed onto the runway before being assembled by the Fire Service prior to being taken back to the terminal.

The 'GEAR DOORS' EICAS message appeared because a hydraulic leak from a 'truck tilt actuator hose' caused a pressure drop which was enough to prevent the door lock from engaging during the gear retraction sequence. This reduced pressure however, was not low enough to trigger an EICAS low pressure warning. After 19 minutes the hydraulic leak produced an EICAS left hand reservoir warning, which is triggered when the reservoir contents drop below 48%. At this stage the captain decided to divert, and when gear down was selected a left hand hydraulic system 'LOW PRESSURE' amber light and EICAS message illuminated because the selection drained away most of the remaining fluid in the left hand system.

Two hydraulic fuses, fitted to the extend/retract lines, failed to operate and isolate the leaking hose. The fuses performed satisfactorily on subsequent tests and may not have operated in the aircraft because their leak detection parameters - flow rate and quantity - were not met. The fuses have been sent to Boeing for further testing.

A check of the operator's records indicated that the failure of this particular hose is an uncommon event, and can therefore be treated as an isolated incident.