

BN2T Islander, G-WOTG

AAIB Bulletin No: 9/97 Ref: EW/G97/06/23 Category: 1.2

Aircraft Type and Registration:	BN2T Islander, G-WOTG
No & Type of Engines:	2 Allison 250-B17C turboprop engines
Year of Manufacture:	1982
Date & Time (UTC):	12 June 1997 at 1045 hrs
Location:	RAF Weston-on-the-Green, Bicester, Oxfordshire
Type of Flight	Royal Air Force Sport Parachute Association
Persons on Board:	Crew - 1 - Passengers - None
Injuries:	Crew - None - Passengers - N/A
Nature of Damage:	Minor damage to the sliding door
Commander's Licence:	Airline Transport Pilot Licence
Commander's Age:	52 years
Commander's Flying Experience:	7,062 hours (of which 231 were on type) Last 90 days - 69 hours Last 28 days - 47 hours
Information Source:	Aircraft Accident Report Form submitted by the pilot and AAIB telephone enquiries

This aircraft was being used for the dropping of sport parachutists and was fitted with a sliding door on the left side of the cabin, in accordance with the manufacturers approved modification. On the fourth flight of the day the last two students were dropped, followed by the jumpmaster, at a height of 3000 feet leaving the pilot the sole occupant of the aircraft. The sliding door is retained in the forward position by a spring latch which may be released by the operation of an internal red painted handle accessible to the pilot, behind and to the left of his seat. Upon his release of the door it reportedly slid back under the influence of the slipstream as intended but, on reaching full travel, over-travelled the 'stop block' located at the lower rear corner of the door aperture. The corner of the door then over-rode the fairing tube attached to the aircraft's skin, thereby inducing some distortion in the door, which allowed it to detach from the aircraft. The door fell to earth close to the centre of the drop zone, sustaining minimal damage, and the aircraft then landed safely.

The aircraft was subsequently flown to a maintenance organisation at a nearby airfield, where the door was repaired and re-fitted to the aircraft. It was apparent that a small degree of wear, effectively

a chamfer, was present on the outer edge of the stopblock. After this symmetrical block was re-fitted to the aircraft but turned through 180° to present a fresh 'stop' face, and the door runner blocks had been re-shimmed to reduce vertical play, the aircraft was returned to service. A supplement to the aircraft's Flight Manual included information on operation with the sliding door modification. This stated that the door may be moved from open to the closed position at speeds up to 90 kt IAS, and that the aircraft may be flown to a maximum speed of 130 kt with the door open.