

BAe 146-200, G-JEAS, 19 May 1996

AAIB Bulletin No: 8/96 Ref: EW/C96/5/8 Category: 1.1

Aircraft Type and Registration: BAe 146-200, G-JEAS

No & Type of Engines: 4 Lycoming ALF502 - R5 turbofanengines

Year of Manufacture: 1984

Date & Time (UTC): 19 May 1996 at about 1205 hrs

Location: Exeter Airport, Devon

Type of Flight: Public Transport

Persons on Board: Crew - 5 Passengers - None

Injuries: Crew - None Passengers - N/A

Other - 1 serious

Nature of Damage: Slight damage to fuselage paint

Commander's Licence: Not relevant

Commander's Age: Not relevant

Commander's Flying Experience: Not relevant

Information Source: AAIB Field Investigation

History of the accident

The aircraft was parked parallel to the terminal building, about 65 metres behind a Fokker F-27. Both aircraft were facing southwest; the BAe 146 was about one metre to the right of the yellow taxiway line and the F-27 about one metre to the left. The 1150hrs weather observation for Exeter gave the surface wind as 250°/19kt with gusts to 28 kt; the direction varied between 220° and 280°. A gust of 26 kt was recorded at 1203 hrs. The concrete ramp surface was wet from recent rain.

The passengers had disembarked from the BAe146 and only the operating crew and ground handling personnel were on board. One of the latter, a member of the airport catering staff, had just delivered some supplies. She left the aircraft through the front passenger door, and had both feet on the top section of the aircraft steps, when the F-27 started to taxi forward; at this point the bottom of the steps started to move rearwards in an arc centred on their rear top corner which was against the fuselage. The lady fell backwards, from a height of about 2 metres, onto the ground below and

sustained serious injury to her back, ribs and head. The steps continued rearwards scraping along the fuselage and came to rest against the left main landing gear. First aid was rendered by airport staff until the lady could be transferred to the Exeter and Devon General Hospital; her condition remained critical and she was later transferred to a specialist unit in a hospital in Plymouth.

Aircraft steps

The rigid frame steps were carried on four, 5 inch diameter nylon wheels; the wheels at the aircraft end were fixed and unbraked while those at the other end were able to castor through 360° and were braked by the action of a metal pad applying pressure to the perimeter of the wheel. When the steps were first positioned, the No 1 cabin attendant was not satisfied and asked for them to be repositioned, however, this was because the moveable flap which compensates for the variation of door sill height during loading/unloading was considered to be a trip hazard to disembarking passengers. The steps were repositioned with the protective pad not so firmly butted against the side of the fuselage, and a member of the customer services staff stood at the front of the top platform to guard a gap between the opened aircraft door and the hand rail.

When the steps are correctly positioned the brakes are applied and the normal practice is for the ground handler to pull back on the hand rails to check that the brake is effective. The ground handler who positioned the steps prior to the accident stated that he had carried out this check both initially and following the repositioning. An eye witness in the terminal building had watched the arrival of the BAe146 and, having heard about the accident, contacted the Airport Operations Director to say she had watched the ground handler position the steps and had been impressed by his thoroughness; she particularly noted that he had done something to the small wheels at the bottom of the steps. All the arriving passengers, many elderly and some needing wheelchairs, had disembarked from the forward passenger door via these steps without incident.

The commander of the F27 said that he had applied about 11,500 RPM to start his aircraft moving from the stand; this is a normal setting for the prevailing conditions. Fokker Services estimated that the speed of the propeller wash at 60 to 70 metres, in still air, would have been of the order of 18 to 23 kt.

The steps had been obtained from another airport in about 1989 and had been used infrequently, mainly on BAe146 type aircraft, since that time. Maintenance of the steps was done locally; there are few moving parts and maintenance was on an 'on condition' basis. No maintenance records were available.

Initial post accident examination of the steps, in a hangar, revealed that the brake on the right wheel (looking up the steps) was ineffective; the brake on the left wheel was more effective, however, distortion of the frame of the steps meant that, on a flat surface, this wheel did not touch the ground. In this condition the steps could be manoeuvred easily with both brakes applied. The steps were subsequently positioned in approximately the same area as they had been at the time of the accident; the surface was relatively flat and the effect of the distortion was evident. The construction of the frame and brakes was such that it was felt unlikely that the condition of the steps was a consequence of the event but rather that it had existed for some time.

Aircraft parking

While it was usual practice to park propeller driven aircraft along the front of the terminal building, often in line facing into the prevailing south westerly wind, jet aircraft were normally parked on

another part of the ramp. On this occasion the BAe146 was parked in front of the terminal because of lack of space in the normal jet parking area. The minimum spacing of one aircraft behind another is determined by the clearance needed for the rear one to leave the ramp first.

A ground handling crew would not normally indicate that an aircraft was clear to start if passengers were embarking or disembarking from one parked directly behind it. However, if only ground or aircrew personnel are attending that aircraft it does not appear to generate the same caution. Compared with nose-in parking, nose to tail parking can make personnel and equipment more vulnerable to the effects of jet blast or propeller wash as well as increasing the possibility of foreign object damage to other aircraft in the line.

Ramp safety training

The onus for training catering personnel who were required to carry out tasks airside, fell to the catering company. In this case the injured lady started with the company at the end of February and her training was done by the catering manager who also accompanied her onto the ramp for the first four days. There was no evidence to suggest that this training was done in other than a thorough and professional manner and it was not a factor in the accident.

Health and Safety Executive (HSE)

Regulatory responsibility for airfields is shared by both HSE and CAA; although some aspects can be specific to either organisation, many responsibilities are common and there is an overlap of interests. Attention is drawn to CAP 642 - Apron Safety Management. HSE carried out a parallel investigation into this accident and a Specialist Inspector (Mechanical Engineering) undertook an assessment of the serviceability and suitability of the steps.