

Stinson V-77 Reliant, G-BUCH

AAIB Bulletin No: 6/97 Ref: EW/G96/08/30 Category: 1.3

Aircraft Type and Registration:	Stinson V-77 Reliant, G-BUCH
No & Type of Engines:	1 Lycoming R-680-E3B piston engine
Year of Manufacture:	1942
Date & Time (UTC):	8 August 1996 at 1540 hrs
Location:	White Waltham Airfield, Berkshire
Type of Flight:	Private
Persons on Board:	Crew - 1 - Passengers - None
Injuries:	Crew - None - Passengers - N/A
Nature of Damage:	Engine seized, no damage to airframe
Commander's Licence:	Private Pilot's Licence
Commander's Age:	37 years
Commander's Flying Experience:	450 hours Last 90 days -Nil Last 28 days -Nil
Information Source:	Aircraft Accident Report Form submitted by the pilot and metallurgical examination of the failed engine cylinder

After a normal start and ground run of the engine, the pilot tookoff from White Waltham intending to fly to Popham airfield. The aircraft climbed quickly to 1,800 feet when the pilot became aware of slight puffs of smoke from the engine which he initially thought were reflections or small pockets of cloud. He checked the engine Temperature and Pressure indications which were normal but the smoke continued. He calculated that it would be quicker to return to White Waltham than to continue to Popham and accordingly turned the aircraft through 180°. Shortly afterwards the pilot believed that the engine had caught fire when it deposited oil on the windscreen, despite the engine Temperature and Pressure instruments indicating normally. As he was still at 1,800 feet, he tried to restore power by closing and opening the throttle, but the airframe vibrated violently so he feathered the propeller. With White Waltham in sight he continued to track towards the airfield at the appropriate glide speed whilst upgrading his previous PAN message to a MAYDAY.

The pilot realised that a landing within the airfield boundary was probably achievable. Even though it would be downwind he felt this was preferable to some fields which, although into wind, may

have been of a rough, uneven nature. Touchdown was smooth on the airfield but not on the runway. He applied fairly hard braking which caused the brakes to overheat and lock on, however the aircraft did not tip onto its nose and there was no further damage. The fire services attended promptly but there was no sign of fire.

There was a delay of some three months in notification to AAIB of this incident as the pilot did not think it was notifiable. During that time, the aircraft was examined by both its maintainer and an insurance surveyor who found that the upper cylinder of the radial engine had fractured (Figures 1 & 2) causing severe distress to the rest of the engine and loss of oil. There was no sign of fire around the engine, the symptoms of which were probably smoke and vapour from the ruptured cylinder barrel. The AAIB requested that they examine the cylinder and piston and asked for the engine log book to determine the engine's maintenance history. The parts were obtained but the owner seemed to experience difficulty in finding the log book. From his recall, an organisation specialising in vintage aircraft engines had last done work on the engine in January 1992 and they were contacted for details. They were unable to give any figures as to the overhaul history of the engine and it appeared that their involvement had been, at the (previous) owner's request, to address a reported problem of high oil consumption by honing the cylinder bores, fitting new piston rings, valve springs and guides. At that time, the organisation concerned did not have any CAA approvals to certify the work, which was carried out under the signature of the licensed engineer who maintained the aircraft. They recalled that 0.010 of an inch oversize pistons were fitted to the engine but their measurements showed that the degree of wear was such that 0.020 of an inch oversize rebore and pistons were more appropriate. At the insistence of the owner in order to minimise cost, only honing and fitment of 0.020 of an inch oversize piston rings was specified.

Metallurgical examination of the failed cylinder showed that a fatigue crack had developed from the outside, originating at the location shown in Figure 1 and associated with corrosion pitting. It was concluded that the crack had developed slowly over a large number of cycles and had been present for some considerable period of time. Examination of the exterior of the cylinder showed evidence of extensive corrosion damage under the varnish, which had apparently been cleaned-out by abrasive blasting prior to re-painting. Figure 2 illustrates this effect and the eroded thickness of the cooling fins which suggests that it had probably been done more than once. Measurement of the cylinder wall thickness showed it to be 0.078 of an inch in the region of the failure. A Lycoming drawing indicated a minimum thickness of 0.091 of an inch for a new component. The engineering company referred to above stated that a maximum oversize rebore of 0.020 of an inch was permitted so that the minimum wall thickness of a cylinder in this maximum rebored state would be 0.081 of an inch.