

DH115 Vampire T55, G-DHAV

AAIB Bulletin No: 2/98 Ref: EW/G97/11/19 Category: 1.1

Aircraft Type and Registration:	DH115 Vampire T55, G-DHAV
No & Type of Engines:	1 De Havilland Goblin MK35B turbojet engine
Year of Manufacture:	1956
Date & Time (UTC):	29 November 1997 at 1326 hrs
Location:	Swansea Airport, Wales
Type of Flight:	Private
Persons on Board:	Crew - 1 - Passengers - 1
Injuries:	Crew - None - Passengers - None
Nature of Damage:	Damage to landing gear and leading edge of left wing
Commander's Licence:	Commercial Pilot's Licence
Commander's Age:	30 years
Commander's Flying Experience:	1,700 hours (of which 7 were on type) Last 90 days - 141 hours Last 28 days - 37 hours
Information Source:	Aircraft Accident Report Form submitted by the pilot

The aircraft was returning to Swansea airport, after a local flight, to land on concrete Runway 22 with a Landing Distance Available (LDA) of 1,261 metres. The weather was CAVOK with a surface wind of 280°/15 gusting to 25 kt.

As the aircraft turned final the pilot encountered moderate turbulence and decided to increase the approach speed by 10 kt giving a threshold speed of 110 kt. The aircraft floated slightly during the flare despite the application of airbrakes. The wheel brakes were checked immediately after touchdown and large amounts of left rudder and left brake were required to compensate for the crosswind from the right. Approximately halfway along the landing roll the braking effectiveness reduced and, despite the application of full brake pressure and full rearward control column, the aircraft veered to the right and overran the end of the runway. The pilot closed the HP and LP cocks prior to leaving the paved surface. Both crew members were uninjured and vacated the aircraft having made safe their ejection seats.

A report by the Company Chief Pilot into the accident stated that the pneumatic bag braking system, common to most aircraft of this vintage, is notorious for 'brake fade' due to over heating which can result in a serious reduction, if not total failure, in braking effectiveness. Braking and rudder cannot be applied separately in the Vampire. Landing in strong crosswind conditions means that most of the braking effort will be applied to one side only. 'Brake fade' will cause a severe reduction in braking effectiveness and eventual loss of directional control. As a result of this accident the company have imposed a crosswind component limit of 15 kt on Vampire aircraft using Runway 04/22 at Swansea.