

Piper PA-31-350, G-BRFA, 12 August 1996

AAIB Bulletin No: 11/96 Ref: EW/C96/8/7 Category: 1.2

Aircraft Type and Registration:	Piper PA-31-350, G-BRFA
No & Type of Engines:	2 Lycoming TIO-540-J2BD piston engines
Year of Manufacture:	1978
Date & Time (UTC):	12 August 1996 at 1651 hrs
Location:	10 nm East of Ronaldsway Airport, Isle of Man
Type of Flight:	Public Transport
Persons on Board:	Crew - 1 - Passengers - 4
Injuries:	Crew - Nil - Passengers - Nil
Nature of Damage:	None
Commander's Licence:	Air Transport Pilot's Licence
Commander's Age:	38 years
Commander's Flying Experience:	1,150 hours (of which 53 were on type) Last 90 days - 140 hours Last 28 days - 53 hours
Information Source:	AAIB Field Investigation

History of the Flight

The aircraft was planned to fly a scheduled passenger service from Blackpool Airport to Ronaldsway Airport, on the Isle of Man, which was a 25 minute flight. The weather for the flight was excellent with a visibility of 25 kilometres, a few clouds at 2,500 feet, a surface wind of 360°/10 kt, temperature +17°C and a QNH of 1015 mb. The pilot had flown the same schedule earlier in the day in similar weather conditions.

The aircraft was serviceable with the fuel distribution prior to the flight of 350 litres in the inboard tanks and 30 litres in the outboard tanks. This was in accordance with the normal company procedures whereby the total fuel required for the flight was contained in the inboard tanks and a small amount of fuel was retained in the outboard tanks. The pilot, having assured himself that the fuel quantity and distribution were correct, completed the pre-flight checks and took off at 1630 hrs.

The take off and initial transit were uneventful and, 10 minutes into the flight the pilot completed a fuel check. He contacted Ronaldsway ATC at 1644 hrs whilst at 2,000 feet and was cleared under VFR to position for Runway 35. Shortly afterwards the right engine began to misfire; the pilot selected both emergency pumps 'ON' and the engine operation returned to normal. The pilot then noticed that the right boost pump annunciator was illuminated; this illuminates when the fuel boost pressure is less than 3 psi. The right engine began to misfire again and the pilot checked the engine instruments but there were no indications to explain the rough running; he disconnected the autopilot and considered shutting down the engine.

The pilot had not increased power on the left engine and the aircraft was now descending. At 1651 hrs he informed ATC that he had a rough running engine which he was about to shut down and was offered vectors to Runway 26 in order to reduce his ground track. At 1654 hrs the pilot informed ATC that he was passing 400 feet amsl and now had 'a real problem' because both engines were running roughly. The ATC controller alerted the Airfield Rescue Service to launch the resident rescue boat and also informed HM Coast Guard. At 300 feet amsl the pilot noticed that both fuel pump annunciators were illuminated. He checked the fuel selectors and noted that both were selected to the outboard tanks, he repositioned the selectors to the inboard tanks and both engines recovered almost immediately. He informed ATC who cancelled the launch of the rescue boat and the emergency with the Coast Guard. The aircraft climbed back to 1,000 feet and completed a normal landing at 1658 hrs.

Both the pre-flight checks and the pre take-off checks require the fuel selectors to be positioned for the inboard tanks. The pilot does not remember ever selecting the tanks to the outboard position.