

Boeing 747-236B, G-BDXI

AAIB Bulletin No: 3/97 Ref: EW/C96/10/1 Category: 1.1

| | |
|--|---|
| Aircraft Type and Registration: | Boeing 747-236B, G-BDXI |
| No & Type of Engines: | 4 Rolls-Royce RB211-524D4-19 turbofan engines |
| Year of Manufacture: | 1980 |
| Date & Time (UTC): | 5 October 1996, time not known |
| Location: | On departure Delhi Airport, India |
| Type of Flight: | Public Transport |
| Persons on Board: | Crew - 17 - Passengers - 321 |
| Injuries: | Crew - Nil - Passengers - Nil |
| Nature of Damage: | Damage to the right wing fixed trailing edge upper panel and the fore and mid trailing edge flaps |
| Commander's Licence: | Airline Transport Pilot's Licence |
| Commander's Age: | 47 years |
| Commander's Flying Experience: | 13,210 hours (of which 709 were on type Last 90 days - 193 hours Last 28 days - 64 hours |
| Information Source: | AAIB Field Investigation |

During climb-out from Delhi, at about 500 feet and following the initiation of a turn to the left, the flight deck crew felt an unusual vibration. A short time later the cabin crew reported that there was a 'bad vibration' in the cabin between doors 3 and 4 on the right-hand side. A member of the flight deck crew went back into the cabin to investigate and heard a loud noise above the overhead bins, and felt a vibration through the floor. The vibration subsequently appeared to be speed-related and on reaching the cruise Flight Level the vibration decreased and stopped. After the subsequent arrival at Heathrow Airport, it was found that a large area of the right-hand wing Fixed Trailing Edge Upper Panel, also known as the 'Flying Panel', was missing and inboard areas of the upper surfaces of the fore and mid trailing edge wing flaps were badly damaged. Subsequent examination of the damaged areas showed good evidence to indicate that the Flying Panel had been 'hammering', for a period of time, against the fore flap and had produced two deep grooves in the fore flap's upper surface. No evidence was found to indicate that any defect in the structure or material of the Flying

Panel had contributed to its failure. A major repair of this Flying Panel had previously been carried out, but there was no evidence that the type, or standard, of the repair had contributed to failure of the panel. Below the Flying Panel, it was found that the inboard diagonal tie rod (Figure 1) had bent/bowed laterally outboard in compression and had failed across the lower drain/vent holes. Metallurgical examination of the tie rod showed that it had failed in low cycle/high stress bending fatigue indicating that the force, which had caused the rod to bend, had been of a cyclic nature. The number of bending cycles was assessed as being in the order of 160 to 240 cycles from crack initiation to final failure. Examination of the tie rod also indicated that the rod had previously been adjusted to extend its length. This adjustment appeared to have been accomplished with a 'Stilson/pipe-wrench' type of tool on the external surface of the large diameter area of the rod. Between the 26th February and the 23rd May 1996, the aircraft had undergone a major maintenance check at an aircraft engineering organisation in Australia. Examination of the maintenance documentation for the aircraft did not reveal any evidence of subsequent work having been carried out that would have necessitated the adjustment, or rigging, of the Flying Panel since the maintenance in Australia. The aircraft had performed 230 flights between the maintenance in Australia and the date of this incident. Chapter 57-22 of the Maintenance Manual contains the information about the removal, installation, adjustment and rigging of the Fixed Trailing Edge Upper Panel. A number of pre-conditions and warnings are given throughout the chapter, one of which states that "*Adjustment of the fixed trailing edge upper panels made with the airplane on the gear----*". An AAIB Inspector was present with the operator's engineering staff when the replacement Flying Panel was fitted and rigged. It was noted that the procedures in Chapter 57-22 of the Maintenance Manual were very difficult to follow and in areas were ambiguous. The operator gave assurance that the procedures would be reviewed. However, as a result of this review, the operator decided that no revision of the Maintenance Manual was required. It was noted that there have been three other incidents of in-flight break-up of the Fixed Trailing Edge Upper Panel which AAIB have investigated (AAIB Bulletins 8/92, 2/95 and 10/96). One of these incidents also involved an inboard diagonal tie rod that had failed in compressive overload. Discussion It was concluded that the initiator of this incident was a large compressive force which had been applied to the inboard diagonal tie rod, resulting in bending of the rod. Over a period of time, the compressive force was successively removed and then reapplied resulting in failure of the rod after some 160 to 240 cycles, which then allowed the inboard trailing edge of the Flying Panel to lose its rigged form and contact the upper surface of the foreflap. The upper end of the tie rod was attached to the Flying Panel and the lower end was attached to the lower rear area of the main landing gear beam. It is considered that the large forces required to bend and fail the tie rod were generated by the tie rod being incorrectly adjusted, possibly whilst the airplane was on jacks and then, when it was lowered onto its landing gear, the deflection of the main landing gear beam produced a compressive load in the tie rod. Each time thereafter that the aircraft took-off and landed the compressive force would have been removed and reapplied, producing the fatigue striations observed in the failure surfaces of the tie rod. The number of fatigue striations observed would suggest that the incorrect adjustment of the tie rod had occurred during the period of major maintenance.