

Grumman AA-5A, G-OBSF, 8 February 1997

AAIB Bulletin No: 4/97 Ref: EW/G97/02/05 Category: 1.3

Aircraft Type and Registration: Grumman AA-5A, G-OBSF

No & Type of Engines: 1 Lycoming O-320-E2G piston engine

Year of Manufacture: 1977

Date & Time (UTC): 8 February 1997 at 1650 hrs

Location: Blackbushe Airport, Surrey

Type of Flight: Private

Persons on Board: Crew - 1 - Passengers - None

Injuries: Crew - 1 (Minor) - Passengers - N/A

Nature of Damage: Substantial general damage to engine and airframe

Commander's Licence: Private Pilot's Licence

Commander's Age: 43 years

Commander's Flying Experience: 99 hours (of which 98 were on type)
Last 90 days - 4 hours
Last 28 days - Nil

Information Source: Aircraft Accident Report Form submitted by the pilot and a report by the CFI

At about 1640 hrs, the aircraft took off on Runway 08 for a circuitdetail; the weather was:

Surface wind 190°/2 kt

Visibility 4 to 6 km in Haze

Cloud Few base 800 feet
 Broken base 1,700 feet

Temperature +10°C

On his first circuit the pilot had to descend to 600 feet on the downwind leg to remain visual with the airfield. The weather appeared to be deteriorating rapidly so the pilot decided to land as soon as possible. Unfortunately when he turned onto the crosswind leg he felt that he was not in a good position to continue the approach and so he decided to go-around. The circuit got busier as more aircraft returned to land before the weather deteriorated further and the pilot found the situation very difficult. He went around from the second circuit and, as he established on the crosswind leg of the third, he was told that there was another aircraft on his left side, behind and slightly higher. Meanwhile the CFI, concerned about the deteriorating weather, had instructed the AFISO to tell the pilot to land as soon as possible. He replied that this was already his intention.

As he turned onto final approach there was another aircraft ahead and below; the pilot thought he would have to go-around and prepared to do so. However, the AFISO instructed the aircraft ahead to go-around. The aircraft was now high on the approach so the pilot increased his rate of descent aiming initially at a point one-third down the runway. The aircraft touched down and bounced, the pilot applied some power and then attempted to land again. The aircraft again bounced so he decided to go-around; he applied full power and raised one stage of flap. He could not recall clearly what happened next but he was aware that there was insufficient runway left to complete the go-around. He thought that he had then closed the throttle but there was also insufficient runway left in which to stop.

The aircraft was seen to touch down about halfway along Runway 08, at what appeared to be a faster than normal speed, and it had then started to porpoise. It was estimated that the point at which full power was applied for the go-around was in line with the mobile control tower, about 150 metres from the runway end.

The aircraft went through the boundary fence and came to rest, in a nose down attitude, in a small copse about 50 metres beyond the end of the runway. The pilot who was wearing diagonal upper torso restraint was uninjured and escaped without assistance.

The wreckage was subsequently examined (not by the AAIB); it was reported that the flaps were retracted and the throttle was fully forward; the propeller showed signs of being under power at impact. Both fuel tanks had been ruptured, probably by contact with the fence post, and the nose landing gear had collapsed.