

Robin R1180T Aiglon, G-BLZD and Robin DR400/140B Major, G-OEBA

AAIB Bulletin No: 5/97 Ref: EW/C96/10/9 Category: 1.3

Aircraft Type and Registration:	(i) Robin R1180T Aiglon, G-BLZD (ii) Robin DR400/140B Major, G-OEBA
No & Type of Engines:	(i) 1 Lycoming O-360-A3AD piston engine (ii) 1 Lycoming O-320-D2A piston engine
Year of Manufacture:	(i) 1979 (ii) 1981
Date & Time (UTC):	26 October 1996 at 1010 hrs
Location:	Near Dover, Kent
Type of Flight:	(i) Private (ii) Training
Persons on Board:	(i) Crew - 1 - Passengers - 1 (ii) Crew - 2 - Passengers - None
Injuries:	(i) Crew - None - Passengers - None (ii) Crew - 2 (fatal) - Passengers - N/A
Nature of Damage:	(i) Damaged beyond economic repair (ii) Aircraft destroyed
Commander's Licence:	(i) Private Pilot's Licence (ii) Commercial Pilot's Licence with Flying Instructor and Instrument Ratings
Commander's Age:	(i) 68 years (ii) 62 years
Commander's Flying Experience:	(i) 1,217 hours (of which 162 were on type)

Last 90 days - 16 hours

Last 28 days - 3 hours

(ii) 1,768 hours (of which about 1,600 were on type)

Last 90 days - 32 hours

Last 28 days - 16 hours

Information Source:

AAIB Field Investigation

History of flight

At 0937 hrs, G-BLZD ('ZD') took off from Fairoaks Airport for a VFR flight to Midden-Zeeland in Holland. G-OEBA ('BA') took off from Lashenden (Headcorn) Airfield at 0945 hrs on an instrument flying training detail.

At 1005 hrs, the pilot of 'ZD' called Manston Approach on 126.35MHz and passed the following position report: "Golf Zulu Delta is a Robin aircraft from Fairoaks to Midden-Zeeland - at present just past Ashford town - routing Dover - Mike Kilo - 13 miles to run to Dover at present 3,000 feet on 1019 squawking 7000 - request Flight Information Service". The controller replied "Golf Zulu Delta Flight Information Service - Chatham QNH 1014 - report Dover". There was no evidence of any communication between 'BA' and Manston ATSU.

From 1009 hrs, recorded secondary returns from Debden radar head (see Appendix A) showed an aircraft, believed to be 'ZD', tracking about 095°M; the ground speed was about 150 kt. A series of primary returns from the same radar head approached 'ZD's track from the north east; the nature of the data was such that only an informed estimate could be made of the track and ground speed. The final track was about 245°M and the ground speed about 95 kt. The two tracks crossed at about 1010 hrs and these secondary returns continued, turning initially to track about 140°M. No further primary returns were recorded and it was subsequently found that 'BA' had hit the ground vertically at high speed in the area just to the south of the point where the two tracks crossed. Note: The Manston AR1 radar is not recorded and it was not possible to determine what radar information was available to the controller over the period of the accident. Data recorded at LATCC from the Debden radar was used for the investigation but this information was not available to the Manston controller.

The pilot of 'ZD' reported that a "dark shadow" moved over the cockpit, there was a loud bang and the aircraft shuddered. At 1010:35 hrs, he made a MAYDAY call on the Manston frequency in which he reported "I THINK I'VE BEEN STRUCK - MY TAIL'S BEEN STRUCK BY ANOTHER AIRCRAFT". He was given a track to steer (QDM) to Manston of 194°. This was incorrect as the aircraft was south of Manston at the time; the next QDM, passed about a minute later, was 005°. About 20 seconds after his MAYDAY call, the pilot asked "MANSTON, DO YOU HAVE A RECORD OF OTHER AIRCRAFT IN THE VICINITY" to which the controller replied ".....NOTHING KNOWN AT THIS MOMENT".

Immediately after the collision 'ZD' lost about 1,500 feet of altitude. The pilot had no rudder control and only severely limited elevator control; he found it necessary to apply almost full aft control

column. He managed to exercise some control, by the co-ordinated use of power and aileron, and climbed and turned the aircraft towards Manston. Assisted by further QDMs from Manston ATC, the pilot positioned the aircraft for a landing on Runway 28; the surface wind was 240°/20 kt. At 1016:11 hrs, the pilot reported that he had "DIFFICULTY MAINTAINING CONTROL - ELEVATORS OR TRIMMERS DAMAGED". The controller acknowledged that he understood this and told the pilot to change frequency to Manston Tower on 119.27 MHz.

Despite his difficulties, the pilot managed to change frequency and, at 1016:34 hrs, was offered the choice of the paved Runway 28, or the grass Runway 24; he opted for the former. As he tried to reduce his speed, the aircraft yawed violently to left and right. During the landing phase, he lost lateral control of the aircraft which eventually came to rest on the grass to the right of the runway, a short distance from the Airport Fire Station at about 1019 hrs. The nose landing gear had separated and the aircraft was upright in a nose down attitude. The pilot carried out the shutdown check and, with his passenger, evacuated the aircraft without injury.

On site examination of the aircraft

G-OEBA

AAIB examination of both aircraft commenced with the wreckage of 'BA'. This aircraft was predominantly of wooden construction and painted in overall white with blue wing leading edges and blue/black fuselage cheat lines. It lay in a field/paddock about 100 metres south of farm buildings which comprise Langdon Abbey. It was obvious that the aircraft had descended almost vertically to the ground at a high rate. It had been in a roughly flat, left-wing-down attitude at impact which did not suggest that the aircraft was in any sense 'flying' but falling ballistically. The empennage and rear fuselage were missing from the main wreckage site as was a considerable portion of the left wing. The radio was selected to 122.0 MHz which is the Lashenden (Headcorn) air to ground frequency; the transponder had altitude mode capability but it was too badly damaged to determine which code was selected or whether it was switched on. Both occupants were still in the wreckage.

The missing structure of 'BA' was located in a trail to the east (approximately downwind) of the main site extending over a distance of about 2 km. This trail comprised small pieces of the aft fuselage, the empennage and the outboard, cranked section of the left wing, including the aileron. Other, smaller, debris was identified from further inboard on the left wing. Also in the trail were large pieces of the metal fin and rudder from 'ZD' with very clear impact marks exhibiting considerable blue paint smears in a line running roughly horizontally across the rudder chord. The complete wreckage of 'BA' was recovered to AAIB Farnborough.

G-BLZD

'ZD' which was of metal construction and basically white in colour with brown and orange trim, was examined in a hangar at RAF Manston. The nose landing gear had been detached and the right wing distorted during the forced landing and subsequent departure from the runway. The complete fin and rudder were missing, leaving only the fin/fuselage fillet fairing. About 50% of the left stabilator was missing having evidently been removed by a crushing impact from the front and left. Traces of black rubber scuffing were found in some of the folded metal and some considerable stiffness in the pitch control circuit was occurring due to fouling of the stabilator against structure. The aircraft carried two VHF 'whip' aerials on the fuselage decking behind the cockpit and the aft one of these had been bent whilst both had blue paint smears near the tips.

Subsequent examination and analysis

It was deemed unnecessary to recover 'ZD' to AAIB, and analysis centred on the wreckage of 'BA'. Using scale drawings of the two aircraft, it was possible to devise an accurate assessment of the relative attitudes of the two aircraft at the moment of first impact (see Appendix B). The direction of crushing on the fin and rudder of 'ZD' and the orientation of the blue paint smear showed that the left wing leading edge of 'BA' had struck the fin of 'ZD' at a point somewhere inboard of where the tip cranks upwards. This led to detachment of the outboard section, complete with aileron, but also caused further disruption inboard such that an estimated 50% or more of the wing was probably destroyed. Minor cuts in the leading edge of the cranked section corresponded with the whip aerials of 'ZD', which had blue paint deposits on their tips. This evidence, together with the orientation of the impact marks on the fin, showed that 'BA' had been on a relative bearing of 50° to the left of 'ZD' and in a more-or-less wings-level attitude. First contact was between the outboard wing leading edge of 'BA' and the whip aerials of 'ZD', followed by the left main landing gear of the former on the stabilator of the latter. Almost simultaneously the left wing leading edge of 'BA' struck and removed the fin and rudder of 'ZD' before the two aircraft separated.

The effect of losing such a large amount of wing area on 'BA' would be to roll the aircraft sharply to the left and this alone could probably account for detachment of the empennage. However, there was evidence that some part of the disrupted left wing had struck the fuselage causing crippling of the latter, since the separation point of the empennage was not the clean break which might have been expected but was associated with considerable fragmentation of the plywood fuselage skin over an area as far forward as the rear of the cockpit. The disruption of the left wing would, however, on its own have rendered the aircraft uncontrollable.

Meteorology

An aftercast was obtained from the Meteorological Office at Bracknell. It indicated that for the period of the accident, there was a fresh, unstable westerly airstream established over Kent. The visibility was between 25 and 30 km and the mean sea level pressure was 1,021 mb; the cloud was FEW, base 2,500 to 3,000 feet. The surface wind was generally 250°/15 to 20 kt with gusts to 30 kt; the wind at 3,000 feet was 260°/30 kt. The elevation of the sun at 1010 hrs was 24° and its azimuth was 156°.

Medical and pathology

The pilot of 'ZD' had a current Class 3 medical. The examination was on 8 March 1996 and it was valid for 12 months from the end of that month. He was required to wear spectacles which correct for distant vision and to have available a second pair while exercising the privileges of the licence.

Both occupants of 'BA' died as a result of multiple injuries which occurred when their aircraft struck the ground. Neither had any pre-existing medical condition which would have contributed to the accident.

The instructor had a current Class 1 medical. The examination was on 2 May 1996 and it was valid for 6 months from the end of that month. He was required to wear spectacles which correct for distant vision and to have available a second pair while exercising the privileges of the licence.

The pilot undergoing instruction had a current Class 3 medical. The examination was on 11 November 1995 and it was valid for 12 months from the end of that month. She was required to wear spectacles which correct for distant vision and to have available a second pair while exercising the privileges of the licence.

While there is evidence that the pilot of 'ZD' was wearing spectacles, because of the nature of the accident, it was not possible to determine this in the case of the occupants of 'BA'. However, the instructor was known to wear spectacles at all times and, as the spectacles required were for the correction of distant vision, it would be usual for them to be worn throughout the flight.

Visibility from the two aircraft

Both aircraft were made by the same manufacturer and shared the distinguishing feature of a largely unobstructed canopy giving almost complete all round vision. They were of similar size and predominantly white in colour. 'BA' had not been fitted with instrument flying training screens and there was no evidence of an instrument flying hood found among the wreckage. It was not possible to determine positively whether the pilot undergoing instrument flying training in the left seat of 'BA' was flying the aircraft by reference to instruments alone just prior to the impact. However, it is probable that she was and therefore the lookout would have been done solely by the instructor in the right seat. The lookout from 'ZD' would have been mainly from the left seat as the right seat was occupied by a passenger with no formal piloting experience.

At 1009:51 hrs, about 12 seconds before impact 'BA' was in the left, 11 o'clock position from 'ZD'; conversely 'ZD' was in the right, 1 o'clock position from 'BA'. The aircraft were about 2/3 nm apart and the aspect would have been of the front quarter in both cases. It is possible that, from this time, the pilot of either aircraft could have seen the other had he happened to look in the right direction. However, it should be borne in mind that both pilots had other tasks to perform which would have required the focus of their attention to be in the cockpit for significant periods between looking outside.

At 6 seconds before impact, the tracks and relative bearings of the aircraft had changed little, but they were now only about 1,750 ft apart. To avoid impact either or both aircraft would have had to bank rapidly to the right. The pilot of 'ZD' stated that he did not see 'BA' and the near wings level attitude at impact of the latter would imply that the pilot of 'BA' did not see 'ZD', certainly not until it was too late to initiate any avoiding action.

Services to aircraft outside controlled airspace

The attention of pilots is drawn to AIC121/1993. This circular details the range of services available to aircraft flying outside controlled airspace from both civil and military Air Traffic Control Service Units (ATSU). Manston is a military ATSU and can provide a Lower Airspace Radar Service (LARS) to pilots flying up to and including FL95. LARS is a structured national system within which the participating ATSU can provide a Radar Advisory Service (RAS) or a Radar Information Service (RIS) for pilot's flying within about 30 nm of the unit.

An aircraft receiving a RAS is provided with advisory instructions to maintain the prescribed separation minima between participating aircraft. In addition, the controller will pass the bearing, distance and, if known, the level of non-participating traffic, together with ADVICE on action necessary to resolve the confliction. An aircraft receiving a RIS is provided with the bearing, distance and, if known, the level of conflicting traffic. No avoiding action is offered.

The Flight Information Service (FIS) is a non-radar service in which information is provided to the pilot to assist the safe and efficient conduct of flight. The civilian Manual of Air Traffic Services Part 1 states that "Warnings of proximity hazards are issued when, from aircraft reports, they are self-evident but the decision to make any alteration to the flight remains with the pilot. Warnings are issued entirely at the discretion of the controller". The military equivalent, Joint Services Publication 318A, differs in emphasis, stating that "Details of other traffic, from any source, will also be passed **but only** where there is evidence that the aircraft are, or will be, in dangerous proximity to each other."

The AIC points out that traffic proximity warnings received under FIS may be inaccurate or incomplete because many aircraft fly on a multiplicity of tracks and levels without communicating with an ATSU. It recommends that pilots ask for a Radar Service, rather than FIS on its own, whenever such a service is available. It points out that an ATSU will automatically provide FIS as an integral part of RAS or RIS.