

# Miles M3A Falcon, G-AEEG, 18 September 1997

**AAIB Bulletin No: 12/1997**

**Ref: EW/G97/09/19 Category: 1.1**

Aircraft Type and Registration:	Miles M3A Falcon, G-AEEG
No & Type of Engines:	1 De Havilland Gipsy Major 10 Mk 2 piston engine
Year of Manufacture:	1936
Date & Time (UTC):	18 September 1997 at 1635 hrs
Location:	Thorncote Green, Bedfordshire
Type of Flight:	Private
Persons on Board:	Crew - 1 - Passengers - None
Injuries:	Crew - None - Passengers - N/A
Nature of Damage:	Propeller broken and engine shock loaded. Damage to left wing tip and right gear leg
Commander's Licence:	Private Pilot's Licence with Night Rating
Commander's Age:	49 years
Commander's Flying Experience:	302 hours (of which 2 were on type) Last 90 days - 5 hours Last 28 days - 2 hours
Information Source:	Aircraft Accident Report Form submitted by the pilot

The pilot was undergoing a conversion to the Miles Falcon. As the type only has one pilot's seat, but two passenger seats in the rear of the cockpit, the content of the conversion had been carefully considered. Following a comprehensive briefing on the aircraft, the pilot being converted flew a familiarisation flight, as a passenger, with his briefing pilot who was current on type. Following this, the pilot being converted was confident that he had been properly prepared for his first solo flight. However, as the aircraft was kept at a private airstrip, it was agreed that this solo should take place at a more suitable location. Accordingly, a few days later, the same two pilots flew to Henlow where there was a suitable runway and a large expanse of grass. During the transit, which was flown by the pilot current on type, the pilot being converted was again thoroughly briefed on the operation of the aircraft. At Henlow, he completed his first solo which involved one touch-and-

go followed by a series of fullstop landings. Subsequently, after another flight as a passenger back to the private airstrip, the converting pilot was debriefed and then cleared to operate from the airstrip.

His first flight from Thorncote Green was made on 14 September and involved a take off from Runway 24, transit to Henlow for a landing and then a return flight to Thorncote Green to land on Runway 24. The pilot was content with his performance and planned his next flight to cover upper air work. This next flight was scheduled for 18 September and the weather on the day was good. The surface wind was calm and the pilot decided to use Runway 24 for take off; the airstrip is 708 metres long with short surface grass which was dry at the time. All the pre-flight checks were completed and the pilot set the elevator trim lever to neutral and tightened the trim friction nut.

Initially, the take-off run was normal but, when the pilot attempted to raise the tail off the ground he experienced much greater resistance than normal. He was concerned that, if he pushed too hard, the propeller could strike the ground. With an increasing ground speed and the tail still on the ground, the pilot could not see straight ahead. He sensed that G-AEEG was getting airborne but at too slow a speed for safe flight, and was also aware that he was drifting to the left of the runway. Deciding to abort the take off, the pilot retarded the throttle and applied right rudder; the aircraft swung to the right and ran off the runway into a recently ploughed field. In the subsequent abrupt stop, the left wing tip and the propeller momentarily struck the ground before the aircraft came to rest.

The pilot considered that the cause of the accident was his incorrect setting of the elevator trim lever friction nut. The elevator trim lever is located just forward of the control column and controls a bias spring which is connected to the control column. Under normal operation, the trim lever moves in sympathy with the control column but can be adjusted in flight to reduce air loads on the control column. However, if the friction nut is tightened too much, the movement of the trim lever is restricted and results in increased resistance on control column movement. On the previous flights, the friction nut had been looser and the nut is not accessible by the pilot once he is strapped in. With the situation the pilot found himself in, he considers that his decision to abort the take off was correct; unfortunately, his inexperience on type meant that he was not able to control the subsequent swing resulting from throttle closure and simultaneous rudder input.