

Boeing 747-236B, G-BDXP, 3 June 1996

AAIB Bulletin No: 12/1996

Ref: EW/C96/6/1 Category: 1.1

Aircraft Type and Registration:	Boeing 747-236B, G-BDXP
No & Type of Engines:	4 Rolls Royce RB211-524D-19 turbofan engines
Year of Manufacture:	1988
Date & Time (UTC):	3 June 1996 at 2300 hrs
Location:	Miami Airport, Florida, USA
Type of Flight:	Public Transport
Persons on Board:	Crew - 18 - Passengers - 364
Injuries:	Crew - Nil - Passengers - Nil
Nature of Damage:	Approximately half of the No. 16 leading edge Krueger flap missing
Commander's Licence:	N/A
Commander's Age:	N/A
Commander's Flying Experience:	N/A
Information Source:	AAIB Field Investigation

Following an uneventful flight from Miami, the operator's engineering staff carried out a turn-around maintenance check on the aircraft during which it was found that a large section of the No 16 leading edge Krueger flap was missing. Following a request from the AAIB, the Miami Airport authorities conducted a search of the area around Runway 09L, the runway in use at the time this aircraft departed. Following this search, the missing part of the flap was found and despatched to the AAIB. Examination of the aircraft indicated that during the last third of the flap's deployment travel the outboard end of the flap had been contacting the inboard side of the No 3 engine pylon.

Examination of the detached section of flap indicated that the failure had been progressive and had resulted from repetitive flexural bending loads introduced as a result of contact between the forward outer end of the flap and the No 3 engine pylon, when the flap was deployed and retracted in service.

The aircraft manufacturer had issued Service Bulletin (SB) 747-57-2268 in July 1992, entitled 'Wings - leading edge Krueger flaps - panel trim and seal replacement on outboard side of Krueger flaps 11 and 16', revision three of which was issued in September 1994. The background to this

Service Bulletin was that operators had reported instances of damage to the outboard ends of the Krueger flaps, with sections detaching from some aircraft. The damage occurred on Krueger flaps Nos 11 and 16 where the flap seals contacted the inboard sides of the Nos 2 and 3 engine struts. The damage was caused by flap-to-strut interference due to insufficient clearance. The Krueger flap-to-strut gap introduced at production was 1.35 inches. Most of the damaged flaps had a gap which was less than 1.35 inches. As engine thrust was increased on Boeing 747 aircraft, increased inboard/outboard engine displacement resulted in the need for increased clearance. This SB increased the gap to 1.70 inches between the Krueger flap and the engine strut. The operator's technical records indicated that this Service Bulletin had been implemented on this aircraft in August 1995. Due to the damage sustained by this No 16 Krueger flap it was not possible to measure the gap which had existed between the flap and the engine strut. However, the gap measured between the No 11 Krueger flap and the No 2 engine strut confirmed that the Service Bulletin had been carried out on that flap.

In May 1996, the aircraft manufacturer issued Service Bulletin 747-57-2299 which introduced reinforcement of the Nos 11 and 16 Krueger flaps by the addition of three fibreglass layers to decrease the possibility of flap damage. At the time of this incident, the operator was assessing and planning the action required by this latest Service Bulletin.