

# Boeing 747-100, G-VMIA, 10 October 1996

**AAIB Bulletin No: 12/1996**

**Ref: EW/C96/10/2 Category: 1.1**

<b>Aircraft Type and Registration:</b>	Boeing 747-100, G-VMIA
<b>No &amp; Type of Engines:</b>	4 Pratt & Whitney JTD9D-7 turbofan engines
<b>Year of Manufacture:</b>	1970
<b>Date &amp; Time (UTC):</b>	10 October 1996 at 1459 hrs
<b>Location:</b>	Enroute to Boston, USA
<b>Type of Flight:</b>	Public Transport
<b>Persons on Board:</b>	Crew - 19 - Passengers 359
<b>Injuries:</b>	Crew - None - Passengers - None
<b>Nature of Damage:</b>	None
<b>Commander's Licence:</b>	Airline Transport Pilot's Licence
<b>Commander's Age:</b>	40 years
<b>Commander's Flying Experience:</b>	7,600 hours of which 4,400 were on type) Last 90 days - 202 hours Last 28 days - 82 hours
<b>Information Source:</b>	AAIB Field Investigation

## History of flight

The crew came on duty at 1240 hrs for a 1400 hrs departure on a scheduled 7 hours 10 minutes flight to Boston, USA. The aircraft took off at 1419 hrs. The commander was the handling pilot and he reported that, during the climb, at 330 kt IAS, at around FL290, he noticed that the rate of climb had reduced to less than 500ft/min. He noted that the aircraft was in VMC, climb EPR (Engine Pressure Ratio) was set and the static air temperature was -44°C. Shortly afterwards, the EPR on the No 1 engine began to fluctuate and reduced to about 1.32; there was little response when the flight engineer manipulated the thrust levers. Nacelle anti ice was selected on as a precaution because the aircraft was about to enter a layer of cirrostratus cloud. At about this time, the No 4 engine also ran down. The commander handed control to the first officer and declared a

state of emergency. The flight engineer carried out the memory items of the MULTI ENGINE SHUTDOWN/RESTART drill and the status of the nacelle anti ice, ignition, fuel heat, fuel configuration and fuel booster pump were reported to have been correct at this time.

A successful windmill start was eventually achieved on the No 1 engine. All attempts to restart the No 4 engine resulted in it running with a high egt and low rpm with no thrust lever response and so it was shut down. The aircraft returned to Gatwick where, after jettisoning 40,200 kg of fuel, a three engine approach was made and it landed safely at 1556 hrs.

### **Meteorology**

An aftercast prepared by the Meteorological Office at Bracknell reported that there was an upper ridge of high pressure, lying across the Irish Sea, which had persisted for several days with associated north westerly winds. The 1200 hrs upper air sounding from Aberporth indicated a slow warm advection with wind veering slowly with height. There was an increase and thickening of medium and upper cloud from the west. The wind at 300 mb level (about 30,000 feet) was 315°/40 kt, the temperature was - 42°C and the dew point -50°C.

All information on the recent volcanic activity in Iceland indicated that the ash cloud had not penetrated much above FL200 although the vapour cloud had reached FL280 to FL300 with associated cumulonimbus clouds and thunderstorms. Recent trajectories had taken the plume north east then east into Scandinavia, well away from the Irish Sea.

### **Flight data recorder**

Information obtained from the FDR indicated that the No 1 engine EPR reduced from about 1.5 to about 1.2 as the aircraft passed through FL300; it then recovered to about 1.32. Two minutes 30 seconds after the initial rundown of the No 1 engine, the No 4 engine flamed out; the No 1 engine then flamed out after a further 30 seconds. After one abortive relight the No 1 engine began to function normally and achieved an EPR of 1.4. The No 4 engine did not relight successfully and subsequently was shutdown.

### **Fuel system (see Appendix 1)**

There are four main tanks and one centre wing tank; the No 1 and 4 reserve tanks are considered as a part of their respective main tanks. Each main tank is associated with an engine and fuel can be delivered directly to that engine via fuel booster pumps. There are two booster pumps in each tank, those in the centre wing tank (designated override/jettison pumps) having a higher output pressure than the others, and all the booster pumps feed the delivery system via non-return valves. There is also an ejector pump which scavenges the last 1,400 kg of centre wing tank fuel into the No 2 main tank. A crossfeed gallery connects the various engine feed-pipes and fuel management is by selection of the appropriate combination of cross feed valves and booster pumps. The fuel management procedures are designed to ensure that this crossfeed gallery remains pressurised at all times.

The fuel load on the incident flight was:

Reserve tanks each 1,500 kg

No 1 & 4 tanks each 11,300 kg



Since the output pressure of the centre wing tank override/jettison pumps is higher than that of the booster pumps, the fuel from the centre wing tank is fed to all four engines. When the fuel quantity in the centre wing tank is reduced to a pre-determined level, or its pump low pressure lights illuminate, the centre wing tank pumps are turned 'OFF' and all the engines will then be fed from No 2 & 3 main tanks. This will continue until such time as the quantity in those tanks falls to the same level as the No 1 & 4 tanks when 'main tank to engine' feed is reinstated. The remaining fuel in the centre wing tank, normally about 1,400 kg, is scavenged into the No 2 main tank.

## **Air test**

G-VMIA was air tested on 11 October with an AAIB Operations Inspector on board. The first test involved the aircraft climbing with the fuel system being configured as in the SOP. The exhaustion of the centre wing tank fuel was simulated by switching off the centre wing tank override/jettison pumps once the quantity had reduced to 3,000 kg. The aircraft reached FL390 without incident.

The second test started at FL100 and when, at FL150, the quantities in No 1 and 4 tank were down to between 10,000 and 9,500 kg, the centre wing tank override/jettison pumps were switched on and the No 1 and 4 booster pumps were switched off. The crossfeed valves were, however, left in the configuration they would have been in since take off *ie* No 1 and 4 OPEN and No 2 and 3 CLOSED. At FL280, the centre wing tank low pressure (LP) lights began to flash; the contents were about 1,300 kg. All four engines were set to about 1.46 EPR. The LP lights came on continuously by FL290, so the centre wing tank pumps were turned off and the scavenge pump turned on; the centre wing tank contents were about 1,200 kg at this point. The No 1 engine ran down almost immediately to about 1.29 EPR and was closely followed by the No 4 engine which reacted in a similar manner. Neither engine responded to throttle lever movement. The aircraft was levelled off and the No 1 engine restarted immediately ignition was selected. With the aircraft level at FL300, IAS 300 kt, it continued to run normally, on gravity feed, at 1.49 EPR/782° EGT. The No 4 engine would not restart with gravity feed only and was shut down. The fuel system was then reconfigured with all booster pumps on and all crossfeed valves open and a further attempt was made to start the No 4 engine using the Inflight Start procedure. The engine lit but the N<sub>2</sub> did not rise above 54% even with RICH selected; there was little or no response to throttle lever movement. The engine was shut down and the aircraft descended to FL250 and another inflight start was attempted, again at 300 kt. The engine lit but the N<sub>2</sub> stabilised at 49% (0.78 EPR/660° EGT) and again there was little or no response to throttle lever movement. The engine was shut down and the IAS was reduced to 245 kt so that the Ground Start procedure could be used. This was successful and the N<sub>2</sub> stabilised at 62%. The aircraft then descended to FL200, IAS 300 kt, and the No 4 engine was again shut down; at this level the Inflight Start procedure was successful and the engine restarted normally. The aircraft returned to London Gatwick Airport where, after replacement of the No 4 engine igniters, the aircraft was returned to service.

## **Operations Manual**

Instructions on fuel system management are clearly laid out in the Operations Manual; the procedures which are peculiar to G-VMIA are specified in an approved Differences Supplement. In the interests of standardisation, clarity and ease of access the content of the Flying Training Note entitled Fuel Feed Configuration Changes is being transferred to the Operations Manual.